

11087386, SEB1NN/2,6LN08CD08NNNNNNNNN/NNNNN
111.09.031.00, SEB1NN/2,6RN08CD08NNNNNNNNN/NNNNN
11087387, SEB1NN/3,2LN08CD08NNNNNNNNN/NNNNN
111.09.032.00, SEB1NN/3,2RN08CD08NNNNNNNNN/NNNNN
11096054, SEB1NN/3,8LN08CD08NNNNNNNNN/NNNNN
111.09.033.00, SEB1NN/3,8RN08CD08NNNNNNNNN/NNNNN
111.09.046.00, SEB1NN/4,3LN08CD08NNNNNNNNN/NNNNN
111.09.034.00, SEB1NN/4,3RN08CD08NNNNNNNNN/NNNNN
11087388, SEB1NN/6,0LN08CD08NNNNNNNNN/NNNNN
111.09.035.00, SEB1NN/6,0RN08CD08NNNNNNNNN/NNNNN
11087389, SEB1NN/7,8LN08CD08NNNNNNNNN/NNNNN
111.09.036.00, SEB1NN/7,8RN08CD08NNNNNNNNN/NNNNN
753632, SECHSK.SCHRB. 1/2 -13 UNC LG 76,20 GRD.5
516517, SECHSK.SCHRB.5/16-18 UNC LG 16,00 M.FLAN
443952/P, SECTION-INPUT TMG 51.2
5725.20.4095, SEEGER 47 UNI 7437
5725.20.4265, SEEGER 50 UNI 7437
5725.20.4285, SEEGER 52 UNI 7437
5725.28.1952, SEEGER J19x1 tipo -V-
507458, SEGMENT 51V110-1 ASSY
984L3286, SEL PLUG grey /replaced by 984L3156
11070640, SEM2/ 8 . CO01 +++1.
121.19.132.00, SEM2/11 . CI91 MMJ1.
121.19.131.00, SEM2/11 . CO01 MKM1.
121.19.136.00, SEM2/17 . CI01 MKM1.
121.19.130.00, SEM2/17 . CI91 MMJ1.
121.19.129.00, SEM2/17 . CO01 MKM1.
121.19.135.00, SEM2/19 . CO01 MKM1.
121.19.133.00, SEM2/6 . CO01 MKN1.
121.19.134.00, SEM2/8 . CO01 MKM1.
11107551, SEM2/8 CO01 +++1F
11110350, SEM2/8 SC01 +++1.
121.19.104.00, SEM2DN/011BN01BAD2C3C3NNNNN/NNNNN
121.19.126.00, SEM2DN/011BNG1FAD2C7C7NNNNN/NNNNN
121.19.039.00, SEM2DN/014BN01BBD2C7C7NNNNN/NNNNN
121.19.077.00, SEM2DN/017BN01BAD2C7C7NNNA/NNNNN
121.19.035.00, SEM2DN/017BN01BBD2C7C7NNNNN/NNNNN
121.19.078.00, SEM2DN/019BN01BAD2C7C7NNNA/NNNNN
121.19.105.00, SEM2DN/019BN01FAD2C7C7NNNNN/NNNNN
121.19.124.00, SEM2DN/019BNG1FAD2C7C7NNNNN/NNNNN
121.19.088.00, SEM2DN/6,0BN01BAD2C3C3NNNNN/NNNNN
121.19.041.00, SEM2DN/8,0BN01BAD2F4F4NNNNN/NNNNN
121.19.085.00, SEM2NL/011BN01BAL1C3C3NNNNN/NNNNN
121.19.115.00, SEM2NL/9,5BN02AAL6H7H7NNNA/NNNNN
121.19.108.00, SEM2NN/011BN01BAM1C3C3NNNA/NNNNN
121.19.021.00, SEM2NN/011BN01BAM1C3C3NNNNN/NNNNN
121.19.033.00, SEM2NN/011BN01BAM1C7C7NNNNN/NNNNN
121.19.111.00, SEM2NN/011BN01BAM1F4F4NNNNN/NNNNN
11123901, SEM2NN/011BN01BBM1C3C3NNNA/NNNNN
121.19.079.00, SEM2NN/011BN01DAM1C3C3NNNNN/NNNNN

121.19.122.00, SEM2NN/011BN01FAM1B5B5NNNN/NNNNN
121.19.046.00, SEM2NN/011BN01FAM1C3C3NNNA/NNNNN
121.19.017.00, SEM2NN/011BN01FAM1C3C3NNNN/NNNNN
121.19.071.00, SEM2NN/011BN02AAM1B5B5NNNA/NNNNN
121.19.027.00, SEM2NN/011BN02AAM1B5B5NNNN/NNNNN
121.19.095.00, SEM2NN/011BN03DBM3B5B5NNNN/NNNNN
121.19.113.00, SEM2NN/011BN9FDBM3B5B5NNNA/NNNNN
11078944, SEM2NN/014BN01BAM1B5B5NNNN/NNNNN
121.19.022.00, SEM2NN/014BN01BAM1C7C7NNNN/NNNNN
121.19.034.00, SEM2NN/014BN01BAM1E5E5NNNN/NNNNN
121.19.080.00, SEM2NN/014BN01BAM1F4F4NNNN/NNNNN
121.19.097.00, SEM2NN/014BN01BBM1C7C7NNNA/NNNNN
121.19.036.00, SEM2NN/014BN01BBM1C7C7NNNN/NNNNN
121.19.048.00, SEM2NN/014BN01FAM1C7C7NNNA/NNNNN
121.19.018.00, SEM2NN/014BN01FAM1C7C7NNNN/NNNNN
121.19.112.00, SEM2NN/017BN01BAM1C7C7NNNN/NNNNN
121.19.098.00, SEM2NN/017BN01BBM1C7C7NNNA/NNNNN
121.19.084.00, SEM2NN/017BN01BBM1C7C7NNNN/NNNNN
121.19.040.00, SEM2NN/017BN01DAM1C7C7NNNN/NNNNN
121.19.090.00, SEM2NN/017BN01FAM1C7C7NNNA/NNNNN
121.19.019.00, SEM2NN/017BN01FAM1C7C7NNNN/NNNNN
121.19.092.00, SEM2NN/017BN01FAM1F4F4NNNN/NNNNN
11075230, SEM2NN/017BN91DBM3C7C7NNNN/NNNNN
121.19.109.00, SEM2NN/019BN01BAM1C7C7NNNA/NNNNN
121.19.023.00, SEM2NN/019BN01BAM1C7C7NNNN/NNNNN
121.19.101.00, SEM2NN/019BN01BAM1C7C7NNNN/NNNNN
121.19.089.00, SEM2NN/019BN01BBM1C7C7NNNN/NNNNN
121.19.114.00, SEM2NN/019BN01BBM1F5F5NNNN/NNNNN
121.19.050.00, SEM2NN/019BN01FAM1C7C7NNNA/NNNNN
121.19.031.00, SEM2NN/019BN01FAM1C7C7NNNN/NNNNN
121.19.123.00, SEM2NN/019BN01FAM1F5F5NNNA/NNNNN
11105459, SEM2NN/019BN02AAM1C7C7NNNN/NNNNN
11075302, SEM2NN/019BN91DBM3C7C7NNNN/NNNNN
121.19.128.00, SEM2NN/019BN9LBAM1C7C7NNNN/NNNNN
121.19.025.00, SEM2NN/022BN01BAM1C7C7NNNN/NNNNN
121.19.059.00, SEM2NN/022BN01BBM1C7C7NNNA/NNNNN
121.19.051.00, SEM2NN/022BN01FAM1C7C7NNNA/NNNNN
121.19.110.00, SEM2NN/025BN01BAM1C8C8NNNA/NNNNN
121.19.015.00, SEM2NN/025BN01BAM1C8C8NNNN/NNNNN
121.19.020.00, SEM2NN/025BN01FAM1C8C8NNNN/NNNNN
121.19.093.00, SEM2NN/025BN01FAM1F5F5NNNN/NNNNN
121.19.053.00, SEM2NN/6,0BN01BAM1C3C3NNNA/NNNNN
121.19.028.00, SEM2NN/6,0BN01BAM1C3C3NNNN/NNNNN
11043260, SEM2NN/6,0BN01BAM1C3C3NNNN/NNNWN
11121339, SEM2NN/6,0BN01BBM1C3C3NNNN/NNNNN
121.19.137.00, SEM2NN/6,0BN01DAM1C3C3NNNN/NNNNN
121.19.116.00, SEM2NN/6,0BN01FAM1B5B5NNNN/NNNNN
121.19.047.00, SEM2NN/6,0BN01FAM1C3C3NNNA/NNNNN
121.19.038.00, SEM2NN/6,0BN01FAM1C3C3NNNN/NNNNN
121.19.117.00, SEM2NN/6,0BN03DBM3B5B5NNNA/NNNNN

121.19.118.00, SEM2NN/6,0BN9FDBM3B5B5NNNA/NNNNN
121.19.100.00, SEM2NN/8,0BN01BAM1C3C3NNNN/NNNNN
121.19.094.00, SEM2NN/8,0BN01BAM1F4F4NNNA/NNNNN
121.19.087.00, SEM2NN/8,0BN01BBM1C3C3NNNA/NNNNN
121.19.086.00, SEM2NN/8,0BN01BBM1C3C3NNNN/NNNNN
121.19.026.00, SEM2NN/8,0BN01DAM1C3C3NNNN/NNNNN
121.19.121.00, SEM2NN/8,0BN01FAM1B5B5NNNN/NNNNN
11118771, SEM2NN/8,0BN01FAM1C3C3NNDN/NNNNN
121.19.102.00, SEM2NN/8,0BN01FAM1C3C3NNNA/NNNNN
121.19.016.00, SEM2NN/8,0BN01FAM1C3C3NNNN/NNNNN
121.19.029.00, SEM2NN/8,0BN01FAM1F4F4NNNN/NNNNN
121.19.119.00, SEM2NN/8,0BN03DBM3B5B5NNNA/NNNNN
121.19.120.00, SEM2NN/8,0BN9FDBM3B5B5NNNA/NNNNN
121.19.127.00, SEM2NN/8,0BN9LBAM1C3C3NNNN/NNNNN
730192, SENSOR MCX103C1018 RECHTSANSCHLAG=6V DC
519151, SENSOR-ANGLE ASSY K###
162B4334, SENSORSKRUE ?7
162B1305, SENSORSL?DE
300269, SENSOR-SPEED BOSCH DF6
482406, SENSOR-SPEED TMG ASSY
149055, SENSOR-SPEED-TEMPERATURE, H1
111.09.010.00, SEP1NN/1,0LN03CA03D5D3NNNN/NNNNN
111.09.011.00, SEP1NN/1,9LN03CA03D5D3NNNN/NNNNN
111.09.012.00, SEP1NN/2,8LN03CA03D5D3NNNN/NNNNN
111.09.013.00, SEP1NN/3,8LN03CA03D5D3NNNN/NNNNN
111.09.014.00, SEP1NN/4,7LN03CA03D5D3NNNN/NNNNN
111.09.015.00, SEP1NN/7,8LN03CA03D5D3NNNN/NNNNN
111.19.080.00, SEP2NN/011LN01B1P1C3C3NNNN/NNNNN
111.19.080.00-0L, SEP2NN/011LN01B1P1C3C3NNNN/NNNNN
111.19.047.00, SEP2NN/011LN01BAP1C3C3NNNN/NNNNN
111.19.128.00, SEP2NN/011LN01BBP1C3C3NNNN/NNNNN
111.19.081.00, SEP2NN/011RN01B1P1C3C3NNNN/NNNNN
111.19.081.00-0L, SEP2NN/011RN01B1P1C3C3NNNN/NNNNN
111.19.046.00, SEP2NN/011RN01BAP1C3C3NNNN/NNNNN
111.19.063.00, SEP2NN/011RN01BAP1F5F4NNNN/NNNNN
111.19.127.00, SEP2NN/011RN01BBP1C3C3NNNN/NNNNN
111.19.049.00, SEP2NN/014LN01BAP1C7C3NNNN/NNNNN
111.19.048.00, SEP2NN/014RN01BAP1C7C3NNNN/NNNNN
111.19.051.00, SEP2NN/017LN01BAP1C7C3NNNN/NNNNN
111.19.066.00, SEP2NN/017LN01BAP1F5F4NNNN/NNNNN
111.19.084.00, SEP2NN/017RN01B2P1C7C3NNNN/NNNNN
111.19.050.00, SEP2NN/017RN01BAP1C7C3NNNN/NNNNN
111.19.067.00, SEP2NN/017RN01BAP1F5F4NNNN/NNNNN
111.19.041.00, SEP2NN/4,0LN01BAP1C3C3NNNN/NNNNN
111.19.040.00, SEP2NN/4,0RN01BAP1C3C3NNNN/NNNNN
111.19.069.00, SEP2NN/4,0RN01DAP1C3C3NNNN/NNNNN
111.19.043.00, SEP2NN/6,0LN01BAP1C3C3NNNN/NNNNN
111.19.042.00, SEP2NN/6,0RN01BAP1C3C3NNNN/NNNNN
111.19.131.00, SEP2NN/6,0RN01BBP1C3C3NNNN/NNNDA
111.19.055.00, SEP2NN/6,0RN01BBP1C3C3NNNN/NNNNN

111.19.045.00, SEP2NN/8,0LN01BAP1C3C3NNNN/NNNNN
111.19.045.00-0L, SEP2NN/8,0LN01BAP1C3C3NNNN/NNNNN
111.19.072.00, SEP2NN/8,0LN01DAP1C3C3NNNN/NNNNN
111.19.044.00, SEP2NN/8,0RN01BAP1C3C3NNNN/NNNNN
111.24.003.00, SEP3NN/022LN01BAP1C7C7NNNN/NNNNN
111.24.003.00-0L, SEP3NN/022LN01BAP1C7C7NNNN/NNNNN
111.24.127.00, SEP3NN/022LN01BAP1E8E6NNNN/NNNNN
111.24.105.00, SEP3NN/022LN07SAP1E9E8NNNN/NNNNN
111.24.004.00, SEP3NN/022RN01BAP1C7C7NNNN/NNNNN
111.24.131.00, SEP3NN/022RN01BAP1E8E6NNNN/NNNNN
111.24.110.00, SEP3NN/022RN01BAP1F5F5NNNN/NNNNN
111.24.044.00, SEP3NN/022RN07SAP1E8E6NNNN/NNNNN
111.24.005.00, SEP3NN/026LN01BAP1C7C7NNNN/NNNNN
111.24.005.00-0L, SEP3NN/026LN01BAP1C7C7NNNN/NNNNN
111.24.045.00, SEP3NN/026LN07SAP1E8E6NNNN/NNNNN
111.24.006.00, SEP3NN/026RN01BAP1C7C7NNNN/NNNNN
111.24.046.00, SEP3NN/026RN07SAP1E8E6NNNN/NNNNN
111.24.007.00, SEP3NN/033LN01BAP1CAC7NNNN/NNNNN
111.24.047.00, SEP3NN/033LN07SAP1E9E8NNNN/NNNNN
11083292, SEP3NN/033LN07SAP1F6F5NNNN/NNNNN
111.24.008.00, SEP3NN/033RN01BAP1CAC7NNNN/NNNNN
11051043, SEP3NN/033RN01BAP1F5F5NNNN/NNNNN
111.24.114.00, SEP3NN/033RN01BAP1F6F5NNNN/NNNNN
111.24.048.00, SEP3NN/033RN07SAP1E9E8NNNN/NNNNN
111.24.009.00, SEP3NN/038LN01BAP1CAC7NNNN/NNNNN
111.24.049.00, SEP3NN/038LN07SAP1E9E8NNNN/NNNNN
111.24.010.00, SEP3NN/038RN01BAP1CAC7NNNN/NNNNN
111.24.050.00, SEP3NN/038RN07SAP1E9E8NNNN/NNNNN
111.24.011.00, SEP3NN/044LN01BAP1CACANNNN/NNNNN
111.24.051.00, SEP3NN/044LN07SAP1E9E8NNNN/NNNNN
111.24.012.00, SEP3NN/044RN01BAP1CACANNNN/NNNNN
111.24.052.00, SEP3NN/044RN07SAP1E9E8NNNN/NNNNN
11108232, SERVICE KIT FOR 11040798
11098487, SERVICE KIT GR2 SCANIA
11098489, SERVICE KIT GR3 SCANIA
11082163, SERVICE KIT PRESS SNR 550BAR DANFOSS H1
11065645, SERVICE KIT SGM2Y CO02-06
11060848, SERVICE KIT SGM3Y CO07
11062934, SERVICE KIT SNM2YN CO06 (SPEC.BOBCAT)
11084510, SERVICE KIT,D-SERIES,MOTOR
221.20.044.0K, SERVICE PART SNM2/.. . CO01-06
215.10.171.0K, SERVICE PART TF100/CI02
11050521, SERVICE SHAFT H1B060 ASSY (GN)
11050512, SERVICE SHAFT H1B110 ASSY (DN)
11050495, SERVICE SHAFT H1B110 ASSY (JN)
11054445, SERVICE SHAFT H1B160 ASSY (EN)
11050513, SERVICE SHAFT-SP H1B080 ASSY (JS)
11051879, SERVICE VALVE-SEGMENT 2POS H1B060 ASSY
11051881, SERVICE VALVE-SEGMENT 2POS H1B080 ASSY
11051883, SERVICE VALVE-SEGMENT 2POS H1B110 ASSY

11051880, SERVICE VALVE-SEGMENT H1B060 ASSY
11051884, SERVICE VALVE-SEGMENT H1B110 ASSY
11054387, SERVICE VALVE-SEGMENT H1B160 ASSY
11047885, SERVICE-KIT 51MV PIN SVNCH JOINT
11046242, SERVICE-KIT 90MF130 DWDR-CLAAS
11030920, SERVICE-KIT 90PV100 DWDR-CLAAS
11047104, SERVICE-KIT 90PV130 CYLINDER-BLOCK-CLAAS
11031190, SERVICE-KIT 90PV130 DWDR-CLAAS
505395, SERVO ARM
780023, SERVO ARM ASSY.
772400, SERVO ARM ASSY-9/030
8100499, SERVO ARM ASSY-HOLD DOWN (90P075)
143610, SERVO CONTROL
145870, SERVO CONTROL
146878, SERVO CONTROL
146894, SERVO CONTROL
356758, SERVO CONTROL
500873, SERVO CONTROL
501460, SERVO CONTROL
501930, SERVO CONTROL
502110, SERVO CONTROL
505197, SERVO CONTROL
506399, SERVO CONTROL
506584, SERVO CONTROL
508613, SERVO CONTROL
508616, SERVO CONTROL
562231, SERVO CONTROL
665950, SERVO CONTROL
711077, SERVO CONTROL
719476, SERVO CONTROL
725788, SERVO CONTROL
725796, SERVO CONTROL
731422, SERVO CONTROL
734004, SERVO CONTROL
744706, SERVO CONTROL
751149, SERVO CONTROL
778530/P, SERVO CONTROL
525980, SERVO CONTROL 20-23 (Viton)
10102623, SERVO CTRL PCB CPL.
1700875, SERVO PIEST PISTON-SERVO
543694, SERVO PISTON
612358, SERVO PISTON
612911, SERVO PISTON
624189, SERVO PISTON
652909, SERVO PISTON
711945, SERVO PISTON
734939, SERVO PISTON
9270758, SERVO PISTON ASSY
8000760, SERVO PISTON ASSY, HD, 90P055
335299, SERVO PISTON ASSY.

366666, SERVO PISTON ASSY.
509282, SERVO PISTON ASSY.
637207, SERVO PISTON ASSY.
637231, SERVO PISTON ASSY.
624171, SERVO PISTON GUIDE
652941, SERVO PISTON GUIDE
4510352, SERVO PISTON KIT, 45CC, KRR, SMALL
9260142, SERVO RINK
318030, SERVO SLEEVE
501836, SERVO SLEEVE
505008, SERVO SLEEVE
520106, SERVO SLEEVE
521724, SERVO SLEEVE
548578, SERVO SLEEVE
596544, SERVO SLEEVE
659235, SERVO SLEEVE
659953, SERVO SLEEVE
1740688, SERVO SLEEVE
1740707, SERVO SLEEVE
362087, SERVO SLEEVE ASSY.
362095, SERVO SLEEVE ASSY.
362103, SERVO SLEEVE ASSY.
500653, SERVO SLEEVE ASSY.
588335, SERVO SLEEVE ASSY.
607937, SERVO SLEEVE ASSY.
634733, SERVO SLEEVE ASSY.
704155, SERVO SLEEVE ASSY.
8052F004-B, SERVO SLEEVE KIT-ADJUSTABLE
8052F003-B, SERVO SLEEVE KIT-NO LIMITION
350322, SERVO-ARM 90PV042
354282, SERVO-ARM 90PV042 ASSY
502976, SERVO-ARM 90PV042 ASSY
8000318, SERVO-ARM 90PV055 ASSY
518323, SERVO-ARM 90PV075 ASSY
519046, SERVO-ARM 90PV075 VIP
518629, SERVO-ARM 90PV100 ASSY
521607, SERVO-ARM 90PV100 VIP
303214, SERVO-ARM 90PV130 ASSY
11000397, SERVO-ARM 90PV130 VIP
746339, SERVO-ARM 90PV180-250 ASSY
724807, SERVO-CONTROL 90PV075-100
503014, SERVO-CYLINDER 90P130
515323, SERVOK.(7)90P130 M. VORSP.HUELSE. KPL.
515327, SERVOK.(H)90P100 M. VORSP.HUELSE. KPL.
515836, SERVOK.(H)90P130 M. VORSP.HUELSE KPL.
778365, SERVOKOLBEN KPL.2/119
509276, SERVOKOLBEN KPL.90P042 FBA
511806, SERVOKOLBEN KPL.90P075(E)
511613, SERVOKOLBEN KPL.90P100(E)
509289, SERVOKOLBEN KPL.90P180 DURCHSCHWENK

637199, SERVOKOLBENMANTEL 20/21
630376, SERVOKOLBENMANTEL 22/23
11089763, SERVO-PISTON 2/033-052
11089764, SERVO-PISTON 2/227-334
11043400, SERVO-PISTON 2POS H1B060 ASSY
11023129, SERVO-PISTON 2POS H1B080 ASSY
11020417, SERVO-PISTON 2POS H1B110 ASSY
508186, SERVO-PISTON 51#060-1 ASSY
508181, SERVO-PISTON 51#080-1 ASSY
508187, SERVO-PISTON 51#110-1 ASSY
520688, SERVO-PISTON-TMP-D42
509181, SERVO-PRESS-SUPPLY-OPTION 51# EL BPD, C0
505553, SERVO-PRESS-SUPPLY-OPTION 51#, K1
505554, SERVO-PRESS-SUPPLY-OPTION 51#, K2
505555, SERVO-PRESS-SUPPLY-OPTION 51#, K3/K4
508557, SERVO-PRESS-SUPPLY-OPTION 51#, K5
503927, SERVO-PRESS-SUPPLY-OPTION C2/C4, C5/C6
520701, SERVO-SLEEVE-TMPD42MM
500867, SERVOV.2/033-070 SPV(NULLST.SCHALT.)
142380, SERVOV.GEH.2/033-334 (F.POR,M.RINGKANAL)
513545, SERVOV.KPL.(POR,MBL.,Wechselv-Ebs)1-6000
9260319, SERVOVALEC KPL. SERVOZYLINDER KP
508006/P, SERVOVENT.(M8)90P100
719468, SERVOVENT.(MG)90P055
510549, SERVOVENT.(MN)90P100
507316, SERVOVENT.(MO)90P130
501929, SERVOVENT.(MR)90P055
508506, SERVOVENT.(MS)90P042
508508/P, SERVOVENT.(MS)90P042
509465, SERVOVENT.(NU)90P130
509473, SERVOVENT.(NU)90P130
517401, SERVOVENT.(RS)90P130
510753, SERVOVENT.(RU)90P075
510380, SERVOVENT.(RU)90P075-100
511645, SERVOVENT.(RU)90P130
511646, SERVOVENT.(RU)90P130
515518, SERVOVENT.2/119 (F.POR)
515856, SERVOVENT.2/119 (SMV/O.RINGKANAL)
624098, SERVOVENT.27 POR VITON
507004, SERVOVENT.EINBAUS. BG 25/26 F. POR
684308, SERVOVENT.EINBAUSATZ 23
647305, SERVOVENT.EINBAUSATZ 24
705970, SERVOVENT.POR+MESSBLENDE
732172, SERVOVENT.POR+MESSBLENDE
144790, SERVOVENTILDUESE 1,8
779843, SERVOZYL. 2/119-166
693853, SERVOZYL.(3)90P075 KPL.
694844, SERVOZYL.(4)90P075 M.HUBBEGR. A+B KPL.
348987, SERVOZYL.(6)90P055 FBA KPL.
351692/P, SERVOZYL.(7)90P042 FBA KPL.

773176, SERVOZYL.(7)90P055 FBA KPL.
728287, SERVOZYL.(7)90P130 KPL.
500871, SERVOZYL.(D)90P030 FBA KPL.
508805, SERVOZYL.(E)90P100 M.HUBBEGR. 1+2 KPL.
753178, SERVOZYL.(E)90P180 M.HUBBEGR. 1+2 KPL.
361741, SERVOZYL.2/033-052
362111, SERVOZYL.2/033-052 7/8-14 UNF
362178, SERVOZYL.2/070-089 M18X1,5 FBA
517425, SERVOZYL.2/227-334 7/8-14UNF
155L3162, SET FOR PVM (Reservedelspligt)
153F2112, SET OF FEATHER/TONGUE
155G8510, SET OF SEALES
150B4001, SET OF SEALS
151-1072, SET OF SEALS
151-1101, SET OF SEALS
151-1111, SET OF SEALS
151-1154, SET OF SEALS
151-1159, SET OF SEALS
151-1166, SET OF SEALS
151-1177, SET OF SEALS
151-1178, SET OF SEALS
151-1179, SET OF SEALS
151-1271, SET OF SEALS
151-1272, SET OF SEALS
151-1273, SET OF SEALS
151-1274, SET OF SEALS
151-1284, SET OF SEALS
151-1286, SET OF SEALS
151-1295, SET OF SEALS
151B0115, SET OF SEALS
151B0125, SET OF SEALS
151B0127, SET OF SEALS
151G0201, SET OF SEALS
151G0202, SET OF SEALS
151G2201, SET OF SEALS
151G4103, SET OF SEALS
151H1100, SET OF SEALS
151Z2072, SET OF SEALS
151Z2073, SET OF SEALS
152B4000, SET OF SEALS
152B4012, SET OF SEALS
152B4013, SET OF SEALS
152B6200, SET OF SEALS
153B1104, SET OF SEALS
155G8501, SET OF SEALS
155G8502, SET OF SEALS
155G8505, SET OF SEALS
155G8507, SET OF SEALS
155G8508, SET OF SEALS
155G8518, SET OF SEALS

155G8519, SET OF SEALS
155G8522, SET OF SEALS
155G8523, SET OF SEALS
155G8524, SET OF SEALS
155G8525, SET OF SEALS
155G8526, SET OF SEALS
155G8527, SET OF SEALS
155G8528, SET OF SEALS
155U9900, SET OF SEALS
157B3999, SET OF SEALS
157B4991, SET OF SEALS
157B4996, SET OF SEALS
157B4998, SET OF SEALS
157B4999, SET OF SEALS
157B5999, SET OF SEALS
157B6999, SET OF SEALS
157B8999, SET OF SEALS
633B0520, SET OF SEALS
151-1282, SET OF SEALS DS HPS
11008362, SET OF SEALS FOR EHPS/PVG/OLS320
151-1275, SET OF SEALS OMP
151-1296, SET OF SEALS OMP AND OMR
151-1293, SET OF SEALS OMP/OMR
151-1277, SET OF SEALS OMR
151F1033, SET OF SEALS OMSS
151F1058, SET OF SEALS OMSS
151B1040, SET OF SEALS OMTS
151B1086, SET OF SEALS OMTU
151B1041, SET OF SEALS OMVS
151B1089, SET OF SEALS OMVU
11059548, SET OF SEALS OSQ VITON
1745312, SET SCREW-FLAT PT, M8X1X35-33H DIN913
9007774-0007, SET SCREW-OVAL PT, .375 -24 X .875
K00387, SETSCR,6-32,.19,CUP,IHEX,ST,BO
681X0614, SETSCREW
121.24.003.00, SEU3NN/022RN01BAP1C7C7NNNN/NNNN
121.24.025.00, SEU3NN/026RN01FAP1F5F5NNNN/NNNN
121.24.007.00, SEU3NN/033RN01BAP1C7CANNNN/NNNN
211.24.032.00, SEW3NN/033LN01BLNNCAC7NNNN/NNNN
211.24.033.00, SEW3NN/033RN01BLNNCAC7NNNN/NNNN
211.24.035.00, SEW3NN/038RN01BLNNCAC7NNNN/NNNN
211.24.037.00, SEW3NN/044RN01BLNNCACANNNN/NNNN
11100618, SGM2GC/8,0LA9YDBC5NNNNNNNN/NNNN
11082451, SGM2NC/014BA06BAC5NNNNNNNN/NNNN
11087721, SGM2NC/8,0BA02AAC5NNNNNNNN/NNNN
11082964, SGM2VC/014LA9YDBRANNNNNNN/XAUNN
11095735, SGM2VC/017RA06BARANNNNNNN/XAUNN
11100134, SGM2VC/8,ORA06BARANNNNNNN/XAINN
11039952, SGM2YL/011LA01BAY4NNF4NNNN/XAUNP
11089579, SGM2YL/011LA01BAY4NNF4NNNN/XAUNP

11046981, SGM2YL/011RA02AAY4NNB5NNNN/XAQNN
83016242, SGM2YL/011RA02AAY4NNB5NNNN/XBSNN
83022101, SGM2YL/011RA02AAY4NNB5NNNN/XBUNN
83018425, SGM2YL/014LA06BAY4NNE5NNNN/XAQNN
11085087, SGM2YL/014RA01BAY4NNF4NNNN/XAUNN
83019739, SGM2YL/014RA02AAY4NNB7NNNN/XBUNN
83021005, SGM2YL/014RA02AAY4NNB7NNWN/XBUNN
83014089, SGM2YL/014RA02AAY4NNE5NNNN/XBQNN
83018256, SGM2YL/014RA06BAY4NNE5NNNN/XASNN
11056919, SGM2YL/017LA06BAYXNNE5NNNN/XNNAP
83019467, SGM2YL/017RA01BAY4NNE5NNNN/XBUNN
83019090, SGM2YL/017RA02AAY4NNB7NNNN/XBUNN
83018816, SGM2YL/017RA02AAY4NNB7NNNN/XBWNN
83022744, SGM2YL/017RA02AAY4NNB7NNNN/XBWWN
83013715, SGM2YL/017RA02AAY4NNE5NNNN/XBQNN
83008619, SGM2YL/017RA02AAY4NNE5NNWN/XBUNN
83012937, SGM2YL/022RA02AAY4NNB7NNNN/XBUNN
11059183, SGM2YL/14 D CO+2 XBU1.
11102513, SGM2YL/14 S CO+2 XBS1.
11076885, SGM2YL/17 D CO+2 XBU1E
83022403, SGM2YL/8,0LA02AAY4NNE5NNNN/XBONN
11046632, SGM2YL/8,0RA02AAY4NNB5NNNN/XASNN
11046059, SGM2YL/8,0RA02AAY4NNB5NNNN/XAWNN
11033608, SGM2YL/8,0RA02AAY4NNB5NNNN/XBUNN
121.23.009.00, SGM2YN/011L406GBY6NNE5NNNN/XNNNN
83022652, SGM2YN/011LA01BAY6NNB5NNNN/XBINN
83022532, SGM2YN/011LA01BAY6NNC3NNNN/XBINN
83011697, SGM2YN/011LA02AAY6NNB5NNNN/XBMNN
11032390, SGM2YN/011LA02AAY6NNB5NNNN/XNNNN
11037016, SGM2YN/011LA06BAY6NNE5NNNN/XNNNN
121.23.025.00, SGM2YN/011LA06GBY6NNE5NNNN/XNNNN
121.23.015.00, SGM2YN/011R401BAY6NNC3NNNN/XAQNN
121.23.002.00, SGM2YN/011R406GBY6NNE5NNNN/XNNNN
11046977, SGM2YN/011RA02AAY6NNB5NNNN/XAONN
11032397, SGM2YN/011RA02AAY6NNB5NNNN/XNNNN
83022370, SGM2YN/011RA06BAY6NNE5NNNN/XBYNN
11036988, SGM2YN/011RA06BAY6NNE5NNNN/XNNNN
83007306, SGM2YN/011RA06GBY6NNE5NNNN/XAQNN
83011866, SGM2YN/011RA06GBY6NNE5NNNN/XASNN
83013395, SGM2YN/011RA06GBY6NNE5NNNN/XBUNN
121.23.017.00, SGM2YN/011RA06GBY6NNE5NNNN/XNNNN
121.23.010.00, SGM2YN/014L406GBY6NNE5NNNN/XNNNN
83021766, SGM2YN/014LA01BAY6NNE5NNNN/XAQNN
11032391, SGM2YN/014LA02AAY6NNB7NNNN/XNNNN
11037017, SGM2YN/014LA06BAY6NNE5NNNN/XNNNN
121.23.027.00, SGM2YN/014LA06GBY6NNE5NNNN/XNNNN
121.23.003.00, SGM2YN/014R406GBY6NNE5NNNN/XNNNN
83021111, SGM2YN/014RA01BAY6NNE5NNNN/XBQNN
11032398, SGM2YN/014RA02AAY6NNB7NNNN/XNNNN
83014583, SGM2YN/014RA02AAY6NNE5NNNN/XBONN

11036989, SGM2YN/014RA06BAY6NNE5NNNN/XNNNN
83014270, SGM2YN/014RA06GBY6NNE5NNNN/XAFNN
83011867, SGM2YN/014RA06GBY6NNE5NNNN/XAUNN
83014799, SGM2YN/014RA06GBY6NNE5NNNN/XBQNN
83018541, SGM2YN/014RA06GBY6NNE5NNNN/XBUNN
121.23.019.00, SGM2YN/014RA06GBY6NNE5NNNN/XNNNN
11094077, SGM2YN/014RA9YDBY6NNE5NNNN/XBWNN
121.23.011.00, SGM2YN/017L406GBY6NNE5NNNN/XNNNN
83014672, SGM2YN/017LA02AAY6NNB7NNNN/XBWWN
11032412, SGM2YN/017LA02AAY6NNB7NNNN/XNNNN
11037018, SGM2YN/017LA06BAY6NNE5NNNN/XNNNN
121.23.028.00, SGM2YN/017LA06GBY6NNE5NNNN/XNNNN
121.23.004.00, SGM2YN/017R406GBY6NNE5NNNN/XNNNN
11099156, SGM2YN/017RA01BAY6NNB7NNNN/XBUNN
83014598, SGM2YN/017RA02AAY6NNB7NNNN/XBYNN
11032399, SGM2YN/017RA02AAY6NNB7NNNN/XNNNN
11043372, SGM2YN/017RA02AAY6NNE5NNNN/XNNNN
11050150, SGM2YN/017RA06BAY6NNE5NNNN/XBUNN
11036990, SGM2YN/017RA06BAY6NNE5NNNN/XNNNN
121.23.020.00, SGM2YN/017RA06GBY6NNE5NNNN/XNNNN
121.23.012.00, SGM2YN/019L406GBY6NNE6NNNN/XNNNN
11032413, SGM2YN/019LA02AAY6NNB7NNNN/XNNNN
11037019, SGM2YN/019LA06BAY6NNE6NNNN/XNNNN
121.23.029.00, SGM2YN/019LA06GBY6NNE6NNNN/XNNNN
121.23.005.00, SGM2YN/019R406GBY6NNE6NNNN/XNNNN
83014597, SGM2YN/019RA02AAY6NNB7NNNN/XBWNN
11032400, SGM2YN/019RA02AAY6NNB7NNNN/XNNNN
83022549, SGM2YN/019RA06BAY6NNE6NNNN/XBWAN
11033049, SGM2YN/019RA06BAY6NNE6NNNN/XBWNN
11036991, SGM2YN/019RA06BAY6NNE6NNNN/XNNNN
11070749, SGM2YN/019RA06GBY6NNE6NNNN/XAYNN
83008458, SGM2YN/019RA06GBY6NNE6NNNN/XBUNN
83008043, SGM2YN/019RA06GBY6NNE6NNNN/XBWNN
121.23.021.00, SGM2YN/019RA06GBY6NNE6NNNN/XNNNN
121.23.013.00, SGM2YN/022L406GBY6NNE6NNNN/XNNNN
11032414, SGM2YN/022LA02AAY6NNB7NNNN/XNNNN
11037020, SGM2YN/022LA06BAY6NNE6NNNN/XNNNN
121.23.030.00, SGM2YN/022LA06GBY6NNE6NNNN/XNNNN
121.23.006.00, SGM2YN/022R406GBY6NNE6NNNN/XNNNN
11032401, SGM2YN/022RA02AAY6NNB7NNNN/XNNNN
83009279, SGM2YN/022RA06BAY6NNE6NNNN/XBONN
83009278, SGM2YN/022RA06BAY6NNE6NNNN/XBQNN
83008196, SGM2YN/022RA06BAY6NNE6NNNN/XBSNN
11036992, SGM2YN/022RA06BAY6NNE6NNNN/XNNNN
11066186, SGM2YN/022RA06GBY6NNE6NNNN/XBWNN
121.23.022.00, SGM2YN/022RA06GBY6NNE6NNNN/XNNNN
121.23.014.00, SGM2YN/025L406GBY6NNE6NNNN/XNNNN
11032415, SGM2YN/025LA02AAY6NNB7NNNN/XNNNN
11037021, SGM2YN/025LA06BAY6NNE6NNNN/XNNNN
121.23.031.00, SGM2YN/025LA06GBY6NNE6NNNN/XNNNN

121.23.007.00, SGM2YN/025R406GBY6NNE6NNNN/XNNNN
11032402, SGM2YN/025RA02AAY6NNB7NNNN/XNNNN
11036994, SGM2YN/025RA06BAY6NNE6NNNN/XNNNN
121.23.023.00, SGM2YN/025RA06GBY6NNE6NNNN/XNNNN
121.23.008.00, SGM2YN/8,0L406GBY6NNE5NNNN/XNNNN
11032389, SGM2YN/8,0LA02AAY6NNB5NNNN/XNNNN
11037015, SGM2YN/8,0LA06BAY6NNE5NNNN/XNNNN
83008512, SGM2YN/8,0LA06GBY6NNE5NNNN/XBQNN
121.23.024.00, SGM2YN/8,0LA06GBY6NNE5NNNN/XNNNN
11030082, SGM2YN/8,0R402AAY6NNB5NNNN/XAUNN
121.23.001.00, SGM2YN/8,0R406GBY6NNE5NNNN/XNNNN
83011080, SGM2YN/8,0RA02AAY6NNB5NNNN/XAQNN
11032396, SGM2YN/8,0RA02AAY6NNB5NNNN/XNNNN
11049102, SGM2YN/8,0RA02AAY6NNE5NNNN/XBYVN
11043371, SGM2YN/8,0RA02AAY6NNE5NNNN/XNNNN
11070602, SGM2YN/8,0RA06BAY6NNE5NNNN/XAUNN
11036983, SGM2YN/8,0RA06BAY6NNE5NNNN/XNNNN
83012275, SGM2YN/8,0RA06GBY6NNE5NNNN/XAONN
83009389, SGM2YN/8,0RA06GBY6NNE5NNNN/XASNN
121.23.016.00, SGM2YN/8,0RA06GBY6NNE5NNNN/XNNNN
11082794, SGM3NC/038BA07BCC6NNNNNNNN/NNNNN
11082912, SGM3VC/038LA9YDARANNNNNNNN/XAWNN
11126641, SGM3Y./33 D CO91 +++_E
11124119, SGM3Y./33 S CO91 +++_E
11029970, SGM3YN/022LA07BCY6NNE6NNNN/XBWCN
121.26.021.00, SGM3YN/022LA07BCY6NNE6NNNN/XNNNN
11041645, SGM3YN/022LA07GBY6NNE6NNNN/XNNNN
121.26.008.00, SGM3YN/022LN07BCY6NNE6NNNN/XNNNN
121.26.016.00, SGM3YN/022RA07BCY6NNE6NNNN/XNNNN
11041635, SGM3YN/022RA07GBY6NNE6NNNN/XNNNN
121.26.015.00, SGM3YN/022RN01BAY6NNC7NNNN/XBQNN
121.26.014.00, SGM3YN/022RN01BAY6NNC7NNNN/XBUNN
121.26.003.00, SGM3YN/022RN07BCY6NNE6NNNN/XNNNN
11077199, SGM3YN/026LA07BCY6NNE6NNNN/XNNAP
11077200, SGM3YN/026LA07BCY6NNE6NNNN/XNNAP
121.26.022.00, SGM3YN/026LA07BCY6NNE6NNNN/XNNNN
11041646, SGM3YN/026LA07GBY6NNE6NNNN/XNNNN
121.26.009.00, SGM3YN/026LN07BCY6NNE6NNNN/XNNNN
83022550, SGM3YN/026RA07BCY6NNE6NNNN/XBUAN
83013087, SGM3YN/026RA07BCY6NNE6NNNN/XBUNN
121.26.017.00, SGM3YN/026RA07BCY6NNE6NNNN/XNNNN
83022447, SGM3YN/026RA07GBY6NNE6NNNN/XBONN
11041637, SGM3YN/026RA07GBY6NNE6NNNN/XNNNN
121.26.013.00, SGM3YN/026RN01BAY6NNC7NNNN/XBWNN
121.26.002.00, SGM3YN/026RN07BCY6NNE6NNNN/XAVNN
121.26.001.00, SGM3YN/026RN07BCY6NNE6NNNN/XAWNN
121.26.004.00, SGM3YN/026RN07BCY6NNE6NNNN/XNNNN
121.26.026.00, SGM3YN/026RN07GBY6NNE6NNNN/XNNNN
83022230, SGM3YN/033LA01BAY6NNE6NNNN/XBQNN
11046690, SGM3YN/033LA07BCY6NNA3NNNN/XBUNN

83022941, SGM3YN/033LA07BCY6NNA3NNNN/XNNNN
121.26.023.00, SGM3YN/033LA07BCY6NNE6NNNN/XNNNN
11041647, SGM3YN/033LA07GBY6NNE6NNNN/XNNNN
121.26.010.00, SGM3YN/033LN07BCY6NNE6NNNN/XNNNN
11099287, SGM3YN/033RA01BAY6NNA3NNNN/XBRNN
83022921, SGM3YN/033RA01BAY6NNE6NNNN/XBQNN
83010470, SGM3YN/033RA07BCY6NNE6NNNN/XASNN
83008912, SGM3YN/033RA07BCY6NNE6NNNN/XAWNN
83008459, SGM3YN/033RA07BCY6NNE6NNNN/XBUNN
121.26.018.00, SGM3YN/033RA07BCY6NNE6NNNN/XNNNN
11033686, SGM3YN/033RA07BPY6NNE6NNNN/XBWWN
83019550, SGM3YN/033RA07GBY6NNE6NNNN/XBWNN
11041638, SGM3YN/033RA07GBY6NNE6NNNN/XNNNN
121.26.005.00, SGM3YN/033RN07BCY6NNE6NNNN/XNNNN
121.26.024.00, SGM3YN/038LA07BCY6NNE6NNNN/XNNNN
11041648, SGM3YN/038LA07GBY6NNE6NNNN/XNNNN
121.26.011.00, SGM3YN/038LN07BCY6NNE6NNNN/XNNNN
121.26.019.00, SGM3YN/038RA07BCY6NNE6NNNN/XNNNN
83021664, SGM3YN/038RA07BPY6NNE6NNNN/XBWWN
11041639, SGM3YN/038RA07GBY6NNE6NNNN/XNNNN
121.26.006.00, SGM3YN/038RN07BCY6NNE6NNNN/XNNNN
11068163, SGM3YN/044LA07BCY6NNE6NNNN/XAINN
83013035, SGM3YN/044LA07BCY6NNE6NNNN/XBINN
121.26.025.00, SGM3YN/044LA07BCY6NNE6NNNN/XNNNN
11041649, SGM3YN/044LA07GBY6NNE6NNNN/XNNNN
121.26.012.00, SGM3YN/044LN07BCY6NNE6NNNN/XNNNN
121.26.020.00, SGM3YN/044RA07BCY6NNE6NNNN/XNNNN
11041640, SGM3YN/044RA07GBY6NNE6NNNN/XNNNN
121.26.007.00, SGM3YN/044RN07BCY6NNE6NNNN/XNNNN
984F9856, SHACKLE
144402, SHAFT
145540, SHAFT
148197, SHAFT
148627, SHAFT
305185, SHAFT
307553, SHAFT
322685, SHAFT
337253, SHAFT
340364, SHAFT
347344, SHAFT
500033, SHAFT
500298, SHAFT
506063, SHAFT
509976, SHAFT
514448, SHAFT
515676, SHAFT
524074, SHAFT
524090, SHAFT
525691, SHAFT
532473, SHAFT

536854, SHAFT
537571, SHAFT
537712, SHAFT
554758, SHAFT
566653, SHAFT
566679, SHAFT
566992, SHAFT
573865, SHAFT
574020, SHAFT
575670, SHAFT
576769, SHAFT
577676, SHAFT
578286, SHAFT
587923, SHAFT
592253, SHAFT
594986, SHAFT
594994, SHAFT
596619, SHAFT
600148, SHAFT
606160, SHAFT
613299, SHAFT
622183, SHAFT
632182, SHAFT
647032, SHAFT
658724, SHAFT
660183, SHAFT
728790, SHAFT
728808, SHAFT
740902, SHAFT
780668, SHAFT
1010731, SHAFT
1010921, SHAFT
1020299, SHAFT
1020644, SHAFT
1720336, SHAFT
1720337, SHAFT
1720415, SHAFT
1720428, SHAFT
1720429, SHAFT
1720490, SHAFT
1720630, SHAFT
1720669, SHAFT
8000501, SHAFT
11008368, SHAFT
151-1270, SHAFT
151-1991, SHAFT
151-1992, SHAFT
151-1993, SHAFT
151-2663, SHAFT
151-2664, SHAFT

151-2682, SHAFT
151-2684, SHAFT
151-2685, SHAFT
151-2686, SHAFT
151-2693, SHAFT
151-4100, SHAFT
151-5474, SHAFT
151-5533, SHAFT
151-5537, SHAFT
151-5538, SHAFT
151-5540, SHAFT
151-5541, SHAFT
151-5542, SHAFT
151-5543, SHAFT
151-5544, SHAFT
151-5548, SHAFT
151-5551, SHAFT
151-5552, SHAFT
151-5553, SHAFT
151-5555, SHAFT
151-5556, SHAFT
151-5557, SHAFT
151-5599, SHAFT
151-5600, SHAFT
151-5612, SHAFT
151-5714, SHAFT
151-5715, SHAFT
151-5716, SHAFT
151-5719, SHAFT
151-5721, SHAFT
151-5827, SHAFT
151B0128, SHAFT
151B0180, SHAFT
151B1439, SHAFT
151B1487, SHAFT
151B1597, SHAFT
151B1634, SHAFT
151B1635, SHAFT
151B1727, SHAFT
151B1728, SHAFT
151B1767, SHAFT
151B1831, SHAFT
151B1851, SHAFT
151B1854, SHAFT
151B5306, SHAFT
151B5354, SHAFT
151F0126, SHAFT
151F0127, SHAFT
151F1525, SHAFT
151F1527, SHAFT

151F1528, SHAFT
151F1529, SHAFT
151F1548, SHAFT
151F1577, SHAFT
151F1622, SHAFT
151F1623, SHAFT
151F1740, SHAFT
151F1741, SHAFT
151F1743, SHAFT
151F1786, SHAFT
151F1787, SHAFT
151F1865, SHAFT
151F1890, SHAFT
151F1912, SHAFT
151G0376, SHAFT
151G0377, SHAFT
151G0378, SHAFT
151G0386, SHAFT
151G0440, SHAFT
151G2307, SHAFT
151H0322, SHAFT
151H0323, SHAFT
151H0324, SHAFT
151H0326, SHAFT
151H0327, SHAFT
151H0385, SHAFT
151H0401, SHAFT
151H2309, SHAFT
151H2343, SHAFT
151H2375, SHAFT
151H2398, SHAFT
151H2412, SHAFT
151Z0128, SHAFT
151Z0335, SHAFT
J1720429, SHAFT
1700458, SHAFT 0.875 STR KEY W/AUX (L)
1700480, SHAFT 0.875, LONG STR KEY (K)
1700570, SHAFT 0.875, LONG STR KEY W/AUX (K)
1700261, SHAFT 038-045(K)15Z.-16/32, 21Z.-32/64
1700178, SHAFT 45P038-045(K)13Z.-16/32, 21Z.
3102309, SHAFT CHARGE PUMP
9800233, SHAFT CHG PUMP
9801615, SHAFT CHG PUMP
513580, SHAFT MOTOR
561548, SHAFT MOTOR
561555, SHAFT MOTOR
688481, SHAFT MOTOR
9210468, SHAFT MOTOR
9210547, SHAFT MOTOR
9220399, SHAFT MOTOR

9220516, SHAFT MOTOR
9220976, SHAFT MOTOR
9240216, SHAFT MOTOR
9240232, SHAFT MOTOR
9250348, SHAFT MOTOR
9250379, SHAFT MOTOR
9250415, SHAFT MOTOR
9260151, SHAFT MOTOR
9260181, SHAFT MOTOR
9270423, SHAFT MOTOR
4460121, SHAFT MOTOR (SPARES)
9230448, SHAFT MOTOR (SPARES)
3103117, SHAFT MOTOR, 15U, MF
3103128, SHAFT MOTOR, 15IL, MF
3102735, SHAFT MOTOR18 SERIES
3102765, SHAFT MOTOR18 SERIES
3103237, SHAFT MOTOR18 SERIES
151B1326, SHAFT OMT
151B1374, SHAFT OMT
561530, SHAFT PUMP
9210428, SHAFT PUMP
9210538, SHAFT PUMP
9210663, SHAFT PUMP
9220527, SHAFT PUMP
9221441, SHAFT PUMP
9221447, SHAFT PUMP
9230147, SHAFT PUMP
9230173, SHAFT PUMP
9230476, SHAFT PUMP
9230626, SHAFT PUMP
9231014, SHAFT PUMP
9250409, SHAFT PUMP
9260140, SHAFT PUMP
9260176, SHAFT PUMP
3102424, SHAFT PUMP (15) (SPARES)
3102211, SHAFT PUMP (18)
3102279, SHAFT PUMP (18)
3102308, SHAFT PUMP (18)
4460154, SHAFT PUMP (SPARES)
9210673, SHAFT PUMP (SPARES)
9230656, SHAFT PUMP (SPARES)
3103304, SHAFT PUMP, 15 PV
3102671, SHAFT PUMP, 15 PV (SPARES)
3103143, SHAFT PUMP, 15PV
3102747, SHAFT PUMP, 15PV, 9T
11052758, SHAFT PUMP, 15PV, 9T
3103140, SHAFT PUMP, 15T, PV
3101867, SHAFT PUMP, 15U, PV
3102035, SHAFT PUMP, 15U, PV
3102306, SHAFT PUMP18 SERIES

3102791, SHAFT PUMP18 SERIES
3101045, SHAFT TRUNNION
3102647, SHAFT TRUNNION
151H2308, SHAFT (11018898)
151-2683, SHAFT (11024492)
1700572, SHAFT 0.875, LONG STR KEY W/AUX (L)
4410039, SHAFT- 1 INCH TAPERED, 41CC
4740109, SHAFT- 1.25 STR KEY, 23T 24/48
151B0179, SHAFT 1-1/2" 17T SPLINED WITH BEARING
4740459, SHAFT 14T-12/24 W/AUX
4570081, SHAFT- 14T-12/24, NO AUX
4740461, SHAFT 17T-12/24 W/AUX
1700312, SHAFT 25/30 1IN TAPER
151F0112, SHAFT 32mm WITH BEARING
351122, SHAFT 41P046 15T 16/32 (C3)
151B0178, SHAFT 45mm TAPER WITH BEARING
11016481, SHAFT 45P 25/30 1IN TAPER W/21T AUX
1700757, SHAFT 45P38/45) 0.875 STR KEY
151B0102, SHAFT 50mm WITH BEARING
732685, SHAFT 51#060 14T ASSY (S1)
512570, SHAFT 51#060 14T DIN5480 (D1)
513034, SHAFT 51#060 14T DIN5480 ASSY (D1)
513033, SHAFT 51#060 16T DIN5480 ASSY (D2)
502253, SHAFT 51#060 21T 16/32 (C6)
737957, SHAFT 51#060 21T ASSY (C6)
513025, SHAFT 51#060 W/MAG SPEED RING ASSY (S1)
502258, SHAFT 51#080 14T 12/24 (S1)
722058, SHAFT 51#080 14T 12/24 ASSY (S1)
512572, SHAFT 51#080 16T DIN5480 (D2)
513037, SHAFT 51#080 16T DIN5480 ASSY (D2)
512571, SHAFT 51#080 18T DIN5480 (D3)
513035, SHAFT 51#080 18T DIN5480 ASSY (D3)
502259, SHAFT 51#080 23T 16/32 (C7)
722017, SHAFT 51#080 23T 16/32 ASSY C7
507077, SHAFT 51#080 W/MAG SP RING ASSY (S1)
513024, SHAFT 51#080 W/MAG SPEED RING ASSY (D3)
500100, SHAFT 51#110 13T 8/16 (F1)
725507, SHAFT 51#110 13T 8/16 ASSY (F1)
725507/P, SHAFT 51#110 13T 8/16 ASSY (F1)
512575, SHAFT 51#110 18T DIN5480 (D3)
513039, SHAFT 51#110 18T DIN5480 ASSY (D3)
512573, SHAFT 51#110 21T DIN5480 (D4)
513038, SHAFT 51#110 21T DIN5480 ASSY (D4)
500159, SHAFT 51#110 27T 16/32 (C8)
725499, SHAFT 51#110 27T 16/32 ASSY (C8)
513023, SHAFT 51#110 W/MAG SPEED RING ASSY (D3)
502265, SHAFT 51#160 13T 8/16 (F1,Z1)
720052, SHAFT 51#160 13T ASSY (F1)
719971, SHAFT 51#160 15T ASSY (F2)
512577, SHAFT 51#160 21T DIN5480 (D4)

513041, SHAFT 51#160 21T DIN5480 ASSY D4
512576, SHAFT 51#160 24T DIN5480 (D5)
513040, SHAFT 51#160 24T DIN5480 ASSY (D5)
502266, SHAFT 51#160 27T 16/32 (C8)
11070256, SHAFT 51#160 27T 16/32 (C8)
725515, SHAFT 51#160 27T 16/32 ASSY (C8)
516152, SHAFT 51#160 W/MAG SP RING ASSY (C8)
507078, SHAFT 51#160 W/MAG SP RING ASSY (F2)
513022, SHAFT 51#160 W/MAG SPEED RING ASSY (F1)
502272, SHAFT 51#250 15T 8/16 (F2)
720086, SHAFT 51#250 15T ASSY (F2)
502273, SHAFT 51#250 27T 16/32 (C8)
731117, SHAFT 51#250 27T 16/32 ASSY (C8)
507080, SHAFT 51#250 W/MAG SP RING ASSY (F2)
755801, SHAFT 90K042 15T 16/32 (C4)
733535, SHAFT 90MF030 13T 16/32 (C2)
500079, SHAFT 90MF030 15T 16/32 (C3)
760132, SHAFT 90MF030 STR KEY (K4)
723098, SHAFT 90MF042 13T 16/32 (C2)
787127, SHAFT 90MF042 15T 16/32 (C3)
770347, SHAFT 90MF042 STR KEY,THD M8 (K4)
11014512, SHAFT 90MF055 1.375 STRAIGHT KEY (K1)
347336, SHAFT 90MF055 1.375 TPR,KEY-WDF ASSY(T1)
11012275, SHAFT 90MF055 14T 12/24 (S1)
329680, SHAFT 90MF055 21T 16/32 ASSY (C6)
11012424, SHAFT 90MF075 14T 12/24 (S1)
704759, SHAFT 90MF075 18T B35x31 DIN5482 (D4)
11012279, SHAFT 90MF075 21T 16/32 (C6)
675959, SHAFT 90MF075 23T 16/32 (C7)
510686, SHAFT 90MF075 23T 16/32 M12 E7
361634, SHAFT 90MF100 1.5 TAPER W/KEYWAY (T2)
306696, SHAFT 90MF100 13T 8/16 (F1)
11012429, SHAFT 90MF100 14T 12/24 (S1)
512024, SHAFT 90MF100 21T 16/32 (C6)
11044408, SHAFT 90MF100 23T 16/32 DWDR (C7)
11002315, SHAFT 90MF100 ASSY (F3)
511785, SHAFT 90MF100 TAPER/M24x1.5 (TJ)
310458, SHAFT 90MF130 13T 8/16 (F1)
515344, SHAFT 90MF130 13T 8/16 SPECIAL (F3)
515592, SHAFT 90MF130 23T 16/32 SPECIAL (L7)
11046231, SHAFT 90MF130 27T 16/32 DWDR (C8)
327353, SHAFT 90PV030 15T 16/32 (C3)
319327, SHAFT 90PV042 1.0 TAPER ASSY (T3)
512471, SHAFT 90PV042 1.0 TAPER ASSY (T8)
340521, SHAFT 90PV042 15T 16/32 (C3)
742775, SHAFT 90PV042 19T 16/32 (C5)
342915, SHAFT 90PV042 TAPER (T3)
511778, SHAFT 90PV042 TAPER W/O KEYWAY (T8)
331637, SHAFT 90PV055 1.375 TAPER ASSY (T1)
503396, SHAFT 90PV055+42PV028 21T 16/32 B to B

311993, SHAFT 90PV075 1.5 TPR,KEY-WDF ASSY (T2)
701441, SHAFT 90PV075 14T 12/24 (S1)
318998, SHAFT 90PV075 21T 16/32 (C6)
693838, SHAFT 90PV075 23T 16/32 (C7)
694281, SHAFT 90PV075 23T 16/32 ASSY (C7)
506860, SHAFT 90PV075 23T 16/32 M10 (D7)
504004, SHAFT 90PV075 25T 20/40 (G1)
312009, SHAFT 90PV075 TAPER W/KEYWAY (T2,TA)
511616, SHAFT 90PV075 TAPER/M24x1.5 (T6)
504059, SHAFT 90PV075 TAPER/M24X1.5 (TG)
504058, SHAFT 90PV075 TPR, M24 W/FLG ASSY (TG)
8200176, SHAFT 90PV100 (K3)
319384, SHAFT 90PV100 1.5 TAPER ASSY (T2)
341974, SHAFT 90PV100 13T 8/16 (F1)
341982, SHAFT 90PV100 14T 12/24 (S1)
509239, SHAFT 90PV100 21T 16/32 (C6)
341958, SHAFT 90PV100 23T 16/32 (C7)
305847, SHAFT 90PV100 23T 16/32 ASSY (C7)
504307, SHAFT 90PV100 23T 16/32 M10 (D7)
504352, SHAFT 90PV100 25T 20/40 (G1)
342006, SHAFT 90PV100 TAPER W/KEYWAY (T2,TA)
511617, SHAFT 90PV100 TAPER/M24x1.5 (T6)
366468, SHAFT 90PV130 1.75 TAPER ASSY (T4)
335695, SHAFT 90PV130 13T 8/16 (F1)
506911, SHAFT 90PV130 13T 8/16 (J5)
518465, SHAFT 90PV130 13T 8/16 SPCL SFT END (F4)
303495, SHAFT 90PV130 27T 16/32 (C8)
11031204, SHAFT 90PV130 27T 16/32 DWDR-CLAAS
503443, SHAFT 90PV130 27T 16/32 M10 (D8)
346601, SHAFT 90PV130 TAPER W/KEYWAY (T4,TD)
508592, SHAFT 90PV130 TAPER W/O KEYWAY (T7,TH)
511619, SHAFT 90PV130 TAPER/M30x1.5 (T7)
11004306, SHAFT 90PV180 13T 8/16 (F1)
11004305, SHAFT 90PV180 27T 16/32 (C8)
504411, SHAFT 90PV250 13T 8/16 (F1)
504338, SHAFT 90PV250 27T 16/32 (C8)
4410045, SHAFT ASSEMBLY-1 INCH TAPER
4410027, SHAFT ASSEMBLY-15T, 42P
4410042, SHAFT ASSY, 13T
11049169, SHAFT ASSY, H1P147-165 13T 8/16 (G3)
517895, SHAFT ASSY, W/MAG SP RING, S51_250
513594, SHAFT ASSY, W/SPEED RING, S51_080
4280059, SHAFT ASSY-13 T
4280060, SHAFT ASSY-15 T
8801040, SHAFT ASSY-CONTROL
517309, SHAFT ASSY-SYNC S51_080
8100142, SHAFT CHARGE PUMP (SPARES)
151G4346, SHAFT FOR OMN
151B1633, SHAFT FOR OMT
151B1825, SHAFT FOR OMT FL

141961, SHAFT H1P045-053 TAPER 25-3 SPCL K(J0F2)
11000794, SHAFT H1P069-078 23T 16/32
11011437, SHAFT H1P089-100 14T 12/24
11011436, SHAFT H1P089-100 21T 16/32
11011438, SHAFT H1P089-100 23T 16/32
140412, SHAFT H1P147-165 13T 8/16
11049118, SHAFT H1P147-165 13T 8/16
11047745, SHAFT H1P147-165 27T 16/32
140254, SHAFT H1P147-165 27T 16/32 SPECIAL
9801208, SHAFT- IDLER
518730, SHAFT IPS2 23T 16/32 SHORT (E)
682L8031, SHAFT KEY
682L9044, SHAFT KEY
9510701, SHAFT KIT-MOTOR, 15 SERIES
11056747, SHAFT LOG-BEARING CARTRIGE MOTOR ASSY
11007487, SHAFT MODUL
11007488, SHAFT MODUL
151F6606, SHAFT MODUL
151Z2039, SHAFT MODUL
151Z2199, SHAFT MODUL
151Z9053, SHAFT MODUL
151Z2005, SHAFT MODUL FOR TMT
151Z2006, SHAFT MODUL FOR TMT
151Z2020, SHAFT MODUL FOR TMT
151Z2028, SHAFT MODUL FOR TMT
151Z2029, SHAFT MODUL FOR TMT
151Z2030, SHAFT MODUL FOR TMT
151Z2061, SHAFT MODUL FOR TMT
151B0174, SHAFT MODULE
151F6607, SHAFT MODULE
151Z2055, SHAFT MODULE
151Z2220, SHAFT MODULE TMTW
9210708, SHAFT MOTOR
3103142, SHAFT MOTOR, 15 MF
3103541, SHAFT MOTOR, 15 MF
3103540, SHAFT MOTOR, 15IL, MF
151-5461, SHAFT OMP
151-5539, SHAFT OMPR ?25 EM
151F1526, SHAFT OMS SPLINES
151F1573, SHAFT OMS SPLINES
151F1691, SHAFT OMS SPLINES
151F1555, SHAFT OMS US
151B1824, SHAFT OMT
151B1726, SHAFT OMT #40 CYL
151B1437, SHAFT OMV KONISK
1720622, Shaft OPV1/023 (Splined)
1720432, SHAFT OPV1/038 13 Z./9 Z. (1720432)
1700159, SHAFT P025-030 (L) 15Z.-16/32
1700058, SHAFT P038-045 (K) 13Z.-16/32
1700205, SHAFT P038-045 (K) KEG./SCHEIB.

11011897, SHAFT PLUG
11016253, SHAFT PLUG
151Z5002, SHAFT PLUG
5009.60.0010, SHAFT PROTECTOR KAP100-15.88X25.41X1.52
500069, SHAFT PUMP
8000079, SHAFT PUMP
9260193, SHAFT PUMP
8200118, SHAFT PUMP (SPARES)
8000112, SHAFT PUMP 90P055 14Z. 12/24
3103353, SHAFT PUMP, 15 PV
3103526, SHAFT PUMP, 15 PV
3103532, SHAFT PUMP, 15 PV
3103534, SHAFT PUMP, 15 PV
3103904, SHAFT PUMP, 15 PV
3103910, SHAFT PUMP, 15 PV
3104139, SHAFT PUMP, 15 PV
3103331, SHAFT PUMP, 15 PV (SPARES)
3103533, SHAFT PUMP, 15PV
3102526, SHAFT PUMP, 15PV (SPARES)
1700072, SHAFT PUMP, 15T (K)
3103546, SHAFT PUMP, 15U, PV
3103525, SHAFT PUMP, 21T PV
8100266, SHAFT PUMP, 90PV075 23T 16/32 (C7)
148668, SHAFT SEAL
305193, SHAFT SEAL
372433, SHAFT SEAL
686626, SHAFT SEAL
1040461, SHAFT SEAL
1040570, SHAFT SEAL
1740779, SHAFT SEAL
1740973, SHAFT SEAL
633B0417, SHAFT SEAL
633B0652, SHAFT SEAL
633B0654, SHAFT SEAL
5893.01.0015, SHAFT SEAL 10x19x7 S.DIN3760
5021.01.0033, SHAFT SEAL 11X17X4 (SIMILE DIN3760)
5021.01.0011, SHAFT SEAL 12x19x5 S.DIN3760
5021.01.0022, SHAFT SEAL 12X22X5 (SIMILE DIN3760)
5021.01.0017, SHAFT SEAL 14X22X4 (SIMILE DIN3760)
5021.05.0002, SHAFT SEAL 17,46x28,58x5,8/6,3 NBR
5021.07.0002, SHAFT SEAL 17,46x28,58x5,8/6,3 VITON
5021.01.0001, SHAFT SEAL 25x42x10 S3760
5893.01.0094, SHAFT SEAL 35x50x7 S.DIN3760
5893.01.0007, SHAFT SEAL 8x16x7 S.DIN3760
11096891, SHAFT SEAL AS-HP25x42x6/6,5 DIN 3670 VIT
11096890, SHAFT SEAL AS-HP25x42x6/6,5 DIN 3670(A/P
150L4011, SHAFT SEAL ASSY
11064126, SHAFT SEAL BABSL 20x30x5/5.5 DIN3670 COR
5893.05.0023, SHAFT SEAL BABSL12x22x6/6,5 DIN 3670
5893.07.0023, SHAFT SEAL BABSL12x22x6/6,5 DIN 3670 VIT

5893.05.0002, SHAFT SEAL BABSL14x24x7/7,5 DIN 3670
5893.06.0002, SHAFT SEAL BABSL14x24x7/7,5 DIN 3670
5893.07.0002, SHAFT SEAL BABSL14x24x7/7,5 DIN 3670 VIT
5893.05.0048, SHAFT SEAL BABSL18x30x7/7,5 DIN 3670
5893.05.0050, SHAFT SEAL BABSL20x30x7/7,5 DIN 3670
5893.07.0050, SHAFT SEAL BABSL20x30x7/7,5 DIN 3670 VIT
5893.05.0061, SHAFT SEAL BABSL22x40x7/7,5 DIN 3670
5893.07.0061, SHAFT SEAL BABSL22x40x7/7,5 DIN 3670 VIT
5893.05.0060, SHAFT SEAL BABSL25x42x6/6,5 DIN 3670
5893.07.0071, SHAFT SEAL BABSL25x42x6/6,5 DIN 3670 VIT
5893.05.0079, SHAFT SEAL BABSL28x40x7/7,5 DIN 3670
11058505, SHAFT SEAL BAU1 20x30x5 DIN 3670 CORCOS
5893.36.0007, SHAFT SEAL DL.17,46x28,58x8 VITON
5893.35.0010, SHAFT SEAL DL.22x40x8,5 NBR
5893.35.0006, SHAFT SEAL DL.35x52x12 NB.
5022.50.0002, SHAFT SEAL DYN.FUDL000195 17,46x28,58x8
633B3271, SHAFT SEAL FMP
215.05.014.0K, SHAFT SEAL KIT CORCOS TFR50
221.25.017.0K, SHAFT SEAL KIT SGM3Y./07...1
221.20.024.0K, SHAFT SEAL KIT SNM2Y./01-----06 ...1.
221.20.046.0K, SHAFT SEAL KIT SNM2Y./06 ...1.
221.25.016.0K, SHAFT SEAL KIT SNM3Y./06-07
215.10.173.0K, SHAFT SEAL KIT TFU100/01 CORCOS
11077181, SHAFT SEAL KIT, H1
11092407, Shaft seal mount tool 150-9000-11
11092408, Shaft seal mount tool 150N4014-1
633B3209, SHAFT SEAL OMP(4,5 and 6) OMR(4)
633B0361, Shaft seal OMP/OMR
5021.06.0001, SHAFT SEAL SL.25x42x6 Nit.Rinf.
5893.C1.0007, SHAFT SEAL SL.A 8x16x7 DIN 3670 -CORCOS-
5893.C1.0015, SHAFT SEAL SL.A10x19x7/5,5 DIN 3670
5893.C1.0062, SHAFT SEAL SL.A22x40x7 DIN 3670 -CORCOS-
5893.01.0071, SHAFT SEAL SL.A25x42x7 DIN 3670
5893.C1.0071, SHAFT SEAL SL.A25x42x7 DIN 3670 -CORCOS-
926.0011.0.00, SHAFT SEAL SPACER
326.0136.0.00, SHAFT SEAL SPACER TAM22-90/ 01
326.0135.0.00, SHAFT SEAL SPACER TAM22-90/ 07
397.0015.0.00, SHAFT SEAL SPACER TAP60-200
326.0118.0.00, SHAFT SEAL SPACER TFP100 SC01
326.0133.0.00, SHAFT SEAL SPACER TFR50
326.0134.0.00, SHAFT SEAL SPACER TFU100
5000702, SHAFT SEAL-LIP VITON
151B0109, SHAFT TAPER 60mm WITH BEARINGS OMV
508333, SHAFT TRUNNION
3101703, Shaft Trunnion
11009878, SHAFT WITH BEARING
151B0108, SHAFT WITH BEARING
151B0140, SHAFT WITH BEARING
151B0144, SHAFT WITH BEARING
151B0145, SHAFT WITH BEARING

151B0146, SHAFT WITH BEARING
151B0147, SHAFT WITH BEARING
151B0148, SHAFT WITH BEARING
151B0149, SHAFT WITH BEARING
151B0151, SHAFT WITH BEARING
151B0160, SHAFT WITH BEARING
151B0165, SHAFT WITH BEARING
151B0167, SHAFT WITH BEARING
151B0169, SHAFT WITH BEARING
151B0181, SHAFT WITH BEARING
151B0183, SHAFT WITH BEARING
151B0185, SHAFT WITH BEARING
151F0119, SHAFT WITH BEARING
151B0101, SHAFT WITH BEARING 40MM CYL.
151B0182, SHAFT WITH BEARINGS
3103912, SHAFT, 15PT, STR .750 DIA W/3/16 x 5/8
707828, SHAFT, 20PV
8200597, SHAFT, 90MF100 13T 8/16 (F1)
11103895, SHAFT, H1P069-078 14T 12/24
11103908, SHAFT, H1P089-100 23T 16/32
11001966, SHAFT, H1P115-130 13T 8/16
11103914, SHAFT, H1P115-130 27T 16/32
11022062, SHAFT, H1P115-130 TAPER 44-3 KEYWAY
11103918, SHAFT, H1P147-165 13T 8/16
4570060, SHAFT-1.25 STR KEY, NO AUX
4570059, SHAFT-1.25 TAPER KEY, NO AUX
4400075, SHAFT-13 TOOTH
4254511, SHAFT-13 TOOTH, LV MTR
4416175, SHAFT-13T, 42P(C000C)
4570208, SHAFT-13T-16/32, NO AUX
4570409, SHAFT-13T-16/32, W/AUX
141942, SHAFT-14T 12/24, H1#045/053
4570132, SHAFT-14T-12/24 W/AUX
4740208, SHAFT-14T-12/24, NO AUX, SPECIAL
4400009, SHAFT-15 TOOTH
4254557, SHAFT-15T
141954, SHAFT-15T 16/32, H1T045/053
512377, SHAFT-90K075, 1.50 DIA TAPER
8801177, SHAFT-CHARGE PUMP
8801178, SHAFT-CHARGE PUMP
8801179, SHAFT-CHARGE PUMP
11002235, SHAFT-CHARGE PUMP H1P115-130 15T 16/32
505202, SHAFT-CHARGE-PUMP 90PV042
340646, SHAFT-CHARGE-PUMP 90PV055
11002443, SHAFT-CHARGE-PUMP 90PV180
504439, SHAFT-CHARGE-PUMP 90PV250
141239, SHAFT-CHARGE-PUMP H1P069-078 13T 16/32
141268, SHAFT-CHARGE-PUMP H1P069-078 14T 12/24
11011458, SHAFT-CHARGE-PUMP H1P089-100 11T 16/32
11011457, SHAFT-CHARGE-PUMP H1P089-100 14T 12/24

11011460, SHAFT-CHARGE-PUMP H1P089-100 9T 16/32
11002232, SHAFT-CHARGE-PUMP H1P115-130 13T 16/32
11002234, SHAFT-CHARGE-PUMP H1P115-130 13T 8/16
11002233, SHAFT-CHARGE-PUMP H1P115-130 14T 12/24
11002231, SHAFT-CHARGE-PUMP H1P115-130 9T 16/32
11064272, SHAFT-CHARGE-PUMP H1P115-165 13T 16/32
11064276, SHAFT-CHARGE-PUMP H1P115-165 14T 12/24
11064275, SHAFT-CHARGE-PUMP H1P115-165 15T 16/32
11064260, SHAFT-CHARGE-PUMP H1P115-165 9T 16/32
140975, SHAFT-CHARGE-PUMP H1P147-165 13T 16/32
140966, SHAFT-CHARGE-PUMP H1P147-165 13T 8/16
11045667, SHAFT-CHARGE-PUMP H1P147-165 13T 8/16
140965, SHAFT-CHARGE-PUMP H1P147-165 14T 12/24
11000658, SHAFT-CHARGE-PUMP H1P147-165 15T 16/32
8801210, SHAFT-CHG PMP LG DISPL 90/075-100
9240286, SHAFT-CHG PUMP
513435, SHAFT-CHG PUMP 90PV130
513441, SHAFT-CHG PUMP, 9/030
513438, SHAFT-CHG PUMP, 9/042
513436, SHAFT-CHG PUMP, 9/130
518691, SHAFT-CHG PUMP, 9/250
548875, SHAFT-CHG PUMP, 9T
9801167, SHAFT-CHG-PUMP 2/052-089
9250671, SHAFT-CHRG PUMP
9800204, SHAFT-CONTROL 2/033-334
9801250, SHAFT-IDLER
4400076, SHAFT-LC/KC MOTOR 13 TOOTH (D000A)
4254558, SHAFT-LV MTR, 15T/NONE (D00E)
4250190, SHAFT-MF 7/8 DIA STR KEY
11012276, SHAFT-MF, 1.375 0/1.5 TAPER_S90MF055
11012281, SHAFT-MF, 1.50 STRAIGHT KEY_S90MF075
11012428, SHAFT-MF, 1.75 STRAIGHT KEY_S90MF100
4460582, SHAFT-MF, 13T
4350439, SHAFT-MF, 13T (D00A)
4460285, SHAFT-MF, 15T
8000825, SHAFT-MF, 21T 16/32
11012280, SHAFT-MF, 23T 16/32_S90MF075
4460578, SHAFT-MF, STRAIGHT KEY
4250129, SHAFT-MF, TAPER
11054170, SHAFT-MF, TAPER
8200591, SHAFT-MF, 23T 16/32
670364, SHAFT-MOTOR
9260198, SHAFT-MOTOR
9270390, SHAFT-MOTOR
4460485, SHAFT-MOTOR (SPARES)
4250154, SHAFT-MOTOR 15T W/KEEL HOLD DOWN
9200420, SHAFT-MOTOR 21T_16/32 2/033
3104186, SHAFT-MOTOR, 13T
4250078, SHAFT-MOTOR, 13T, TAPPED
11050599, SHAFT-MOTOR, 13T, TAPPED

3103430, SHAFT-MOTOR, 18 SERIES
4350428, SHAFT-MOTOR, FIXED 13T
4350653, SHAFT-MOTOR, FIXED 13T W/M8 TAP
4350427, SHAFT-MOTOR, FIXED 15T
4350805, SHAFT-MOTOR, FIXED W/TAPER
4350429, SHAFT-MOTOR,.875 DIA STR KEY
3103427, SHAFT-MOTOR18 SERIES
3103428, SHAFT-MOTOR18 SERIES
3103429, SHAFT-MOTOR18 SERIES
8100604, SHAFT-MV, 14T 12/24
11014229, SHAFT-MV, 14T 12/24_S90MV055
11014252, SHAFT-MV, 14T 12/24_S90MV075
4440053, SHAFT-MV, 18T 12P HELICAL/13T AUX
11014230, SHAFT-MV, 21T 16/32_S90MV055
4460251, SHAFT-MV/MC 13T
4460166, SHAFT-MV/MC 15T
151B5319, SHAFTPLUG OMTFK
4350150, SHAFT-PT, FRONT 1.0 DIA/1.5 TAPER
4350149, SHAFT-PT, FRONT 15T 16/32 SPARES
524082, SHAFT-PUMP
3103424, SHAFT-PUMP
3103531, SHAFT-PUMP
4250001, SHAFT-PUMP
4250004, SHAFT-PUMP
4250059, SHAFT-PUMP
4250131, SHAFT-PUMP
4350398, SHAFT-PUMP
8000166, SHAFT-PUMP
8100310, SHAFT-PUMP
8100354, SHAFT-PUMP
9270741, SHAFT-PUMP
4350162, SHAFT-PUMP (SPARES)
1701451, SHAFT-PUMP 1.25 TAPER
11082274, SHAFT-PUMP 1.5 STR KEY E FRAME
11082275, SHAFT-PUMP 1.5 STR KEY E FRAME W/AUX
1700794, SHAFT-PUMP 13T
1716093, SHAFT-PUMP 13T
4570295, SHAFT-PUMP 13T-16/32, NO AUX (LONG)
4570296, SHAFT-PUMP 13T-16/32, W/AUX (LONG)
11025142, SHAFT-PUMP 14T E FRAME
11025144, SHAFT-PUMP 14T W/AUX 14T E FRAME
4461249, SHAFT-PUMP 15/11T AUX
3103833, SHAFT-PUMP 15PV
3103848, SHAFT-PUMP 15PV
1716092, SHAFT-PUMP 15T
1700596, SHAFT-PUMP 15T W/23T AUX
4570170, SHAFT-PUMP 15T-16/32 W/AUX
4570297, SHAFT-PUMP 15T-16/32, W/AUX (LONG)
1700520, SHAFT-PUMP 15T-S45
1713261, SHAFT-PUMP 2/119

1713291, SHAFT-PUMP 2/119
4280061, SHAFT-PUMP ASSY, STRAIGHT KEY, 1.0 DIA
11038239, SHAFT-PUMP H1P060/068 21T
11087475, SHAFT-PUMP OC E FRAME 14T W/AUX
11100384, SHAFT-PUMP OC E FRAME 14T W/O AUX
1716101, SHAFT-PUMP S42/41,R-TANDEM 1
1700396, SHAFT-PUMP, 0.875 STR KEY (L)
1700947, SHAFT-PUMP, 1.25 TAPER W/AUX
1716097, SHAFT-PUMP, 13T
4350397, SHAFT-PUMP, 13T
4460304, SHAFT-PUMP, 13T
1700062, SHAFT-PUMP, 13T (L)
736462, SHAFT-PUMP, 13T, 90/030
4460268, SHAFT-PUMP, 13T/9T AUX
4740012, SHAFT-PUMP, 14T-12/24. NO AUX
4740007, SHAFT-PUMP, 14T-12/24. W/AUX
3104279, SHAFT-PUMP, 15P
3103840, SHAFT-PUMP, 15PV
3103847, SHAFT-PUMP, 15PV
4350431, SHAFT-PUMP, 15T
4460099, SHAFT-PUMP, 15T INPUT
4461323, SHAFT-PUMP, 15T SPECIAL 9T AUX
1700313, SHAFT-PUMP, 15T W/AUX (L)
1716096, SHAFT-PUMP, 15T, 41/51CC
4460484, SHAFT-PUMP, 15T/11T AUX
4461289, SHAFT-PUMP, 15T/13T AUX
4460102, SHAFT-PUMP, 15T/9T AUX
4461293, SHAFT-PUMP, 15T/9T AUX (SPECIAL)
4570139, SHAFT-PUMP, 15T-16/32, NO AUX
4740145, SHAFT-PUMP, 17T-12/24 NO/AUX
4740138, SHAFT-PUMP, 17T-12/24 W/AUX
1716098, SHAFT-PUMP, 19T, 41/51CC
641936, SHAFT-PUMP, 23 SERIES
1700571, SHAFT-PUMP, 7/8IN STR KEY (L)
740910, SHAFT-PUMP, 90/030
8100264, SHAFT-PUMP, 90PV075 14T 12/24 (S1)
8100299, SHAFT-PUMP, 90PV075 21T 16/32 (C6)
1700957, SHAFT-PUMP, OC J FRAME 1.25 STR KEY
1700922, SHAFT-PUMP, OC J FRAME 13T
1700956, SHAFT-PUMP, OC J FRAME 14T 12/24
3103916, SHAFT-PUMP, TANDEM 21T
4460299, SHAFT-PUMP, TAPER
4460373, SHAFT-PUMP, TAPER/11T AUX
4461308, SHAFT-PUMP, TAPERED/9T AUX
4350399, SHAFT-PUMP, W.0.875 STR KEY
1700400, SHAFT-PUMP,17T W/AUX
11086032, SHAFT-PUMP,OC J FRAME 1.25 STR KEY
1700995, SHAFT-PUMP,OC J FRAME 1.25 STR KEY W/AUX
11085899, SHAFT-PUMP,OC J FRAME 1.25 STR KEY W/AUX
1700955, SHAFT-PUMP,OC J FRAME 14T W/AUX

3103425, SHAFT-PUMP18 SERIES
3103426, SHAFT-PUMP18 SERIES
3103432, SHAFT-PUMP18 SERIES
9230445, SHAFT-PUMP-CONE 2/089
8002L0S1, SHAFT-PV, 14T 12/24
4350468, SHAFT-PV, 15T 16/32 (E00G)
509238, SHAFT-PV, 21T 16/32 (L00C6)
1040500, SHAFT-SEAL 12.7X22.23X6.35 NBR70
9510022, SHAFT-SEAL 2/033-070-SUBASSY
9510021, SHAFT-SEAL 2/089-166-SUBASSY
1040593, SHAFT-SEAL 35X55X11
11000199, SHAFT-SEAL-CARRIER 51#250 ASSY
510482, SHAFT-SEAL-CARRIER 51C060-080 ASSY
734905, SHAFT-SEAL-CARRIER 51C080
510484, SHAFT-SEAL-CARRIER 51C110 ASSY
510485, SHAFT-SEAL-CARRIER 51C160 ASSY
515278, SHAFT-SEAL-TMM WDR40X80X7,5 75FPM595
515293, SHAFT-SEAL-TMP WDR65X97X7,5/9,5 75FPM595
768432, SHAFT-SEAL-W/SLEEVE 2/033-070 ASSY
768440, SHAFT-SEAL-W/SLEEVE 2/089-166 ASSY
4570440, SHAFT-STRAIGHT KEY
4570159, SHAFT-STRAIGHT KEY AUX 23T-24/48
4570324, SHAFT-STRAIGHT KEY AUX 23T-24/48 (LONG)
4740460, SHAFT-STRAIGHT KEY W/AUX SPLINE
4460399, SHAFT-TANDEM 1.00 STRAIGHT KEY/23T AUX
4460441, SHAFT-TANDEM, 11T AUX
4460150, SHAFT-TANDEM, 13T AUX
4350425, SHAFT-TANDEM, 15T
4460151, SHAFT-TANDEM, 15T
4350433, SHAFT-TANDEM, 15T (SPECIAL)
4460153, SHAFT-TANDEM, 19T
4460354, SHAFT-TANDEM, 19T
4460152, SHAFT-TANDEM, 9T AUX
4460155, SHAFT-TANDEM, NO AUX
4350426, SHAFT-TANDEM, REAR
4350791, SHAFT-TANDEM, TAPERED
1713069, SHAFT-TAPER
511764, SHAFT-TMM 21T_16/32
520621, SHAFT-TMP 21T_16/32
520622SK, SHAFT-TMP 21T_16/32-SAE-BB
520617, SHAFT-TMP 23T_16/32-SAE-A
11082791, SHAFT-TMP 23T_16/32-SAE-BB
520141, SHAFT-TMP-FLANGE-20CC
513091, SHAFT-TMP-FLANGE-26CC
520076, SHAFT-TMP-FLANGE-SAE-A
515281, SHAFT-TMP-FLANGE-SAE-B
515273, SHAFT-TMP-FLANGE-SAE-BB
4350393, SHAFT-VAR MOTOR, 13T
4350160, SHAFT-VARIABLE MOTOR (SPARES)
11063413, SHB-PARTS-SET TMG 61.2

11032280, SHF 90PV100 PGA
11077414, SHF H1P078R (PN)
502022, SHF-90P075, PPU M/PK+NEST SP+1.5PL(WEAB)
8801225, SHIM
9240225, SHIM
9260111, SHIM
3103007-2, SHIM
9200343-02, SHIM
9210435-01, SHIM
9230482-01, SHIM
9240225-01, SHIM
9250275-01, SHIM
9260111-01, SHIM
9270332-01, SHIM
359034, SHIM 17.25X0,5 OH.BOHRG.
377127, SHIM 42X52/0.3 DIN988
394577, SHIM 50X62/0.1 DIN988
751198, SHIM 50X62/0.2 DIN988
377176, SHIM 50X62/0.5 DIN988
520054, SHIM 56X72X2,0 DIN 988-S
513458, SHIM 63X80/2 DIN988
377267, SHIM 63X80X0,3-98
659326, SHIM KIT
9510423-0001, SHIM KIT-20 SERIES
9510423-0002, SHIM KIT-21 SERIES
9510423-0003, SHIM KIT-22 SERIES
9510423-0004, SHIM KIT-23 SERIES
9510423-0005, SHIM KIT-24 SERIES
9510423-0006, SHIM KIT-25 SERIES
9510423-0007, SHIM KIT-26 SERIES
9510423-0008, SHIM KIT-27 SERIES
9510422-0001, SHIM KIT-TRUNNION, 20 SERIES
9510422-0002, SHIM KIT-TRUNNION, 21 SERIES
9510422-0003, SHIM KIT-TRUNNION, 22 SERIES
9510422-0004, SHIM KIT-TRUNNION, 23 SERIES
9510422-0005, SHIM KIT-TRUNNION, 24 SERIES
9510422-0006, SHIM KIT-TRUNNION, 25 SERIES
9510422-0007, SHIM KIT-TRUNNION, 26 SERIES
3100069-B, SHIM REL VAL-.010
3100069-C, SHIM REL VAL-.015
3100069-D, SHIM REL VAL-.020
3100069-E, SHIM REL VAL-.075
287433, SHIM RING
294272, SHIM RING
294280, SHIM RING
333153, SHIM RING
376822, SHIM RING
376947, SHIM RING
376954, SHIM RING
377119, SHIM RING

377168, SHIM RING
377382, SHIM RING
377390, SHIM RING
377408, SHIM RING
377416, SHIM RING
395459, SHIM RING
505417, SHIM RING
522771, SHIM RING
528273, SHIM RING
668079, SHIM RING
674770, SHIM RING
674796, SHIM RING
674812, SHIM RING
674804, SHIM RING 6X 12X0,5 -988 ST
505367, SHIM SLIPPER GUIDE RETAINER
505368, SHIM SLIPPER GUIDE RETAINER
359067, SHIM, 28,70X0,5 OH.BOHRG.
515264, SHIM, DIN988 56x70x0,1 ST
373563, SHIM-90X110X1.0-988 ST (SPARES)
4800135-0020, SHIM-CHG.RELIEF
4800135-0050, SHIM-CHG.RELIEF
9510445, SHIM-KIT-RELIEF-VALVE
9802196-0001, SHIM-RELIEF, .002
9802196-0004, SHIM-RELIEF, .032
505369, SHIM-SLIPPER GUIDE RETAINER, 9/130
121.21.036.00, SHM2GL/019L206SBL1E5E5NNNA/NNNNN
121.21.033.00, SHM2GL/022L206SBL1E5E5NNNA/NNNNN
121.21.024.00, SHM2IN/025RN06GAV6E6E6NNNN/VGLNN
121.21.028.00, SHM2NL/019B206SIL6E5E5NNNN/NNNNN
121.21.025.00, SHM2NL/021B206SBL6E6E6NNNN/NNNVN
121.21.029.00, SHM2NL/022B206SIL6E5E5NNNN/NNNNN
11080659, SHM2NL/022B2Q2ACLZMEMENNNN/NNNNN
121.21.002.00, SHM2NL/022BN02AAL1B7B7NNNN/NNNNN
121.21.018.00, SHM2NL/025B206SBL6E6E6NNNN/NNNNN
11039230, SHM2NL/025B206SBL6E6E6NNNN/NNNVN
121.21.039.00, SHM2NL/025B2Q2ACL1MGMGNNNN/NNNNN
11050557, SHM2NL/025B2Q2ACLZMGMGNNNN/NNNNN
121.21.030.00, SHM2NN/019B206SIM6E5E5NNNN/NNNNN
121.21.037.00, SHM2NN/019B2Q2ACM1MGMGNNNN/NNNNN
11069827, SHM2NN/022B202ACM1E5C3PRNN/NNNNN
121.21.008.00, SHM2NN/022B202ACM1E6E6NNNN/NNNNN
121.21.031.00, SHM2NN/022B206SIM6E5E5NNNN/NNNNN
121.21.014.00, SHM2NN/025B206SGM6E6E6NNNN/NNNNN
121.21.003.00, SHM2NN/025B2Q2ACM1MGMGNNNN/NNNNN
121.21.009.00, SHM2NN/025BN06GAM6E6E6NNNN/NNNNN
121.21.023.00, SHM2NN/025BN06SFM6E6E6NNNN/NNNNN
11053148, SHOCK- AND SUCTION VALVE
150F0249, SHOCK- AND SUCTION VALVE
162U1002, Short lever, 10 to 90% Vs output range, 5 k?, spring return to center
162U1003, Short lever, 25 to 75% Vs output range, 5 k?, spring return to center

11069963, SHP2IN/022LN04AAI1BBB5NNNN/VMXNN
111.21.013.00, SHP2NN/019LN01BAP1C7C3NNNN/NNNNN
111.21.031.00, SHP2NN/019LN01DAP1B7B5NNNN/NNNNN
111.21.016.00, SHP2NN/019LN04AAP1B7B5NNNN/NNNNN
111.21.011.00, SHP2NN/019RN01BAP1C7C3NNNN/NNNNN
111.21.007.00, SHP2NN/019RN01BAP1F5F4NNNN/NNNNN
111.21.003.00, SHP2NN/019RN02AAP1B7B5NNNN/NNNNN
111.21.022.00, SHP2NN/019RN02AAP1B7B5NNNN/NNNNN
11045069, SHP2NN/019RN04AAP1B7B5NNNN/NNNNN
111.21.029.00, SHP2NN/019RN06SFP1B7B5YYNN/NNNNN
111.21.017.00, SHP2NN/022LN01BAP1C7C3NNNN/NNNNN
83022751, SHP2NN/022LN01DAP1B7B5NNNN/NNNNN
111.21.004.00, SHP2NN/022LN02AAP1B7B5NNNN/NNNNN
83015639, SHP2NN/022LN02DBP1BBB5F1NN/NNNNN
83020714, SHP2NN/022LN04AAP1B7B5NNBN/NNNNN
111.21.030.00, SHP2NN/022LN04AAP1B7B5NNNN/NNNNN
11046890, SHP2NN/022LN04AAP1BBB5EUNN/NNNNN
11036103, SHP2NN/022LN04DBP1B7B5NNNN/NNNNN
111.21.027.00, SHP2NN/022LNB1DGP1C7C3NNBN/NNNNN
111.21.021.00, SHP2NN/022RN01BAP1C7C3NNNN/NNNNN
111.21.008.00, SHP2NN/022RN01BAP1F5F4NNNN/NNNNN
111.21.020.00, SHP2NN/022RN01DAP1C7C3NNNN/NNNNN
111.21.023.00, SHP2NN/022RN02AAP1B7B5NNNN/NNNNN
11048548, SHP2NN/022RN04AAP1BBB5EUNN/NNNNN
111.21.024.00, SHP2NN/022RN04DBP1B7B5EUBN/NNNNN
111.21.028.00, SHP2NN/022RN05DBP1B7B5NNNN/NNNNN
111.21.019.00, SHP2NN/022RN06SFP1MEMENNDN/NNNNN
111.21.001.00, SHP2NN/025LN01BAP1C8C7NNNN/NNNNN
111.21.014.00, SHP2NN/025LN01BAP1F6F5NNNN/NNNNN
111.21.012.00, SHP2NN/025LN01DAP1C8C7NNNN/NNNNN
83020816, SHP2NN/025LN04AAP1B7B5NNBN/NNNNN
111.21.002.00, SHP2NN/025RN01BAP1C8C7NNNN/NNNNN
111.21.009.00, SHP2NN/025RN01BAP1F6F5NNNN/NNNNN
111.21.010.00, SHP2NN/025RN01DAP1C8C7NNNN/NNNNN
111.21.015.00, SHP2NN/025RN01DBP1C8C7NNNN/NNNNN
121.21.035.00, SHU2GN/022LN02AAP1B7B7NNNN/NNNAN
11084368, SHU2GN/022LN02AAP1B7B7NNNN/NNNNN
121.21.038.00, SHU2GN/022LN02AAP1B7BBNNNN/NNNAN
121.21.038.00-0S, SHU2GN/022LN02AAP1B7BBNNNN/NNNAN
K06039, SHUTTLE PLATE ASSEMBLY
505420, SHUTTLE VALVE
155L6618, SHUTTLE VALVE
11087986, SHW2NN/022RN02AGP3B7B5NNNN/NNNNN
509936, SICHER.RING 76,20X2,36
511202, SICHER.RING JV22 SEEGER
8510097, SIDE COVER REPLACEMENT KIT, 055
8510098, SIDE COVER REPLACEMENT KIT, 075
8510204, SIDE COVER REPLACEMENT KIT, 100
8510132, SIDE COVER, REPLACEMENT KIT 100
10103788, SILICONE RUBBER CAP, YELLOW, TME

162B1075, SILLICON KEY-PAD
83021846, SKC2NN/011LN06SBC6NNNNNNNNN/NNNNN
111.22.055.0C, SKC2NN/011RN06SBC6NNNNNNNNN/NNNNN
83013869, SKC2NN/019RN06SBC6NNNNNNNNN/NNNNN
11120837, SKC2NN/025RNA6SBC6NNNNNNNNN/NNNNN
151B1741, Skive OMT
83017376, SKM1NN/010BN01BAM1C2C2NNNB/NNNNN
121.12.035.00, SKM1NN/010BN02BBM1C2C2NNNB/NNNNN
121.12.108.00, SKM1NN/010BN06GAM6E4E4NNNB/NNNCN
121.12.058.00, SKM1NN/010BN06GAM6E4E4NNNB/NNNNN
11031341, SKM1NN/010BNC1DCM2F3F3NNNB/NNNNN
121.12.059.00, SKM1NN/012BN06GAM6E4E4NNNN/NNNNN
121.12.020.00, SKM1NN/012BN06SAM6E4E4NNNN/NNNNN
121.12.063.00, SKM1NN/2,6BN01BAM1C2C2NNNN/NNNNN
83020040, SKM1NN/2,6BN02BBM1C2C2NNNN/NNNNN
83020404, SKM1NN/2,6BN02BBM3B2B2NNNN/NNNNN
121.12.073.00, SKM1NN/2,6BN02FAM1C2C2NNNN/NNNNN
121.12.111.00, SKM1NN/2,6BN06GAM3F3F3NNNN/NNNNN
121.12.052.00, SKM1NN/2,6BN06GAM6E4E4NNNN/NNNNN
11047530, SKM1NN/2,6BN06GAMHH5H5NNNN/NNNNN
121.12.013.00, SKM1NN/2,6BN06SAM6E4E4NNNN/NNNNN
121.12.064.00, SKM1NN/3,2BN01BAM1C2C2NNNN/NNNNN
121.12.105.00, SKM1NN/3,2BN01BAMHH5H5NNNN/NNNNN
121.12.030.00, SKM1NN/3,2BN02BBM1C2C2NNNN/NNNNN
121.12.074.00, SKM1NN/3,2BN02FAM1C2C2NNNN/NNNNN
11060451, SKM1NN/3,2BN06GAM6E4E4NNNB/NNNNN
121.12.053.00, SKM1NN/3,2BN06GAM6E4E4NNNN/NNNNN
121.12.014.00, SKM1NN/3,2BN06SAM6E4E4NNNN/NNNNN
121.12.065.00, SKM1NN/3,8BN01BAM1C2C2NNNN/NNNNN
11058659, SKM1NN/3,8BN01BAM1E3E3NNNN/NNNNN
121.12.112.00, SKM1NN/3,8BN01BAMHH5H5NNNB/NNNNN
121.12.075.00, SKM1NN/3,8BN02FAM1C2C2NNNN/NNNNN
121.12.054.00, SKM1NN/3,8BN06GAM6E4E4NNNN/NNNNN
121.12.015.00, SKM1NN/3,8BN06SAM6E4E4NNNN/NNNNN
121.12.066.00, SKM1NN/4,3BN01BAM1C2C2NNNN/NNNNN
121.12.032.00, SKM1NN/4,3BN02BBM1C2C2NNNN/NNNNN
121.12.041.00, SKM1NN/4,3BN02DBM1C2C2NNNN/NNNNN
83012933, SKM1NN/4,3BN02FAM1C2C2NNNB/NNNNN
121.12.076.00, SKM1NN/4,3BN02FAM1C2C2NNNN/NNNNN
121.12.091.00, SKM1NN/4,3BN02FAM1F3F3NNNN/NNNNN
83019018, SKM1NN/4,3BN06GAM3F3F3NNNB/NNNNN
121.12.055.00, SKM1NN/4,3BN06GAM6E4E4NNNN/NNNNN
121.12.005.00, SKM1NN/4,3BN06SAM6E4E4NNNB/NNNVN
121.12.016.00, SKM1NN/4,3BN06SAM6E4E4NNNN/NNNNN
121.12.023.00, SKM1NN/4,3BN06SAM6E4E4NNNN/NNNNN
121.12.067.00, SKM1NN/6,0BN01BAM1C2C2NNNN/NNNNN
83018224, SKM1NN/6,0BN01BAM1D5D5NNNN/NNNNN
83015812, SKM1NN/6,0BN01BAM3F4F4NNNN/NNNNN
83017859, SKM1NN/6,0BN02BBM1C2C2NNNN/NNNNN
121.12.077.00, SKM1NN/6,0BN02FAM1C2C2NNNN/NNNNN

11053227, SKM1NN/6,0BN06BBM2F4F4NNNN/NNNNN
121.12.056.00, SKM1NN/6,0BN06GAM6E4E4NNNN/NNNNN
121.12.017.00, SKM1NN/6,0BN06SAM6E4E4NNNN/NNNNN
121.12.049.00, SKM1NN/7,8BN01BAM1C2C2NNNN/NNNNN
121.12.011.00, SKM1NN/7,8BN01BAM2F3F3NNNN/NNNNN
121.12.061.00, SKM1NN/7,8BN01BAM3C2C2NNNN/NNNNN
121.12.034.00, SKM1NN/7,8BN02BBM1C2C2NNNN/NNNNN
121.12.070.00, SKM1NN/7,8BN02BBM3F4F4NNNN/NNNNN
121.12.043.00, SKM1NN/7,8BN02DBM1C2C2NNNN/NNNNN
83012934, SKM1NN/7,8BN02FAM1C2C2NNNB/NNNNN
121.12.078.00, SKM1NN/7,8BN02FAM1C2C2NNNN/NNNNN
121.12.057.00, SKM1NN/7,8BN06GAM6E4E4NNNN/NNNNN
121.12.018.00, SKM1NN/7,8BN06SAM6E4E4NNNN/NNNNN
83008257, SKM1WL/012B606SGW6E4E4NNNB/VGNNN
111.12.046.0C, SKP1IN/3,2RN06GAI1E4E3NNNN/VJXNN
111.12.120.0A, SKP1NN/010LN01BAP1C3C3DFNB/NNNNN
111.12.112.0A, SKP1NN/010LN01BAP1C3C3NNNB/NNNNN
111.12.021.0A, SKP1NN/010LN06GAP1E4E3NNNB/NNNNN
111.12.010.0A, SKP1NN/010LN06SAP1E4E3NNNB/NNNNN
111.12.112.0C, SKP1NN/010RN01BAP1C3C3NNNB/NNNNN
111.12.021.0C, SKP1NN/010RN06GAP1E4E3NNNB/NNNNN
111.12.010.0C, SKP1NN/010RN06SAP1E4E3NNNB/NNNNN
111.12.022.0A, SKP1NN/012LN06GAP1E4E3NNNN/NNNNN
111.12.011.0A, SKP1NN/012LN06SAP1E4E3NNNN/NNNNN
111.12.022.0C, SKP1NN/012RN06GAP1E4E3NNNN/NNNNN
111.12.011.0C, SKP1NN/012RN06SAP1E4E3NNNN/NNNNN
83020992, SKP1NN/1,2LN02BBP1H5H4NNHB/NNNNN
111.12.023.0A, SKP1NN/1,2LN02FAP1C2C2NNNN/NNNNN
111.12.012.0A, SKP1NN/1,2LN06GAP1E4E3NNNN/NNNNN
111.12.001.0A, SKP1NN/1,2LN06SAP1E4E3NNNN/NNNNN
111.12.075.0A, SKP1NN/1,2LN06SAP1F3F2NNNN/NNNNN
111.12.076.0C, SKP1NN/1,2RN02FAP1F3F3NNNN/NNNNN
111.12.099.0C, SKP1NN/1,2RN06CEP1E4E3NNNN/NNNNN
111.12.012.0C, SKP1NN/1,2RN06GAP1E4E3NNNN/NNNNN
83015798, SKP1NN/1,2RN06SAP1B2B1NNNN/NNNNN
111.12.001.0C, SKP1NN/1,2RN06SAP1E4E3NNNN/NNNNN
111.12.024.0A, SKP1NN/1,7LN02FAP1C2C2NNNN/NNNNN
111.12.013.0A, SKP1NN/1,7LN06GAP1E4E3NNNN/NNNNN
111.12.002.0A, SKP1NN/1,7LN06SAP1E4E3NNNN/NNNNN
111.12.100.0C, SKP1NN/1,7RN06CEP1E4E3NNNN/NNNNN
111.12.013.0C, SKP1NN/1,7RN06GAP1E4E3NNNN/NNNNN
111.12.073.0C, SKP1NN/1,7RN06SAP1E4E3NNNB/NNNNN
111.12.002.0C, SKP1NN/1,7RN06SAP1E4E3NNNN/NNNNN
11058863, SKP1NN/1,7RN06SAP1F3F3NNNN/NNNNN
111.12.025.0A, SKP1NN/2,2LN02FAP1C2C2NNNN/NNNNN
111.12.078.0A, SKP1NN/2,2LN02FAP1F3F3NNNN/NNNNN
111.12.101.0A, SKP1NN/2,2LN06CEP1E4E3NNNN/NNNNN
111.12.014.0A, SKP1NN/2,2LN06GAP1E4E3NNNN/NNNNN
111.12.003.0A, SKP1NN/2,2LN06SAP1E4E3NNNN/NNNNN
11029616, SKP1NN/2,2RN02BBP1C2C2NNNN/NNNNN

111.12.025.0C, SKP1NN/2,2RN02FAP1C2C2NNNN/NNNNN
111.12.101.0C, SKP1NN/2,2RN06CEP1E4E3NNNN/NNNNN
111.12.014.0C, SKP1NN/2,2RN06GAP1E4E3NNNN/NNNNN
111.12.003.0C, SKP1NN/2,2RN06SAP1E4E3NNNN/NNNNN
111.12.026.0A, SKP1NN/2,6LN02FAP1C2C2NNNN/NNNNN
111.12.074.0A, SKP1NN/2,6LN02FAP1F3F3NNNN/NNNNN
111.12.015.0A, SKP1NN/2,6LN06GAP1E4E3NNNN/NNNNN
111.12.004.0A, SKP1NN/2,6LN06SAP1E4E3NNNN/NNNNN
83015660, SKP1NN/2,6RN02BBP1C2C2NNNN/NNNNN
111.12.026.0C, SKP1NN/2,6RN02FAP1C2C2NNNN/NNNNN
111.12.074.0C, SKP1NN/2,6RN02FAP1F3F3NNNN/NNNNN
111.12.015.0C, SKP1NN/2,6RN06GAP1E4E3NNNN/NNNNN
111.12.004.0C, SKP1NN/2,6RN06SAP1E4E3NNNN/NNNNN
83016601, SKP1NN/3,2LN01BAP1C2C2NNNN/NNNNN
111.12.027.0A, SKP1NN/3,2LN02FAP1C2C2NNNN/NNNNN
111.12.080.0A, SKP1NN/3,2LN02FAP1F3F3NNNN/NNNNN
111.12.115.0A, SKP1NN/3,2LN02FAP1F4F4NNNN/NNNNN
111.12.016.0A, SKP1NN/3,2LN06GAP1E4E3NNNN/NNNNN
83019992, SKP1NN/3,2LN06SAP1C2C2NNHN/NNNNN
111.12.005.0A, SKP1NN/3,2LN06SAP1E4E3NNNN/NNNNN
111.12.027.0C, SKP1NN/3,2RN02FAP1C2C2NNNN/NNNNN
111.12.103.0C, SKP1NN/3,2RN06CEP1E4E3NNNN/NNNNN
111.12.016.0C, SKP1NN/3,2RN06GAP1E4E3NNNN/NNNNN
111.12.005.0C, SKP1NN/3,2RN06SAP1E4E3NNNN/NNNNN
111.12.028.0A, SKP1NN/3,8LN02FAP1C2C2NNNN/NNNNN
111.12.017.0A, SKP1NN/3,8LN06GAP1E4E3NNNN/NNNNN
111.12.006.0A, SKP1NN/3,8LN06SAP1E4E3NNNN/NNNNN
11038940, SKP1NN/3,8RN02BBP1F3F3NNNN/NNNNN
111.12.028.0C, SKP1NN/3,8RN02FAP1C2C2NNNN/NNNNN
111.12.104.0C, SKP1NN/3,8RN06CEP1E4E3NNNN/NNNNN
111.12.017.0C, SKP1NN/3,8RN06GAP1E4E3NNNN/NNNNN
111.12.006.0C, SKP1NN/3,8RN06SAP1E4E3NNNN/NNNNN
111.12.116.0C, SKP1NN/3,8RNV6SAP1E4E3NNNN/NNNNN
111.12.098.0A, SKP1NN/4,3LN02DDP1C2C2NNNN/NNNNN
111.12.098.0A-OL, SKP1NN/4,3LN02DDP1C2C2NNNN/NNNNN
111.12.029.0A, SKP1NN/4,3LN02FAP1C2C2NNNN/NNNNN
11061113, SKP1NN/4,3LN02FAP1F3F3NNNN/NNNNN
111.12.105.0A, SKP1NN/4,3LN06CEP1E4E3NNNN/NNNNN
111.12.018.0A, SKP1NN/4,3LN06GAP1E4E3NNNN/NNNNN
111.12.007.0A, SKP1NN/4,3LN06SAP1E4E3NNNN/NNNNN
83018408, SKP1NN/4,3RN01BAP1E4E3NNNN/NNNNN
111.12.093.0C, SKP1NN/4,3RN02DBP1C2C2NNNN/NNNNN
111.12.098.0C, SKP1NN/4,3RN02DDP1C2C2NNNN/NNNNN
111.12.029.0C, SKP1NN/4,3RN02FAP1C2C2NNNN/NNNNN
111.12.105.0C, SKP1NN/4,3RN06CEP1E4E3NNNN/NNNNN
111.12.018.0C, SKP1NN/4,3RN06GAP1E4E3NNNN/NNNNN
111.12.007.0C, SKP1NN/4,3RN06SAP1E4E3NNNN/NNNNN
83021334, SKP1NN/4,3RN06SAP1F4F3NNNN/NNNNN
111.12.110.0C, SKP1NN/5,5RN06CEP1E4E3NNNN/NNNNN
111.12.117.0C, SKP1NN/5,5RN06TBP1E4E3NNNN/NNNNN

111.12.113.0A, SKP1NN/6,0L601BAP1C3C3NNNN/NNNNN
111.12.056.0A, SKP1NN/6,0LN02BBP1C2C2NNNN/NNNNN
111.12.030.0A, SKP1NN/6,0LN02FAP1C2C2NNNN/NNNNN
111.12.072.0A, SKP1NN/6,0LN02FAP1F4F4NNNN/NNNNN
11052616, SKP1NN/6,0LN06GAP1E4E3NNHN/NNNNN
111.12.019.0A, SKP1NN/6,0LN06GAP1E4E3NNNN/NNNNN
83021045, SKP1NN/6,0LN06SAP1C2C2NNHN/NNNNN
111.12.008.0A, SKP1NN/6,0LN06SAP1E4E3NNNN/NNNNN
111.12.118.0A, SKP1NN/6,0LNB1BAP1C3C3NNIB/NNNNN
111.12.056.0C, SKP1NN/6,0RN02BBP1C2C2NNNN/NNNNN
111.12.030.0C, SKP1NN/6,0RN02FAP1C2C2NNNN/NNNNN
111.12.019.0C, SKP1NN/6,0RN06GAP1E4E3NNNN/NNNNN
111.12.008.0C, SKP1NN/6,0RN06SAP1E4E3NNNN/NNNNN
111.12.071.0A, SKP1NN/7,8L6B1BGP2C3C3DFIA/NNNNN
111.12.057.0A, SKP1NN/7,8LN02BBP1C2C2NNNN/NNNNN
111.12.031.0A, SKP1NN/7,8LN02FAP1C2C2NNNN/NNNNN
111.12.042.0A, SKP1NN/7,8LN02FAP1E4E3NNNN/NNNNN
111.12.020.0A, SKP1NN/7,8LN06GAP1E4E3NNNN/NNNNN
111.12.119.0A, SKP1NN/7,8LN06SAP1C3C3NNNB/NNNNN
111.12.111.0A, SKP1NN/7,8LN06SAP1E4E3NNNN/NNNAN
111.12.009.0A, SKP1NN/7,8LN06SAP1E4E3NNNN/NNNNN
111.12.114.0A, SKP1NN/7,8LNB1BAP1C3C3NNIB/NNNNN
111.12.057.0C, SKP1NN/7,8RN02BBP1C2C2NNNN/NNNNN
111.12.031.0C, SKP1NN/7,8RN02FAP1C2C2NNNN/NNNNN
111.12.107.0C, SKP1NN/7,8RN06CEP1E4E3NNNN/NNNNN
111.12.020.0C, SKP1NN/7,8RN06GAP1E4E3NNNN/NNNNN
111.12.009.0C, SKP1NN/7,8RN06SAP1E4E3NNNN/NNNNN
11091269, SKP2/14 D SC46 DUX4.
11117317, SKP2/17 D SC36 +++2.
11117311, SKP2/17 D SC36 DUY2.
11079831, SKP2/17 D SC46 DUX4.
11091585, SKP2/17 S SC05 +++_H
111.22.034.0C, SKP2EN/022RN06SBE6E8E5NNNN/VCQCN
83023322, SKP2IN/011LN06SBI1E6E5NNNN/VNFNN
83022422, SKP2IN/019RN06SBI1E6E5NNNN/VNPNN
11056394, SKP2IN/022RN06SBI1E6E5NNNN/VIXNN
83017799, SKP2IN/025LN06SBI1E6E5NNNN/VFSNN
111.22.060.0A, SKP2NN/011LN06SBP1B7B5NNGN/NNNNN
111.22.014.0A, SKP2NN/011LN06SBP1B7B5YYNN/NNNNN
111.22.024.0A, SKP2NN/011LN06SBP1E6E5NNNN/NNNNN
111.22.056.0A, SKP2NN/011LN06SBP1E8E4NNNN/NNNNN
83007736, SKP2NN/011LN06SBP1E8E6NNNN/NNNNN
111.22.031.0A, SKP2NN/011LNA6SBP1B7B5YYNN/NNNNN
111.22.060.0C, SKP2NN/011RN06SBP1B7B5NNGN/NNNNN
111.22.014.0C, SKP2NN/011RN06SBP1B7B5YYNN/NNNNN
111.22.056.0C, SKP2NN/011RN06SBP1E8E4NNNN/NNNNN
111.22.061.0C, SKP2NN/011RN06SBP1E8E5NNNN/NNNNN
83017406, SKP2NN/011RN06SBP1F5F4NNNN/NNNNN
111.22.015.0A, SKP2NN/014LN06SBP1B7B5YYNN/NNNNN
111.22.005.0A, SKP2NN/014LN06SGP1B7B5YYNN/NNNNN

111.22.039.0C, SKP2NN/014RN01BAP1C7C3NNNN/NNNNN
83021974, SKP2NN/014RN06SBP1B7B5YYNN/NNNNN
83017310, SKP2NN/014RN06SBP1C7C3NNNN/NNNNN
111.22.025.0C, SKP2NN/014RN06SBP1E6E5NNNN/NNNNN
11045110, SKP2NN/014RN06SBP1E8E5NNNN/NNNNN
111.22.005.0C, SKP2NN/014RN06SGP1B7B5YYNN/NNNNN
11040599, SKP2NN/017LN06SBP1B7B5YYNN/NNNNN
83007690, SKP2NN/017LN06SBP1E8E6NNNN/NNNNN
83009448, SKP2NN/017RN06SBP1B7B5YYNN/NNNNN
111.22.026.0C, SKP2NN/017RN06SBP1E6E5NNNN/NNNNN
83010687, SKP2NN/017RN06SBP1F5F4NNNN/NNNNN
83013886, SKP2NN/019LN06SBP1C7C3NNNN/NNNNN
111.22.027.0A, SKP2NN/019LN06SBP1E6E5NNNN/NNNNN
111.22.065.0A, SKP2NN/019LN06SBP1E6E5NNNN/NNNNN
111.22.020.0A, SKP2NN/019LNH6SBP1MGMENNDN/NNNNN
111.22.067.0A, SKP2NN/019LNH6SGP1MGMENNDN/NNNNN
111.22.017.0C, SKP2NN/019RN06SBP1B7B5YYNN/NNNNN
11045171, SKP2NN/019RN06SBP1C7C3NNNN/NNNNN
11063476, SKP2NN/019RN06SBP1E6E5NNNN/NNNNN
111.22.020.0C, SKP2NN/019RNH6SBP1MGMENNDN/NNNNN
111.22.067.0C, SKP2NN/019RNH6SGP1MGMENNDN/NNNNN
111.22.028.0A, SKP2NN/022LN06SBP1E6E5NNNN/NNNNN
111.22.064.0A, SKP2NN/022LN06SBP1E6E5NNNN/NNNNN
111.22.069.0A, SKP2NN/022LNA6SBP1C7C3NNNN/NNNNN
111.22.058.0C, SKP2NN/022RN06SBP1B7B5ZZNN/NNNNN
111.22.062.0C, SKP2NN/022RN06SBP1E6E5NNNN/NNNIN
111.22.028.0C, SKP2NN/022RN06SBP1E6E5NNNN/NNNNN
111.22.057.0C, SKP2NN/022RN06SBP1E8E6NNNN/NNNNN
83011666, SKP2NN/022RN06SBP1F5F4NNNN/NNNNN
111.22.010.0C, SKP2NN/022RN06SBP1MEMENNDA/NNNNN
111.22.068.0C, SKP2NN/022RN06SGP1E6E5NNNN/NNNNN
111.22.019.0A, SKP2NN/025LN06SBP1B7B5YYNN/NNNNN
83011243, SKP2NN/025LN06SBP1E6E5NNNN/NNNNN
111.22.063.0A, SKP2NN/025LN06SBP1F6F5NNNN/NNNNN
111.22.059.0A, SKP2NN/025LNA6SBP1B7B5YYNN/NNNNN
111.22.043.0C, SKP2NN/025RN01BAP1C8C7NNNN/NNNNN
111.22.019.0C, SKP2NN/025RN06SBP1B7B5YYNN/NNNNN
111.22.029.0C, SKP2NN/025RN06SBP1E6E5NNNN/NNNNN
11033897, SKP2NN/025RN06SBP1E8E5NNNN/NNNAN
11100084, SKP2NN/025RN06SBP1F6F5NNNN/NNNNN
111.22.063.0C, SKP2NN/025RN06SBP1F6F5NNNN/NNNNN
11031731, SKP2NN/025RNA6SBP1B7B5YYNN/NNNNN
111.22.030.0C, SKP2NN/025RNH6SBP1MGMENNNA/NNNNN
11079954, SKP2NN/4,0LN06SBP1B6B5YYNN/NNNNN
111.22.032.0A, SKP2NN/6,0LNA6SBP1B6B5YYNN/NNNNN
111.22.032.0C, SKP2NN/6,0RNA6SBP1B6B5YYNN/NNNNN
111.22.013.0A, SKP2NN/8,0LN06SBP1B7B5YYNN/NNNNN
111.22.066.0A, SKP2NN/8,0LN06SBP1C3C3NNNN/NNNNN
111.22.023.0A, SKP2NN/8,0LN06SBP1E6E5NNNN/NNNNN
11048332, SKP2NN/8,0RN06SBP1C3C3NNNN/NNNNN

111.22.023.0C, SKP2NN/8,ORN06SBP1E6E5NNNN/NNNNN
111.22.054.0C, SKP2NN/8,ORNA6SBP1B7B5YYNN/NNNNN
681X0038, SKR.M10 X 180 CS
681X0098, SKR.M8 X 60 CS
11090459, SKR1NN/3,8RN01BAM1D5D5NNNN/NNNNN
11030849, SKR1NN/3,8RN01BAM1F3F3NNNN/NNNNN
11100736, SKR1NN/6,ORN01BAM1F3F3NNNN/NNNNN
121.12.110.0A, SKU1IN/4,3LN01BAI1H5H5NNNB/VKVNN
11039209, SKU1NC/2,6LN02BBCHNNNNNNNN/NNNNN
121.12.093.0A, SKU1NF/7,8LN02FA08C1NNSTNN/NNNNN
11064065, SKU1NN/2,6LN02FAP1C2C2NNNN/NNNNN
11099184, SKU1NN/2,6RN01BAP1H2H4NNNN/NNNNN
11038240, SKU1NN/2,6RN02BBP1H2H4NNNN/NNNNN
11053652, SKU1NN/2,6RN06GAP1E3E4NNHN/NNNCN
121.12.083.0A, SKU1NN/3,2LN02FAP1C2C2NNNN/NNNNN
11053631, SKU1NN/3,2RN06GAP1E3E4NNHN/NNNCN
121.12.098.0C, SKU1NN/3,2RN06SAP1E3E4NNNN/NNNNN
121.12.084.0A, SKU1NN/3,8LN02FAP1C2C2NNNN/NNNNN
11086841, SKU1NN/3,8LN06GAP1F3F3NNNN/NNNNN
121.12.084.0C, SKU1NN/3,8RN02FAP1C2C2NNNN/NNNNN
121.12.085.0A, SKU1NN/4,3LN02FAP1C2C2NNNN/NNNNN
121.12.090.0A, SKU1NN/4,3LN06GAP1E3E4NNHN/NNNCN
11109101, SKU1NN/4,3RN02BBP1H2H4NNNB/NNNNN
121.12.090.0C, SKU1NN/4,3RN06GAP1E3E4NNHN/NNNCN
121.12.086.0C, SKU1NN/6,ORN02FAP1C2C2NNNN/NNNNN
211.12.004.0A, SKW1NN/4,3LN06BUNNE4E3NNNN/NNNNN
211.12.011.0C, SKW1NN/4,3RN06CINNE4E3NNNN/NNNNN
211.22.043.0A, SKW2NN/011LN06SSNNB7B5YYNN/NNNNN
211.22.037.0A, SKW2NN/011LN06SSNNC3C3NNNN/NNNNN
211.22.037.0C, SKW2NN/011RN06SSNNC3C3NNNN/NNNNN
83010120, SKW2NN/014LN06SSNNB7B5YYNN/NNNNN
211.22.045.0A, SKW2NN/014LNA6SSNNB7B5YYNN/NNNNN
11029866, SKW2NN/014RN06SSNNB7B5YYNN/NNNNN
83015339, SKW2NN/014RN06SSNNE6E5NNNN/NNNNN
11060709, SKW2NN/014RNA6SSNNB7B5YYNN/NNNNN
83008558, SKW2NN/017LN06SSNNB7B5YYNN/NNNNN
211.22.034.0A, SKW2NN/017LN06SSNNE6E5NNNN/NNNNN
11038825, SKW2NN/017LN06SSNNE6E5NNNN/NNNVN
211.22.044.0A, SKW2NN/017LNA6SSNNB7B5YYNN/NNNNN
83008420, SKW2NN/017LNA6SSNNE6E5NNNN/NNNNN
211.22.038.0A, SKW2NN/017LNA6SSNNH8H7NNNN/NNNNN
11039775, SKW2NN/017RN06SSNNB7B5YYNN/NNNNN
83009566, SKW2NN/017RN06SSNNE6E5NNNN/NNNNN
83007658, SKW2NN/017RN06SSNNF5F4NNNN/NNNNN
83010600, SKW2NN/017RNA6SSNNE6E5NNNN/NNNNN
11087110, SKW2NN/019LN06SSNNB7B5YYNN/NNNNN
83018699, SKW2NN/019LN06SSNNC7C3NNNN/NNNNN
211.22.031.0C, SKW2NN/019RN01BXNNC7C3NNNN/NNNNN
83022127, SKW2NN/019RN06SSNNB7B5YYNN/NNNNN
211.22.033.0A, SKW2NN/022LN06SSNNB7B5YYNN/NNNNN

211.22.040.0A, SKW2NN/022LNA6SSNNB7B5YYNN/NNNNN
11060711, SKW2NN/022RN06SSNNB7B5YYNN/NNNNN
11034041, SKW2NN/022RN06SSNNE6E5NNNN/NNNNN
83012128, SKW2NN/022RN06SSNNF5F4NNNN/NNNNN
211.22.040.0C, SKW2NN/022RNA6SSNNB7B5YYNN/NNNNN
211.22.039.0A, SKW2NN/025LN06SSNNB7B5YYNN/NNNNN
211.22.042.0A, SKW2NN/025LNA6SSNNB7B5YYNN/NNNNN
11069722, SKW2NN/025RN01BXNNB7B5DBNN/NNNNN
11035105, SKW2NN/025RN01BXNNC8C7NNNN/NNNNN
211.22.042.0C, SKW2NN/025RNA6SSNNB7B5YYNN/NNNNN
211.22.035.0C, SKW2NN/028RN01BQNNC8C7NNNN/NNNNN
11040819, SKW2NN/8,ORN06SSNNB7B5YYNN/NNNNN
211.22.036.0C, SKW2NN/8,ORN06SSNNE6E4NNNN/NNNNN
345413, SLEEVE
500041, SLEEVE
550210, SLEEVE
575704, SLEEVE
9801035, SLEEVE
150F0461, SLEEVE
150G1355, SLEEVE
9801930, SLEEVE SPRING
K22303, SLEEVE AND SNAP RING ASSEMBLY
150F0455, SLEEVE AND SPOOL SET
150G5207, SLEEVE AND SPOOL SETS OSP
4461342, SLEEVE ASSY - .031 ORIFICE
4461343, SLEEVE ASSY - .036 ORIFICE
4461341, SLEEVE ASSY - .046 ORIFICE
4461358, SLEEVE ASSY - .062 ORIFICE
4461340, SLEEVE ASSY - .250 ORIFICE
510411, SLEEVE ASSY 51V#
510414, SLEEVE ASSY 51V#
500821, SLEEVE ASSY-4 WAY VALVE
510410, SLEEVE ASSY-51V
4510160, SLEEVE ASSY-CONTROL VALVE, .031
4510158, SLEEVE ASSY-CONTROL VALVE, .036
4510159, SLEEVE ASSY-CONTROL VALVE, .046
4510157, SLEEVE ASSY-CONTROL VALVE, .250
510415, SLEEVE ASSY-S51V
510416, SLEEVE ASSY-S51V
511088, SLEEVE ASSY-SERVO, 26/27
11023345, SLEEVE DEUTSCH 6P (1011-086-0605 BLACK)
9510350, SLEEVE KIT-SERVO, 22/23
9510208, SLEEVE KIT-SERVO, 24/25
9510331, SLEEVE KIT-SERVO, 26/27
9510708, SLEEVE KIT-SERVO, 26/27
9260408, SLEEVE SERVO
1721958-01, SLEEVE SERVO(1.71)
500025, SLEEVE,SPRING
587063, SLEEVE,SPRING
587071, SLEEVE,SPRING

4460917, SLEEVE-CONTROL VALVE, .036
4460914, SLEEVE-CONTROL VALVE, .046
4460916, SLEEVE-CONTROL VALVE, .250
665026, SLEEVE-CYLINDER-BLOCK 90#075
10100581, SLEEVE-DEUTSCH 12P(1011-053-1205 BLACK)
11000737, SLEEVE-DEUTSCH 3P (1011-056-0305 GREY)
11000736, SLEEVE-DEUTSCH 3P (1011-084-0305 BLACK)
9260386, SLEEVE-SERVO
510174, SLEEVE-SERVO ASSY
608000, SLEEVE-SERVO ASSY
623371, SLEEVE-SERVO ASSY
11028750, Slew module for HIAB
1741009, SLIDE BEARING
1741491, SLIDE BEARING
151B1030, SLIDE BEARING
151B1032, SLIDE BEARING
505365, SLIPPER GUIDE RETAINER SHIM
505366, SLIPPER GUIDE RETAINER SHIM
681726, SLIPPER GUIDE RETAINER SHIM
4570387, SLIPPER RETAINER
4510167, SLIPPER RETAINER AND GUIDE KIT
334391, SLIPPER RETAINER GUIDE
334409, SLIPPER RETAINER GUIDE
722090, SLIPPER RETAINER GUIDE
733469, SLIPPER RETAINER GUIDE
4510354, SLIPPER RETAINER KIT, FRAME G 74CC
710426, SLIPPER-21 SERIES
710442, SLIPPER-23 SERIES
710459, SLIPPER-24 SERIES
716704, SLIPPER-27 SERIES
710434, SLIPPER-FORGED-2/070
4740161, SLIPPER-RETAINER
150-0422, SMALL STEEL BEARING RACE
993L3081, smc POS Blue plastic bag 100x200mm
162B5297, SML. PCB
162B5288, SML.PCB DJ MAIN
5725.19.1237, SNAP RING 12 UNI 7435
5725.20.1645, SNAP RING 16 UNI 7437
5725.20.1952, SNAP RING 19 UNI 7437
5725.20.2259, SNAP RING 22 UNI 7437
5725.20.2464, SNAP RING 24 UNI 7437
5725.22.2975, SNAP RING 29 DIN 472
5725.20.3075, SNAP RING 30 UNI 7437
5725.20.3675, SNAP RING 40 UNI 7437
5725.20.3795, SNAP RING 42 UNI 7437
682L4173, SNAPRING
111.10.164.00, SNC1NN/1,7RN01BAC1NNNNNNNNN/NNNNN
111.10.168.00, SNC1NN/2,6RN01BAC1NNNNNNNNN/NNNNN
83008313, SNC1NN/4,3RN01BAC1NNNNNNNNN/NNNNN
111.20.A49.00, SNC2/19 D SC06 LNE_.

11045905, SNC2/19 S SC06 LNE_
11048537, SNC2NN/011LN06SAC6NNNNNNNNN/NNNVN
111.20.931.00, SNC2NN/011RN01BAC1NNNNNNNNN/NNNNN
111.20.959.00, SNC2NN/011RN01BBC2NNNNNNNNN/NNNNN
111.20.A56.00, SNC2NN/011RN06SAC1NNNNNNNNN/NNNNN
83008497, SNC2NN/014LN01BAC1NNNNNNNNN/NNNNN
83012900, SNC2NN/014LN06SAC6NNNNNNNNN/NNNVN
111.20.B38.00, SNC2NN/014RN01BAC1NNNNNNNNN/NNNNN
111.20.807.00, SNC2NN/014RN03DBC1NNNNNNNNN/NNNNN
111.20.950.00, SNC2NN/014RN06SAC1NNNNNNNNN/NNNNN
111.20.808.00, SNC2NN/014RN9ADBC1NNNNNNNNN/NNNNN
11035864, SNC2NN/017LN04AAC1NNNNNNNNN/NNNNN
111.20.C29.00, SNC2NN/017LN06SAC1NNNNNNNNN/NNNNN
111.20.B63.00, SNC2NN/017LNA6SAC6NNNNNNNNN/NNNNN
111.20.932.00, SNC2NN/017RN01BAC1NNNNNNNNN/NNNNN
111.20.A72.00, SNC2NN/017RN04DBC1NNNNNNNNN/NNNNN
111.20.A42.00, SNC2NN/017RN06SAC1NNNNNNNNN/NNNNN
111.20.933.00, SNC2NN/019RN01BAC1NNNNNNNNN/NNNNN
111.20.A29.00, SNC2NN/019RN04DBC1NNNNNNNNN/NNNNN
83018889, SNC2NN/019RN06SAC6NNNNNNNNN/NNNNN
11055861, SNC2NN/022LN06SAC1NNNNNNNNN/NNNNN
111.20.A62.00, SNC2NN/022RN01BAC1NNNNNNNNN/NNNNN
111.20.967.00, SNC2NN/022RN06SAC1NNNNNNNNN/NNNNN
111.20.A55.00, SNC2NN/022RNA6SAC1NNNNNNNNN/NNNNN
111.20.B04.00, SNC2NN/4,0LN06SAC6NNNNNNNNN/NNNNN
11045246, SNC2NN/4,0RN06SAC6NNNNNNNNN/NNNNN
111.20.B48.00, SNC2NN/6,0RN01BAC1NNNNNNNNN/NNNNN
111.20.C09.00, SNC2NN/6,0RN06SAC1NNNNNNNNN/NNNNN
111.20.A23.00, SNC2NN/8,0RN01BBC6NNNNNNNNN/NNNNN
11079465, SNC2NN/8,0RN04DBC1NNNNNNNNN/NNNNN
111.20.A73.00, SNC2NN/8,0RN06SAC6NNNNNNNNN/NNNNN
111.20.B74.00, SND2NN/011RN03DBD1F5NNNNNNN/NNNNN
111.20.952.00, SND2NN/011RN03DBD6E6NNNNNNN/NNNNN
111.20.B75.00, SND2NN/011RN9ADB1F5NNNNNNN/NNNNN
111.20.968.00, SND2NN/011RN9JDBD6E6NNNNNNN/NNNNN
111.20.732.00, SND2NN/014RN03DBD1F5NNNNNNN/NNNNN
11106433, SNI2/14 D SC1C MNW_G
111.20.B53.00, SNI2/8 D SC06 MKO_G
11110404, SNM2.L/ 11 . SC06 +++4F
11110465, SNM2.L/ 13 . SC06 +++4F
11108231, SNM2.L/ 6 . CO05 +++4M
11103516, SNM2/ 4 D CO01 +++1.
11058451, SNM2/10 . CI01 LFU1E
11063659, SNM2/14 . CO94 RYH_
121.20.672.00, SNM2/17 . CI91 MMJ1.
11069955, SNM2/25 . CE06 +++1.
121.20.682.00, SNM2DN/011BN01BAD2C3C3NNNNN/NNNNN
11102579, SNM2DN/011BN02DBD2B5B5NNNNN/NNNNN
121.20.561.00, SNM2DN/011BN03CAD3B5B5NNNNN/NNNNN
121.20.792.00, SNM2DN/011BN06GAD2E5E5NNNNN/NNNNN

121.20.683.00, SNM2DN/014BN01BAD2C7C7NNNN/NNNN
121.20.570.00, SNM2DN/014BN03CAD3B5B5NNNN/NNNN
121.20.157.00, SNM2DN/014BN06SAD2E5E5NNNN/NNNN
121.20.571.00, SNM2DN/017BN03CAD3B5B5NNNN/NNNN
121.20.163.00, SNM2DN/022BN02AAD2B7B7NNNN/NNNN
121.20.655.00, SNM2DN/6,0BN03CAD3B5B5NNNN/NNNN
121.20.569.00, SNM2DN/8,0BN03CAD3B5B5NNNN/NNNN
121.20.319.00, SNM2FL/011LN06SAJ6E5E5NNNC/YWANN
121.20.446.00, SNM2FL/014LN01BAJ1E5E5NNNC/YWANN
121.20.320.00, SNM2FL/014LN06SAJ6E5E5NNNC/YWANN
121.20.445.00, SNM2FL/014RN01BAJ1E5E5NNNC/YWANN
121.20.321.00, SNM2FL/017LN06SAJ6E5E5NNNC/YWANN
121.20.317.00, SNM2FL/6,0LN06SAJ6E5E5NNNC/YWANN
121.20.318.00, SNM2FL/8,0LN06SAJ6E5E5NNNC/YWANN
121.20.473.00, SNM2FN/012RN06SAF6E5E5NNNC/YWANN
121.20.197.00, SNM2FN/6,0LN06SAF1F4F4NNNA/YWANN
121.20.198.00, SNM2FN/6,0RN06SAF1F4F4NNNA/YWANN
121.20.271.00, SNM2FN/8,0LN06SAF1F4F4NNNA/YWANN
121.20.272.00, SNM2FN/8,0RN06SAF1F4F4NNNA/YWANN
11060721, SNM2G./10 D CI01 LFU1E
121.20.654.00, SNM2GC/9,5R402AAG1NNNNNNNN/NNNN
83021517, SNM2GL/011LN01BAL1C3C3NNNN/NNNN
121.20.752.00, SNM2GL/011LN01BALSC3C3NNNN/NNNN
121.20.731.00, SNM2GL/025RN03DBL3C8C8NNNN/NNNN
121.20.732.00, SNM2GL/025RN9ADBL3C8C8NNNN/NNNN
83019310, SNM2GL/6,0LN01FAL1F4F4NNNN/NNNN
83019311, SNM2GL/6,0RN01FAL1F4F4NNNN/NNNN
83022424, SNM2GL/8,0RN01FAL1F4F4NNNN/NNNN
121.20.634.00, SNM2GN/011LN03DBM4E5E5NNNN/NNNN
121.20.456.00, SNM2GN/011LN06GBM6E5E5NNNN/NNNN
83021972, SNM2GN/011LN06SAM6E5E5NNNN/NNNN
121.20.635.00, SNM2GN/011LN9JDBM4E5E5NNNN/NNNN
121.20.447.00, SNM2GN/011RN01BAM1C3C3NNNN/NNNN
11082892, SNM2GN/011RN01BAM1F4F4NNNN/NNNN
121.20.528.00, SNM2GN/011RN01BAM6D7D7NNNN/NNNN
121.20.436.00, SNM2GN/011RN01BAM6E5E6NNNN/NNNN
83014803, SNM2GN/011RN01FAM1F4F4NNNN/NNNN
121.20.766.00, SNM2GN/011RN03DBM4E5E5NNNN/NNNN
83014000, SNM2GN/011RN06GAM6E4E4NNNN/NNNN
11050099, SNM2GN/011RN06GAM6E5E5NNNN/NNNN
83021839, SNM2GN/011RN06GBM6E4E4NNNN/NNNN
121.20.767.00, SNM2GN/011RN9JDBM4E5E5NNNN/NNNN
11082848, SNM2GN/011RN9LBAM1C3C3NNNN/NNNN
121.20.793.00, SNM2GN/014LN01BAM1C7C7NNNN/NNNN
83017713, SNM2GN/014LN01BAM6E5E5NNNN/NNNN
121.20.726.00, SNM2GN/014LN06GBM6E5E5NNNN/NNNN
83019543, SNM2GN/014RN01BAM1C7C7NNNN/NNNN
121.20.457.00, SNM2GN/014RN06GBM6E5E5NNNN/NNNN
83017755, SNM2GN/014RN94DBM3B5B5NNNN/NNNN
11113646, SNM2GN/014RN9LBAM1C7C7NNNN/NNNN

121.20.363.00, SNM2GN/017LN02AAM1B5B5NNNN/NNNNN
83009123, SNM2GN/017RN01B1M1C7C7NNNA/NNNNN
11046265, SNM2GN/017RN01B1M1C7C7NNNN/NNNNN
11049938, SNM2GN/017RN01BAM1C7C7NNNA/NNNNN
121.20.362.00, SNM2GN/017RN01BAM1C7C7NNNN/NNNNN
121.20.529.00, SNM2GN/017RN01BAM6D7D7NNNN/NNNNN
11065046, SNM2GN/017RN01FAM1C7C7NNDN/NNNNN
121.20.749.00, SNM2GN/017RN01FAM1C7C7NNNN/NNNNN
121.20.366.00, SNM2GN/017RN06BAM6E5E5NNNN/NNNNN
11046902, SNM2GN/017RN9HDBM4E5E5NNNN/NNNVN
121.20.450.00, SNM2GN/019LN01BAM1C7C7NNNN/NNNNN
121.20.632.00, SNM2GN/019LN06BAM6E6E6NNNN/NNNNN
11065617, SNM2GN/019LN06GAM6E6E6NNNN/NNNNN
121.20.718.00, SNM2GN/019LN06GBM6E6E6NNNN/NNNNN
121.20.449.00, SNM2GN/019RN01BAM1C7C7NNNN/NNNNN
121.20.492.00, SNM2GN/019RN01BAM6E5E6NNNN/NNNNN
121.20.779.00, SNM2GN/019RN01FAM1C7C7NNNN/NNNNN
121.20.453.00, SNM2GN/019RN06BAM6E6E6NNNN/NNNNN
121.20.443.00, SNM2GN/019RN06GBM6E6E6NNNN/NNNNN
83022286, SNM2GN/019RN06GBM6E6E6NNXN/NNNNN
121.20.451.00, SNM2GN/022LN01BAM1C7C7NNNN/NNNNN
11046228, SNM2GN/022LN06SAM6E5E5NNNA/NNNAN
11035590, SNM2GN/022RN06GAM6E6E6NNNN/NNNNN
11106670, SNM2GN/022RN94DBM3B5B5NNNN/NNNNN
83010986, SNM2GN/022RN94DBM3B7B7NNNN/NNNNN
83016739, SNM2GN/025LN06SAM6E6E6NNNA/NNNAN
83020251, SNM2GN/6,0LN06GAM6E5E5NNNN/NNNNN
83014791, SNM2GN/6,0RN01FAM1F4F4NNNN/NNNNN
121.20.574.00, SNM2GN/6,0RN06GAM6E5E5NNNN/NNNNN
11120716, SNM2GN/8,0L406SAM6E5E5NNNA/NNNVN
121.20.503.00, SNM2GN/8,0LN01BAM1C3C3NNNN/NNNNN
121.20.540.00, SNM2GN/8,0LN02AAM1B5B5NNNN/NNNNN
11066662, SNM2GN/8,0LN06GAM6E5E5NNNN/NNNNN
83017054, SNM2GN/8,0LN06SAM6E4E4NNDN/NNNNN
11118216, SNM2GN/8,0R406SAM6E5E5NNNN/NNNNN
121.20.791.00, SNM2GN/8,0RN01BAM1C3C3NNNN/NNNNN
83015969, SNM2GN/8,0RN02AAM1B5B5NNNN/NNNNN
83009632, SNM2GN/8,0RN02DBM1B5B5NNNN/NNNNN
121.20.642.00, SNM2GN/8,0RN06AAM6E5E5NNNN/NNNNN
121.20.619.00, SNM2GN/8,0RN06GAM6E5E5NNNN/NNNNN
83022287, SNM2GN/8,0RN06GBM6E5E5NNXN/NNNNN
83017319, SNM2GN/8,0RN06SAM6E4E4NNDN/NNNNN
11114718, SNM2GN/9,0L406SAM6E5E5NNNA/NNNVN
121.20.775.00, SNM2IL/014LN03CAV2B5B5NNNA/VJSNN
121.20.770.00, SNM2IL/014RN03CAV2B5B5NNNA/VJSNN
121.20.236.00, SNM2IN/014LN03CAV1B5B5NNNA/VJSNN
121.20.237.00, SNM2IN/014RN03CAV1B5B5NNNA/VJSNN
121.20.616.00, SNM2IN/017LN02DBV1B5B5NNNA/VJJNN
83011514, SNM2IN/017RN01FAV1F5F5NNNA/VGENN
121.20.265.00, SNM2IN/017RN01FAV1F5F5NNNN/VGENN

121.20.615.00, SNM2IN/017RN02DBV1B5B5NNNA/VJJNN
121.20.720.00, SNM2IN/017RN03DBV1B5B5NNNN/VJSNN
83019916, SNM2IN/017RN06SAV1E6E6NNNN/VAQNN
121.20.721.00, SNM2IN/017RN9FDBV1B5B5NNNN/VJSNN
121.20.500.00, SNM2IN/022LN02DBV1B7B7NNNA/VGUNN
121.20.501.00, SNM2IN/022RN02DBV1B7B7NNNA/VGUNN
121.20.679.00, SNM2IN/025LN06SAV6E6E6NNDN/VGKNN
121.20.696.00, SNM2IN/6,0LN03DBV6E5E5NNNN/VLTNN
121.20.697.00, SNM2IN/6,0LN9JDBV6E5E5NNNN/VLTNN
121.20.234.00, SNM2IN/8,0LN03CAV1B5B5NNNA/VOPNN
121.20.235.00, SNM2IN/8,0RN03CAV1B5B5NNNA/VOPNN
11032854, SNM2J./22 D CO06 +++1.
11052631, SNM2JL/019RN9HDBV7E6E6NNNA/VKMCN
11040742, SNM2JL/022RN9HDBV7E6E6NNNA/VGOCN
11055631, SNM2JN/011LN01BAV1C3C3NNNN/VOWNN
83019662, SNM2JN/011LN01BAV1C7C7NNNN/VLZNN
121.20.737.00, SNM2JN/011LN01BBV1C3C3NNNN/VOWNN
83008162, SNM2JN/011LN02AAV1E5E5NNNN/VMWNN
11056349, SNM2JN/011LN06GAV6E5E5NNNN/VOXNN
11087782, SNM2JN/011LN06GBV6E5E5NNYN/VOXVN
83020264, SNM2JN/011RN01BAV1C7C7NNNN/VKXNN
83011523, SNM2JN/011RN02AAV1B5B5NNNN/VKXNN
83015386, SNM2JN/011RN02FAV1B5B5NNYN/VLWNN
83008520, SNM2JN/014LN01BAV1C7C7NNNN/VLZNN
121.20.671.00, SNM2JN/014LN01BBV1C7C7NNNN/VMWNN
83008163, SNM2JN/014LN02AAV1E5E5NNNN/VMWNN
83020265, SNM2JN/014RN01BAV1C7C7NNNN/VKXNN
121.20.624.00, SNM2JN/014RN06BAV6E5E5NNNN/VGVNN
121.20.670.00, SNM2JN/014RN06GAV6E5E5NNNN/VLKNN
83022766, SNM2JN/014RN06GBV6E5E5NNNN/VNXWN
121.20.763.00, SNM2JN/017LN01BAV1C7C7NNNN/VIXNN
83020266, SNM2JN/017RN01BAV1C7C7NNNN/VKXNN
83016652, SNM2JN/019LN01BBV1C7C7NNNN/VGQNN
83020267, SNM2JN/019RN01BAV1C7C7NNNN/VKXNN
121.20.643.00, SNM2JN/019RN06GAV6E6E6NNNN/VKLNN
121.20.558.00, SNM2JN/022RN03DBV6E6E6NNNA/VGOCN
121.20.722.00, SNM2JN/022RN03DBV6E6E6NNNA/VGPZN
121.20.559.00, SNM2JN/022RN03DBV6E6E6NNNA/VGQCN
11039332, SNM2JN/022RN9HDBV6E6E6NNNA/VGMCN
121.20.552.00, SNM2JN/022RN9HDBV6E6E6NNNA/VGOCN
121.20.723.00, SNM2JN/022RN9HDBV6E6E6NNNA/VGPCN
121.20.557.00, SNM2JN/022RN9HDBV6E6E6NNNA/VGQCN
121.20.725.00, SNM2JN/022RN9HDBV6E6E6NNNA/VGRCN
11039380, SNM2JN/022RN9HDBV6MEMENNNNA/VGOCN
83013868, SNM2JN/022RN9JDBV1B7B7NNNN/VGWNN
83012246, SNM2JN/025LN01BBV1C7C7NNNN/VGQNN
11056350, SNM2JN/8,0LN06GAV6E5E5NNNN/VOXNN
11044762, SNM2JN/8,0RN01BAV1C3C3NNNN/VKUNN
121.20.546.00, SNM2JN/8,0RN02AAV1B5B5NNNN/VMLNN
83008269, SNM2JN/8,0RN06GAV6E5E5NNNN/VNLNN

11039419, SNM2JN/9,5RN01FAV1C3C3NNNN/VIWNN
121.20.482.00, SNM2NC/011B401BAG1NNNNNNNA/NNNNN
121.20.692.00, SNM2NC/011B401DAG6NNNNNNNA/NNNCN
121.20.768.00, SNM2NC/014B401BAG6NNNNNNNA/NNNCN
121.20.504.00, SNM2NC/014B403DBG6NNNNNNNN/NNNNN
121.20.605.00, SNM2NC/014B406GAG6NNNNNNNN/NNNNN
11038867, SNM2NC/014B406GAG6NNNNNNNN/NNNVN
121.20.641.00, SNM2NC/014B406GBG6NNNNNNNN/NNNIN
121.20.693.00, SNM2NC/019B401BAG6NNNNNNNA/NNNCN
11066693, SNM2NC/019B401BAG6NNNNNNNN/NNNNN
83011648, SNM2NC/019B402AAG1NNNNNNNN/NNNNN
83008585, SNM2NC/019B406GBG6NNNNNNNN/NNNVN
121.20.508.00, SNM2NC/025B403DBG6NNNNNNNN/NNNNN
121.20.684.00, SNM2NC/025B406GBG6NNNNNNNN/NNNIN
11038963, SNM2NC/025B406GBG6NNNNNNNN/NNNVN
83013392, SNM2NC/8,0B49JDBG6NNNNNNNN/NNNNN
121.20.677.00, SNM2NC/8,0BN06GAG6NNNNNNNA/NNNIN
121.20.220.00, SNM2NC/8,0BN06GAG6NNNNNNNA/NNNNN
121.20.474.00, SNM2NC/9,5B406GAG6NNNNNNDN/NNNNN
11109239, SNM2NL/011B402AAL1B5B5NNNN/NNNNN
11111787, SNM2NL/011B406GALSE5E5NNNN/NNNNN
83011515, SNM2NL/011BN01B1L1C3C3NNNA/NNNNN
121.20.585.00, SNM2NL/011BN01B1L1C3C3NNNN/NNNNN
121.20.353.00, SNM2NL/011BN01BAL1C3C3NNNN/NNNNN
121.20.675.00, SNM2NL/011BN01BBL1B5B5NNNN/NNNNN
83017648, SNM2NL/011BN01FALDC3C3NNNN/NNNNN
121.20.491.00, SNM2NL/011BN02AAL1B5B5NNNN/NNNNN
121.20.698.00, SNM2NL/011BN03CALTB5B5NNNN/NNNNN
121.20.422.00, SNM2NL/011BN05AALFB5B5NNNN/NNNNN
121.20.595.00, SNM2NL/011BN06BAL1F4F4NNNN/NNNAN
11083158, SNM2NL/011BN06BAL6E4E5PRYA/NNNAN
121.20.459.00, SNM2NL/011BN06GALSE5E5NNNA/NNNNN
121.20.140.00, SNM2NL/011BN06GALSE5E5NNNN/NNNNN
121.20.128.00, SNM2NL/011BN06SAL7E5E5NNNN/NNNNN
121.20.545.00, SNM2NL/011BN06SAL8E5E5NNNN/NNNNN
121.20.137.00, SNM2NL/011BN06SEL7E5E5NNNN/NNNNN
121.20.783.00, SNM2NL/012BN01BBL1F4F4NNNN/NNNNN
121.20.204.00, SNM2NL/012BN06SAL7E5E5NNNN/NNNNN
11038082, SNM2NL/012BN06SAL7E5E5NNNN/NNNVN
121.20.772.00, SNM2NL/012BN91DBL3F4F4NNNA/NNNNN
121.20.426.00, SNM2NL/014B206ECL1B5B5YYNA/NNNNN
11047428, SNM2NL/014BN01BAL1C7C7NNNN/NNNNN
83016939, SNM2NL/014BN01FALDC7C7NNNN/NNNNN
121.20.680.00, SNM2NL/014BN03CAL3B5B5NNNN/NNNNN
11080607, SNM2NL/014BN06BAL6E4E5PRYA/NNNAN
83018746, SNM2NL/014BN06GBL6E5E5NNNN/NNNNN
121.20.322.00, SNM2NL/014BN06SAL6E5E5NNNN/NNNNN
121.20.573.00, SNM2NL/017B206ECL1B5B5YYNA/NNNNN
83011516, SNM2NL/017BN01B1L1C7C7NNNA/NNNNN
121.20.586.00, SNM2NL/017BN01B1L1C7C7NNNN/NNNNN

11032079, SNM2NL/017BN01BAL1B5B5NNNN/NNNNN
83008990, SNM2NL/017BN01BBL1B5B5NNNN/NNNNN
11046290, SNM2NL/017BN01BBL1C7C7NNNN/NNNNN
83009507, SNM2NL/017BN02AAL1B5B5NNNA/NNNNN
83023031, SNM2NL/017BN02DBL1B5B5NNNN/NNNNN
121.20.691.00, SNM2NL/017BN03CALTB5B5NNNN/NNNNN
83013585, SNM2NL/017BN06BAL6E4E5PLYA/NNNAN
11059020, SNM2NL/017BN06BAL6E4E5PRYA/NNNAN
83019594, SNM2NL/017BN06BAL6E6E6NNNA/NNNNN
11043973, SNM2NL/017BN06BALXE4E5PRNN/NNNAN
11056936, SNM2NL/017BN06BALXE4E5PRYA/NNNAN
83017509, SNM2NL/017BN06GAL1F5F5NNYA/NNNNN
121.20.103.00, SNM2NL/019B206ECL1B5B5YYNA/NNNNN
83011517, SNM2NL/019BN01B1L1C7C7NNNA/NNNNN
121.20.587.00, SNM2NL/019BN01B1L1C7C7NNNN/NNNNN
83015056, SNM2NL/019BN01BAL1B7B7NNNA/NNNNN
83015057, SNM2NL/019BN01BALZB7B7NNNA/NNNNN
121.20.379.00, SNM2NL/019BN02AAL1B7B7NNNA/NNNNN
121.20.358.00, SNM2NL/019BN02AAL1B7B7NNNN/NNNNN
121.20.181.00, SNM2NL/019BN02AAL1C7C7NNNN/NNNNN
83023032, SNM2NL/019BN02DBL1B5B5NNNN/NNNNN
121.20.583.00, SNM2NL/019BN03CAL3B7B7NNNN/NNNNN
121.20.633.00, SNM2NL/019BN03CALTB7B7NNNN/NNNNN
121.20.488.00, SNM2NL/019BN06BAL6E6E6NNNA/NNNNN
121.20.187.00, SNM2NL/019BN06CFL6E5E5NNNN/NNNNN
121.20.674.00, SNM2NL/019BN92CAL3B7B7NNNN/NNNNN
121.20.673.00, SNM2NL/019BN92CALTB7B7NNNN/NNNNN
83017214, SNM2NL/019BN9FDBL3B7B7NNNN/NNNNN
121.20.748.00, SNM2NL/022BN01BBL1C7C7NNNN/NNNNN
121.20.592.00, SNM2NL/022BN06BAL6E4E5PRNN/NNNAN
11068061, SNM2NL/022BN06BAL6E4E5PRYA/NNNAN
11033039, SNM2NL/022BN06BAL6E5E5NNNN/NNNAN
11112172, SNM2NL/022BN9FDBLFB7B7NNNN/NNNNN
83022937, SNM2NL/022BN9FDBLTB5B5NNNA/NNNWN
83011520, SNM2NL/025BN01B1L1C8C8NNNA/NNNNN
121.20.588.00, SNM2NL/025BN01B1L1C8C8NNNN/NNNNN
83016478, SNM2NL/025BN01BBL1C7C7NNNN/NNNNN
121.20.729.00, SNM2NL/025BN03DBL3C8C8NNNN/NNNNN
121.20.730.00, SNM2NL/025BN9ADBL3C8C8NNNN/NNNNN
121.20.589.00, SNM2NL/6,0BN01B1L1C3C3NNNN/NNNNN
121.20.525.00, SNM2NL/6,0BN04AALDB5B5NNDA/NNNAN
121.20.442.00, SNM2NL/6,0BN06GBLSE5E5NNNN/NNNCN
121.20.686.00, SNM2NL/6,0BN06SALHE5E5NNNN/NNNNN
121.20.648.00, SNM2NL/6,0BN06SALSE5E5NNNN/NNNNN
11109623, SNM2NL/8,0B402FAL1B5B5NNNN/NNNNN
121.20.514.00, SNM2NL/8,0B406GAL8E5E5NNDN/NNNNN
11038664, SNM2NL/8,0B406GAL8E5E5NNDN/NNNVN
11106210, SNM2NL/8,0B406GALSE5E5NNNN/NNNNN
11106105, SNM2NL/8,0B406GALSE5E5NNNN/NNNNP
11106202, SNM2NL/8,0B406GALSE5E5NNNN/NNNNP

11111797, SNM2NL/8,0B406GBLSE5E5NNNN/NNNNN
121.20.584.00, SNM2NL/8,0BN01B1L1C3C3NNNN/NNNNN
121.20.327.00, SNM2NL/8,0BN01BAL1C3C3NNNN/NNNNN
83018061, SNM2NL/8,0BN01FALCC3C3NNNN/NNNNN
121.20.289.00, SNM2NL/8,0BN02DBL1B5B5NNNN/NNNNN
121.20.743.00, SNM2NL/8,0BN02FAL1B5B5NNNN/NNNNN
121.20.699.00, SNM2NL/8,0BN03CALTB5B5NNNN/NNNNN
83009143, SNM2NL/8,0BN04AAL1B5B5NNNN/NNNNN
83014739, SNM2NL/8,0BN06GAL6E5E5NNNN/NNNNN
121.20.401.00, SNM2NL/8,0BN06GBLSE5E5NNNN/NNNCN
121.20.762.00, SNM2NL/8,0BN06SAL8B6E5PRNN/NNNNN
121.20.493.00, SNM2NL/8,0BN06SAL8E5E5NNNN/NNNNN
121.20.435.00, SNM2NL/9,5BN02AALSF4F5PLDA/NNNAN
11080748, SNM2NL/9,5BN02AALSF4F5PLDA/NNNNN
11110083, SNM2NN/011B406SAM6E5E5NNNN/NNNNN
121.20.705.00, SNM2NN/011BN01BAM1B5B5NNNN/NNNNN
121.20.711.00, SNM2NN/011BN01BAM1C3C3NNNA/NNNNN
121.20.173.00, SNM2NN/011BN01BAM1C3C3NNNN/NNNNN
11042793, SNM2NN/011BN01BAM1C3C3NNNN/NNNWN
121.20.741.00, SNM2NN/011BN01BAM1F4F4NNNN/NNNNN
121.20.658.00, SNM2NN/011BN01BBM1C3C3NNNN/NNNNN
121.20.703.00, SNM2NN/011BN01DAM6E5E5NNNN/NNNCN
83019937, SNM2NN/011BN01FAM1B5B5NNNN/NNNNN
121.20.246.00, SNM2NN/011BN01FAM1C3C3NNNN/NNNNN
11033463, SNM2NN/011BN01FAM1F4F4NNNN/NNNNN
121.20.694.00, SNM2NN/011BN01FAM6E5E5NNNN/NNNNN
121.20.058.00, SNM2NN/011BN02AAM1B5B5NNNN/NNNNN
83009912, SNM2NN/011BN02AAM6E5E5NNNN/NNNNN
121.20.136.00, SNM2NN/011BN02DBM1B5B5NNNN/NNNNN
121.20.713.00, SNM2NN/011BN03CAM3B5B5NNNA/NNNNN
121.20.040.00, SNM2NN/011BN03CAM3B5B5NNNN/NNNNN
83012408, SNM2NN/011BN03CAM3C3C3NNNN/NNNNN
121.20.479.00, SNM2NN/011BN03CAM3F4F4NNNN/NNNNN
121.20.149.00, SNM2NN/011BN03CAM4E5E5NNNN/NNNNN
11048643, SNM2NN/011BN03DBM3B5B5NNNN/NNNNN
121.20.354.00, SNM2NN/011BN03DBM3C3C3NNNN/NNNNN
121.20.188.00, SNM2NN/011BN03DBM3F4F4NNNN/NNNNN
121.20.771.00, SNM2NN/011BN03DBM4E5E5NNNN/NNNNN
121.20.305.00, SNM2NN/011BN03TCM4E5E5NNNN/NNNNN
121.20.336.00, SNM2NN/011BN06AAM1F4F4NNNN/NNNNN
121.20.676.00, SNM2NN/011BN06BAM6E5E5NNNN/NNNNN
83015640, SNM2NN/011BN06BAM6E5E5NNNN/NNNVN
83021661, SNM2NN/011BN06BAM6E5E5NNYN/NNNVN
121.20.788.00, SNM2NN/011BN06DBM1C3C3NNNN/NNNNN
121.20.441.00, SNM2NN/011BN06GAM1F4F4NNNN/NNNNN
83007402, SNM2NN/011BN06GAM6C3C3NNNN/NNNNN
83007790, SNM2NN/011BN06GAM6E5E5NNDN/NNNNN
83017364, SNM2NN/011BN06GAM6E5E5NNNA/NNNNN
121.20.043.00, SNM2NN/011BN06GAM6E5E5NNNN/NNNNN
11037774, SNM2NN/011BN06GAM6E5E5NNNN/NNNVN

121.20.685.00, SNM2NN/011BN06GBM6E4E4NNNN/NNNVN
121.20.383.00, SNM2NN/011BN06GBM6E5C3PRNN/NNNNN
121.20.341.00, SNM2NN/011BN06GBM6E5E5NNNN/NNNNN
83020303, SNM2NN/011BN06GBM6E5E5NXXN/NNNNN
121.20.485.00, SNM2NN/011BN06SAM6E5E5NNNA/NNNIN
121.20.052.00, SNM2NN/011BN06SAM6E5E5NNNN/NNNNN
83016433, SNM2NN/011BN06SAM6E5E5NNNN/NNNZN
121.20.714.00, SNM2NN/011BN92CAM3B5B5NNNA/NNNNN
121.20.661.00, SNM2NN/011BN92CAM3B5B5NNNN/NNNNN
11058750, SNM2NN/011BN94DBM3B5B5NNNN/NNNNN
121.20.355.00, SNM2NN/011BN9ADB3C3C3NNNN/NNNNN
11045337, SNM2NN/011BN9ADB3F4F4NNNN/NNNNN
11048620, SNM2NN/011BN9FDBM3B5B5NNNN/NNNNN
11029605, SNM2NN/011BN9JDBM4E5E5NNNN/NNNNN
121.20.733.00, SNM2NN/011BN9MBBM1C3C3NNNN/NNNNN
121.20.153.00, SNM2NN/012BN03CAM4E5E5NNNN/NNNNN
121.20.734.00, SNM2NN/012BN06GAM1F4F4NNNN/NNNAN
121.20.276.00, SNM2NN/012BN06SAM6E5E5NNNN/NNNNN
11125114, SNM2NN/014B49ADB4E5E5NNNN/NNNNN
121.20.132.00, SNM2NN/014BN01BAM1C7C7NNNN/NNNNN
121.20.541.00, SNM2NN/014BN01BAM1E5E5NNNN/NNNNN
121.20.423.00, SNM2NN/014BN01BAM1F4F4NNNN/NNNNN
121.20.750.00, SNM2NN/014BN01BAM1F4F4NNNN/NNNNN
11029550, SNM2NN/014BN01DAM1C7C7NNNN/NNNNN
121.20.247.00, SNM2NN/014BN01FAM1C7C7NNNN/NNNNN
83010462, SNM2NN/014BN01FAM1F4F4NNNA/NNNNN
121.20.609.00, SNM2NN/014BN01FAM1F4F4NNNN/NNNNN
121.20.068.00, SNM2NN/014BN02AAM1B5B5NNNN/NNNNN
121.20.753.00, SNM2NN/014BN02AAM1F4F4NNNN/NNNNN
121.20.119.00, SNM2NN/014BN02DBM1B5B5NNNA/NNNNN
121.20.066.00, SNM2NN/014BN03CAM3B5B5NNNN/NNNNN
11067108, SNM2NN/014BN03CAM3F4F4NNNN/NNNNN
121.20.154.00, SNM2NN/014BN03CAM4E5E5NNNN/NNNNN
121.20.637.00, SNM2NN/014BN03DBM3B5B5NNNN/NNNNN
121.20.433.00, SNM2NN/014BN03DBM4E5E5NNNN/NNNNN
121.20.302.00, SNM2NN/014BN03TCM4E5E5NNNN/NNNNN
121.20.668.00, SNM2NN/014BN04AAM1B5B5NNNN/NNNNN
11030558, SNM2NN/014BN05AAM1B5B5NNNN/NNNNN
83017864, SNM2NN/014BN05AAM1E5E5NNNN/NNNNN
83017905, SNM2NN/014BN05BAM1E5E5NNNN/NNNNN
121.20.611.00, SNM2NN/014BN06AAM6E5E5NNNN/NNNNN
11057813, SNM2NN/014BN06BAM6E5E5NNNA/NNNNN
121.20.784.00, SNM2NN/014BN06DBM1C7C7NNNN/NNNNN
83019709, SNM2NN/014BN06GAM1B5B5YYNN/NNNNN
121.20.757.00, SNM2NN/014BN06GAM1C7C7NNNN/NNNNN
83013720, SNM2NN/014BN06GAM1F4F4NNNN/NNNAN
121.20.185.00, SNM2NN/014BN06GAM6E5C3PRNN/NNNNN
121.20.044.00, SNM2NN/014BN06GAM6E5E5NNNN/NNNNN
121.20.348.00, SNM2NN/014BN06GBM6E5C3PRNN/NNNNN
121.20.270.00, SNM2NN/014BN06GBM6E5E5NNNN/NNNNN

121.20.765.00, SNM2NN/014BN06SAM1B5B5YYNN/NNNNN
121.20.667.00, SNM2NN/014BN06SAM1C7C7NNNN/NNNNN
121.20.053.00, SNM2NN/014BN06SAM6E5E5NNNN/NNNNN
121.20.778.00, SNM2NN/014BN9ADB4E5E5NNNN/NNNNN
121.20.638.00, SNM2NN/014BN9FDBM3B5B5NNNN/NNNNN
121.20.434.00, SNM2NN/014BN9JDBM4E5E5NNNN/NNNNN
121.20.590.00, SNM2NN/017BN01BAM1B5B5NNNN/NNNNN
121.20.357.00, SNM2NN/017BN01BAM1C7C7NNNA/NNNNN
121.20.166.00, SNM2NN/017BN01BAM1C7C7NNNN/NNNNN
83013922, SNM2NN/017BN01BAM1F4F4NNNN/NNNNN
121.20.780.00, SNM2NN/017BN01BBM1C7C7NNNN/NNNNN
121.20.307.00, SNM2NN/017BN01FAM1C7C7NNNN/NNNNN
83015877, SNM2NN/017BN01FAM1F4F4NNNN/NNNNN
121.20.707.00, SNM2NN/017BN02AAM1B5B5NNNA/NNNNN
83010998, SNM2NN/017BN02AAM1B5B5NNNN/NNNKN
121.20.059.00, SNM2NN/017BN02AAM1B5B5NNNN/NNNNN
83019915, SNM2NN/017BN02AAM6E5E5NNNN/NNNNN
11057869, SNM2NN/017BN02DBM1B5B5NNNA/NNNNN
121.20.174.00, SNM2NN/017BN02DBM1B5B5NNNN/NNNNN
121.20.041.00, SNM2NN/017BN03CAM3B5B5NNNN/NNNNN
121.20.169.00, SNM2NN/017BN03CAM3M3MDPRNN/NNNNN
121.20.626.00, SNM2NN/017BN03DBM3C7C7NNNN/NNNNN
121.20.303.00, SNM2NN/017BN03TCM4E5E5NNNN/NNNNN
121.20.581.00, SNM2NN/017BN05AAM1B5B5NNNN/NNNNN
121.20.337.00, SNM2NN/017BN06AAM1F4F4NNNN/NNNNN
121.20.342.00, SNM2NN/017BN06BAM6E5E5NNNN/NNNNN
121.20.751.00, SNM2NN/017BN06BBM1F4F4NNNN/NNNNN
121.20.785.00, SNM2NN/017BN06DBM1C7C7NNNN/NNNNN
121.20.756.00, SNM2NN/017BN06GAM1C7C7NNNN/NNNNN
121.20.400.00, SNM2NN/017BN06GAM1F4F4NNNN/NNNNN
121.20.147.00, SNM2NN/017BN06GAM6E5C3PRNN/NNNNN
121.20.566.00, SNM2NN/017BN06GAM6E5E5NNNN/NNNCN
121.20.045.00, SNM2NN/017BN06GAM6E5E5NNNN/NNNNN
121.20.263.00, SNM2NN/017BN06GBM6E5C3PLNN/NNNNN
83016922, SNM2NN/017BN06GBM6E5C3PRNN/NNNNN
121.20.258.00, SNM2NN/017BN06GBM6E5E5NNNN/NNNNN
121.20.048.00, SNM2NN/017BN06GBM6E6E6NNNN/NNNNN
121.20.764.00, SNM2NN/017BN06SAM1F4F4NNNN/NNNNN
121.20.072.00, SNM2NN/017BN06SAM6E5E5NNNN/NNNNN
11037900, SNM2NN/017BN06SAM6E5E5NNNN/NNNVN
121.20.662.00, SNM2NN/017BN92CAM3B5B5NNNN/NNNNN
121.20.627.00, SNM2NN/017BN9ADB3C7C7NNNN/NNNNN
11059575, SNM2NN/017BN9JDBM4E6E6NNNN/NNNNN
121.20.621.00, SNM2NN/019BN01BAM1B7B7NNNN/NNNNN
121.20.175.00, SNM2NN/019BN01BAM1C7C7NNNN/NNNNN
121.20.568.00, SNM2NN/019BN01FAM1C7C7NNNN/NNNNN
121.20.376.00, SNM2NN/019BN01FAM1F5F5NNNN/NNNNN
121.20.688.00, SNM2NN/019BN02AAM1B7B7NNDN/NNNNN
121.20.347.00, SNM2NN/019BN02AAM1B7B7NNNN/NNNNN
121.20.715.00, SNM2NN/019BN02AAM1F4F4NNNN/NNNNN

121.20.142.00, SNM2NN/019BN02DBM1B7B7NNNN/NNNNN
121.20.483.00, SNM2NN/019BN02DBM1B7B7NNNN/NNNNN
121.20.067.00, SNM2NN/019BN03CAM3B7B7NNNN/NNNNN
121.20.207.00, SNM2NN/019BN03CAM4E6E6NNNN/NNNNN
121.20.101.00, SNM2NN/019BN03DBM3B5B5NNNA/NNNNN
121.20.782.00, SNM2NN/019BN03DBM3B7B7NNNN/NNNNN
121.20.408.00, SNM2NN/019BN03DBM3C7C7NNNN/NNNNN
121.20.338.00, SNM2NN/019BN06AAM1F5F5NNNN/NNNNN
121.20.138.00, SNM2NN/019BN06AAM6E6E6NNNN/NNNNN
121.20.331.00, SNM2NN/019BN06BAM6E6E6NNDN/NNNNN
121.20.324.00, SNM2NN/019BN06BAM6E6E6NNNN/NNNNN
121.20.786.00, SNM2NN/019BN06DBM1C7C7NNNN/NNNNN
121.20.758.00, SNM2NN/019BN06GAM1C7C7NNNN/NNNNN
121.20.487.00, SNM2NN/019BN06GAM1F5F5NNNN/NNNNN
121.20.387.00, SNM2NN/019BN06GAM6E6C3PRNN/NNNNN
121.20.049.00, SNM2NN/019BN06GAM6E6E6NNNN/NNNNN
121.20.264.00, SNM2NN/019BN06GBM6E5C3PLNN/NNNNN
11068302, SNM2NN/019BN06GBM6E5C3PRNN/NNNNN
121.20.259.00, SNM2NN/019BN06GBM6E6E6NNNN/NNNNN
121.20.612.00, SNM2NN/019BN06SAM1F5F5NNNN/NNNNN
121.20.054.00, SNM2NN/019BN06SAM6E6E6NNNN/NNNNN
121.20.205.00-02, SNM2NN/019BN06SAM6E6E6TDNN/NNNBN
121.20.754.00, SNM2NN/019BN94DBM3C7C7NNNN/NNNNN
121.20.409.00, SNM2NN/019BN9ADB3C7C7NNNN/NNNNN
11037097, SNM2NN/019BN9FDBM3B7B7NNNN/NNNNN
121.20.063.00, SNM2NN/019BN9JDBM3B5B5NNNA/NNNNN
11029617, SNM2NN/019BN9JDBM4E6E6NNNN/NNNNN
121.20.740.00, SNM2NN/022BN01BAM1B7B7NNNN/NNNNN
121.20.176.00, SNM2NN/022BN01BAM1C7C7NNNN/NNNNN
121.20.789.00, SNM2NN/022BN01BAM1F5F5NNNN/NNNNN
121.20.360.00, SNM2NN/022BN01DAM6E6E6NNNN/NNNNN
121.20.190.00, SNM2NN/022BN01FAM1C7C7NNNN/NNNNN
121.20.070.00, SNM2NN/022BN02AAM1B7B7NNNA/NNNNN
121.20.113.00, SNM2NN/022BN02DBM1B7B7NNNA/NNNNN
121.20.191.00, SNM2NN/022BN03CAM3B7B7NNNN/NNNNN
121.20.172.00, SNM2NN/022BN03CAM4E6E6NNNN/NNNNN
11038575, SNM2NN/022BN03DBM3B7B7NNNN/NNNNN
121.20.431.00, SNM2NN/022BN03DBM3C7C7NNNN/NNNNN
121.20.351.00, SNM2NN/022BN03DBM4E6E6NNNN/NNNNN
121.20.368.00, SNM2NN/022BN03DLM8B7B7NNNN/NNNNN
11100230, SNM2NN/022BN04AAM1B5B5NNNN/NNNNN
83010974, SNM2NN/022BN04AAM1B7B7NNNN/NNNNN
83010536, SNM2NN/022BN05AAM1B7B7NNNN/NNNNN
83009264, SNM2NN/022BN06BAM6E6E6NNNN/NNNNN
121.20.787.00, SNM2NN/022BN06DBM1C7C7NNNN/NNNNN
11055506, SNM2NN/022BN06GAM1B7B7YYNN/NNNNN
121.20.613.00, SNM2NN/022BN06GAM1C7C7NNNN/NNNNN
121.20.759.00, SNM2NN/022BN06GAM1C7C7NNNN/NNNNN
121.20.562.00, SNM2NN/022BN06GAM1F5F5NNNA/NNNNN
121.20.073.00, SNM2NN/022BN06GAM6E6E6NNNN/NNNNN

121.20.359.00, SNM2NN/022BN06GBM6E6C3PRNN/NNNNN
121.20.597.00, SNM2NN/022BN06GBM6E6E6NNNN/NNNNN
121.20.274.00, SNM2NN/022BN06SAM1C7C7NNNN/NNNNN
83018165, SNM2NN/022BN06SAM1F5F5NNNN/NNNNN
121.20.380.00, SNM2NN/022BN06SAM6E6E6NNNN/NNNAN
121.20.055.00, SNM2NN/022BN06SAM6E6E6NNNN/NNNNN
83013692, SNM2NN/022BN91DBM3C7C7NNNN/NNNNN
121.20.432.00, SNM2NN/022BN9ADB3C7C7NNNN/NNNNN
11038576, SNM2NN/022BN9FDBM3B7B7NNNN/NNNNN
121.20.370.00, SNM2NN/022BN9GDL8B7B7NNNN/NNNNN
121.20.352.00, SNM2NN/022BN9JDBM4E6E6NNNN/NNNNN
121.20.223.00, SNM2NN/025BN01BAM1C8C8NNNN/NNNNN
121.20.617.00, SNM2NN/025BN01BAM1F5F5NNNN/NNNNN
83022043, SNM2NN/025BN01FAM1B7B7NNNN/NNNNN
121.20.776.00, SNM2NN/025BN01FAM1C8C8NNNN/NNNNN
83015648, SNM2NN/025BN01FAM1F5F5NNNN/NNNNN
83022678, SNM2NN/025BN01FAM6E6E6NNNN/NNNNN
121.20.069.00, SNM2NN/025BN02AAM1B7B7NNNN/NNNNN
121.20.195.00, SNM2NN/025BN02DBM1B7B7NNNN/NNNNN
121.20.114.00, SNM2NN/025BN03CAM3B7B7NNNN/NNNNN
121.20.536.00, SNM2NN/025BN03CAM3C8C8NNNN/NNNNN
121.20.739.00, SNM2NN/025BN04AAM1B7B7NNNN/NNNNN
121.20.285.00, SNM2NN/025BN06BAM6E6E6NNNN/NNNNN
121.20.761.00, SNM2NN/025BN06GAM1C7C7NNNN/NNNNN
121.20.735.00, SNM2NN/025BN06GAM1F5F5NNNA/NNNNN
121.20.050.00, SNM2NN/025BN06GAM6E6E6NNNN/NNNNN
11068188, SNM2NN/025BN06GBM6E6C3PLNN/NNNNN
11052382, SNM2NN/025BN06GBM6E6C3PRNN/NNNNN
11046685, SNM2NN/025BN06GBM6E6E6NNNN/NNNNN
121.20.145.00, SNM2NN/025BN06GCM6E6E6TENN/NNNNN
121.20.554.00, SNM2NN/025BN06SAM1C8C8NNNA/NNNNN
121.20.056.00, SNM2NN/025BN06SAM6E6E6NNNN/NNNNN
121.20.663.00, SNM2NN/025BN92CAM3B7B7NNNN/NNNNN
83017236, SNM2NN/025BN9JDBM4E6E6NNNN/NNNNN
83018880, SNM2NN/6,0B401BAM1C3C3NNNA/NNNNN
83018635, SNM2NN/6,0B406BAM1C3C3NNNA/NNNNN
11121003, SNM2NN/6,0B406SAM6E5E5NNNN/NNNNN
121.20.255.00, SNM2NN/6,0BN01BAM1C3C3NNNN/NNNNN
121.20.736.00, SNM2NN/6,0BN01BAM1F4F4NNNN/NNNNN
121.20.727.00, SNM2NN/6,0BN01FAM1C3C3NNNN/NNNNN
83015876, SNM2NN/6,0BN01FAM1F4F4NNNN/NNNNN
121.20.192.00, SNM2NN/6,0BN02AAM1B5B5NNNN/NNNNN
11043208, SNM2NN/6,0BN02AAM1B5B5NNNN/NNNWN
121.20.193.00, SNM2NN/6,0BN02DBM1B5B5NNNN/NNNNN
121.20.124.00, SNM2NN/6,0BN03CAM3B5B5NNNN/NNNNN
121.20.168.00, SNM2NN/6,0BN03CAM4E5E5NNNN/NNNNN
121.20.599.00, SNM2NN/6,0BN03DBM3C3C3NNNN/NNNNN
83010987, SNM2NN/6,0BN04AAM1B5B5NNNN/NNNNN
121.20.755.00, SNM2NN/6,0BN06BAM6E5E5NNNN/NNNNN
11043227, SNM2NN/6,0BN06GAM1B5B5YYDN/NNNWN

121.20.547.00, SNM2NN/6,0BN06GAM1B5B5YYNN/NNNNN
121.20.742.00, SNM2NN/6,0BN06GAM1F4F4NNNA/NNNNN
11046161, SNM2NN/6,0BN06GAM6E5E5NNNA/NNNAN
121.20.095.00, SNM2NN/6,0BN06GAM6E5E5NNNN/NNNNN
121.20.582.00, SNM2NN/6,0BN06SAM1F4F4NNNA/NNNNN
121.20.097.00, SNM2NN/6,0BN06SAM6E5E5NNNN/NNNNN
121.20.603.00, SNM2NN/6,0BN06SAM7F4F4NNNA/NNNNN
83011366, SNM2NN/6,0BN9FDBM3B5B5NNNN/NNNNN
121.20.600.00, SNM2NN/6,0BN9JDBM3C3C3NNNN/NNNNN
11029569, SNM2NN/6,0BN9JDBM4E5E5NNNN/NNNNN
11109618, SNM2NN/8,0B401DAM1B5B5NNNN/NNNNN
11109594, SNM2NN/8,0B402DBM1B5B5NNNN/NNNNN
11114494, SNM2NN/8,0B406SAM6E5E5NNNN/NNNNN
11115598, SNM2NN/8,0B4L5DBM1B5B5NNNN/NNNNN
83014887, SNM2NN/8,0BN01BAM1B5B5NNDN/NNNNN
83014031, SNM2NN/8,0BN01BAM1B5B5NNNN/NNNNN
121.20.256.00, SNM2NN/8,0BN01BAM1C3C3NNNN/NNNNN
121.20.161.00, SNM2NN/8,0BN01BAM1F4F4NNNN/NNNNN
121.20.716.00, SNM2NN/8,0BN01BBM1F4F4NNNN/NNNNN
121.20.657.00, SNM2NN/8,0BN01DAM1B5B5NNNN/NNNNN
11057269, SNM2NN/8,0BN01FAM1C3C3NNNN/NNNNN
121.20.647.00, SNM2NN/8,0BN01FAM6E5E5NNNA/NNNNN
121.20.646.00, SNM2NN/8,0BN02AAM1B5B5NNDN/NNNNN
121.20.057.00, SNM2NN/8,0BN02AAM1B5B5NNNN/NNNNN
83014929, SNM2NN/8,0BN02AAM6E5E5NNNN/NNNNN
83016179, SNM2NN/8,0BN02DBM1B5B5NNDN/NNNNN
121.20.111.00, SNM2NN/8,0BN02DBM1B5B5NNNN/NNNNN
121.20.039.00, SNM2NN/8,0BN03CAM3B5B5NNNN/NNNNN
121.20.164.00, SNM2NN/8,0BN03CAM4E5E5NNNN/NNNNN
121.20.311.00, SNM2NN/8,0BN03DBM3F4F4NNNN/NNNNN
11041325, SNM2NN/8,0BN03DBM4E5E5NNNN/NNNNN
121.20.665.00, SNM2NN/8,0BN04AAM1B5B5NNNN/NNNNN
121.20.549.00, SNM2NN/8,0BN05AAM1B5B5NNNN/NNNNN
121.20.596.00, SNM2NN/8,0BN06AAM6E5E5NNNN/NNNNN
11078241, SNM2NN/8,0BN06BAM6E5E5NNYN/NNNVN
11067272, SNM2NN/8,0BN06DBM1C3C3NNNN/NNNNN
11058154, SNM2NN/8,0BN06GAM1C3C3NNNN/NNNNN
121.20.490.00, SNM2NN/8,0BN06GAM1F4F4NNNA/NNNNN
11052478, SNM2NN/8,0BN06GAM6C3C3NNNN/NNNNN
83011410, SNM2NN/8,0BN06GAM6E5E5NNDN/NNNNN
121.20.096.00, SNM2NN/8,0BN06GAM6E5E5NNNN/NNNNN
121.20.687.00, SNM2NN/8,0BN06GBM6E5E5NNNN/NNNNN
121.20.666.00, SNM2NN/8,0BN06SAM1C3C3NNNN/NNNNN
83020524, SNM2NN/8,0BN06SAM1F4F4NNNN/NNNNN
121.20.098.00, SNM2NN/8,0BN06SAM6E5E5NNNN/NNNNN
11037970, SNM2NN/8,0BN06SAM6E5E5NNNN/NNNVN
121.20.312.00, SNM2NN/8,0BN9ADB3F4F4NNNA/NNNNN
11059712, SNM2NN/8,0BN9FDBM3B5B5NNNN/NNNNN
11041326, SNM2NN/8,0BN9JDBM4E5E5NNNN/NNNNN
121.20.622.00, SNM2NN/9,0BN06SAM6E5E5NNNA/NNNVN

121.20.232.00, SNM2NN/9,5BN06GAM6E5E5NNNN/NNNNN
121.20.250.00, SNM2SN/019LN03DBS1NNNNNNNN/NNNNN
121.20.251.00, SNM2SN/019LN9JDBS1NNNNNNNN/NNNNN
121.20.252.00, SNM2SN/019RN03DBS1NNNNNNNN/NNNNN
121.20.253.00, SNM2SN/019RN9JDBS1NNNNNNNN/NNNNN
11055561, SNM2SN/022LN9JDBS1NNNNNNNN/NNNNN
11032305, SNM2Y./8 D CO06 +++4.
11083124, SNM2YL/011RN06BAY4E4E5NNYA/XNNAN
121.20.717.00, SNM2YL/014R401BAY4C6C6NNNN/XAONN
11104485, SNM2YL/014RN06BAY4E4E5NNYA/XNNAN
11045421, SNM2YL/017L406BAYXE4E5NNNN/XNNAN
11077281, SNM2YL/017LN06BAY4E4E5NNYA/XNNAN
11056497, SNM2YL/017RN06BAY4E4E5NNYA/XNNAN
121.20.618.00, SNM2YL/022L406BAYXE4E5NNNN/XNNAN
11041819, SNM2YL/022R491DBY4E6E6NNNN/XBSNN
11056498, SNM2YL/022RN06BAY4E4E5NNYA/XNNAN
11034908, SNM2YL/6 S CE06 +++1.
11032286, SNM2YL/6 S CE06 +++4.
11089308, SNM2YL/8 S CE06 +++1.
121.20.695.00, SNM2YN/011R402AAY6E5E5NNNA/XASNN
11080608, SNM2YN/014LN06BAY6E4E5NNYA/XNNAN
121.20.769.00, SNM2YN/014R402AAY6E5E5NNNA/XASNN
121.20.660.00, SNM2YN/017L406GAY6E5E5NNNA/XAFNN
121.20.644.00, SNM2YN/017L406GBY6E5E5NNNA/XAFNN
11080939, SNM2YN/022LN06BAY6E4E5NNYA/XNNAN
121.20.777.00, SNM2YN/022R491DBY6E6E6NNNN/XBSNN
121.20.774.00, SNM2YN/8,0R402AAY6B5B5NNNN/XAYNN
121.20.773.00, SNM2YN/8,0R402AAY6B5B5NNNN/XBONN
121.20.653.00, SNM2YN/8,0R402AAY6E5E5NNNA/XASNN
11066763, SNM3/22 . CI07 +++_E
121.25.264.00, SNM3/26 . CO01 LOY_
121.25.265.00, SNM3/33 . CO01 LOY_
11123588, SNM3/33 . CO91 +++_E
11126943, SNM3/75 . CO07 +++_C
121.25.253.00, SNM3CN/026RN01DAC1C7C7NNNN/NNNNN
121.25.154.00, SNM3DN/022BN01BAD1C7C7NNNN/NNNNN
121.25.155.00, SNM3DN/026BN01BAD1C7C7NNNN/NNNNN
121.25.156.00, SNM3DN/033BN01BAD1CACANNNN/NNNNN
121.25.158.00, SNM3DN/033BN03CBD1CACANNNN/NNNNN
11084197, SNM3DN/033BN07SAD1E9E9NNNN/NNNNN
121.25.157.00, SNM3DN/038BN01BAD1CACANNNN/NNNNN
121.25.289.00, SNM3GN/022RN01BAM1C7C7NNNN/NNNNN
121.25.300.00, SNM3GN/026LN07BCM6E8E8NNNN/NNNNN
121.25.233.00, SNM3GN/026LN07GAM6E8E8NNNN/NNNNN
83017484, SNM3GN/033LN01FAM6CACANNNN/NNNNN
83013368, SNM3GN/033LN07GAM6A4A4NNNN/NNNNN
121.25.094.00, SNM3GN/033RN07BCM6A4A4NNNN/NNNNN
121.25.250.00, SNM3GN/033RN07BCM6E9E9NNNN/NNNNN
121.25.260.00, SNM3GN/038LN07BCM6E9E9NNNN/NNNNN
11031170, SNM3GN/038RN01BAM1BBBBNNNN/NNNAN

11048124, SNM3GN/038RN01BAM1BBBBNNNN/NNNAN
11061727, SNM3GN/038RN07BCM1A4A4NNNN/NNNNN
121.25.272.00, SNM3GN/038RN07BCM6A2A3NNNN/NNNNN
121.25.251.00, SNM3GN/044LN07BCM6E9E9NNNN/NNNNN
121.25.234.00, SNM3GN/044LN07GAM6E9E9NNNN/NNNNN
121.25.270.00, SNM3GN/044RN01BAM1CACANNNN/NNNNN
83017546, SNM3GN/044RN07BCM6E9E9NNBN/NNNNN
121.25.288.00, SNM3GN/048LN07BCM6E9E9NNNN/NNNNN
83012653, SNM3GN/048RN07BBMFACANNBN/NNNNN
121.25.302.00, SNM3GN/048RN07BCM6A4A4NNNN/NNNNN
121.25.220.00, SNM3GN/048RN07BCM6E9E9NNNN/NNNNN
11061932, SNM3GN/048RN07GAM6E8E8NNNN/NNNNN
121.25.239.00, SNM3GN/055LN07BCM6E9E9NNNN/NNNCN
11037521, SNM3GN/055LN07GBM6A4A4NNNN/NNNNN
11032238, SNM3GN/055LN07GBM6CZE8NNNN/NNNNN
83017881, SNM3GN/055RN01BAM6E9E9NNNN/NNNNN
83019157, SNM3GN/055RN01DAM6E9E9NNNN/NNNNN
11107240, SNM3GN/055RN91BAM6E9E9NNNN/NNNNN
11051189, SNM3GN/063LN07SAM6E9E9NNNN/NNNNN
83009525, SNM3GN/063RN07BBMFCDNBN/NNNNN
11056496, SNM3NL/026BN07BCL6E5E5NNYB/NNNAN
121.25.274.00, SNM3NL/026BN07SAL1F5F5NNNN/NNNNN
11077628, SNM3NL/033BN01BAL1CACANNNN/NNNNN
11069667, SNM3NL/033BN06AAL1BABANNNB/NNNNN
11066961, SNM3NL/033BN07BCL6E5E5NNYB/NNNAN
121.25.295.00, SNM3NL/044BN06AAL2BBBBNNNN/NNNNN
121.25.126.00, SNM3NL/055BN07SALTE8E8NNNN/NNNVN
83007910, SNM3NN/022BN01BAM1C7C7NNNB/NNNNN
121.25.096.00, SNM3NN/022BN01BAM1C7C7NNNN/NNNNN
121.25.118.00, SNM3NN/022BN01DAM1C7C7NNNN/NNNNN
121.25.127.00, SNM3NN/022BN01FAM1C7C7NNNN/NNNNN
121.25.245.00, SNM3NN/022BN06AAM1BABANNNB/NNNNN
121.25.188.00, SNM3NN/022BN07BCM6A3A3NNNN/NNNNN
121.25.174.00, SNM3NN/022BN07BCM6CZE8PLNN/NNNNN
121.25.135.00, SNM3NN/022BN07BCM6E8E8NNNN/NNNNN
121.25.221.00, SNM3NN/022BN07GAM1C7C7NNNN/NNNNN
121.25.163.00, SNM3NN/022BN07GAM6A3A3NNNN/NNNNN
121.25.240.00, SNM3NN/022BN07GAM6E8E8NNNN/NNNCN
121.25.178.00, SNM3NN/022BN07GAM6E8E8NNNN/NNNNN
121.25.105.00, SNM3NN/022BN07GBM6CZE8PLNN/NNNNN
121.25.198.00, SNM3NN/022BN07SAM6A3A3NNNN/NNNNN
121.25.296.00, SNM3NN/022BN07SAM6C7C7NNNN/NNNNN
121.25.208.00, SNM3NN/022BN07SAM6E8E8NNNN/NNNNN
121.25.097.00, SNM3NN/026BN01BAM1C7C7NNNN/NNNNN
11103149, SNM3NN/026BN01BAM1F5F5NNNN/NNNNN
83007755, SNM3NN/026BN01BAMFACANNBN/NNNNN
121.25.143.00, SNM3NN/026BN01DAM1C7C7NNNB/NNNNN
121.25.119.00, SNM3NN/026BN01DAM1C7C7NNNN/NNNNN
121.25.128.00, SNM3NN/026BN01FAM1C7C7NNNN/NNNNN
121.25.252.00, SNM3NN/026BN06AAM1BABANNNB/NNNNN

83020482, SNM3NN/026BN07BCM1BABANNBN/NNNNN
121.25.189.00, SNM3NN/026BN07BCM6A3A3NNNN/NNNNN
121.25.175.00, SNM3NN/026BN07BCM6CZE8PLNN/NNNNN
121.25.223.00, SNM3NN/026BN07BCM6CZE8PRNN/NNNNN
121.25.136.00, SNM3NN/026BN07BCM6E8E8NNNN/NNNNN
121.25.164.00, SNM3NN/026BN07GAM6A3A3NNNN/NNNNN
121.25.179.00, SNM3NN/026BN07GAM6E8E8NNNN/NNNNN
121.25.106.00, SNM3NN/026BN07GBM6CZE8PLNN/NNNNN
121.25.199.00, SNM3NN/026BN07SAM6A3A3NNNN/NNNNN
11057594, SNM3NN/026BN07SAM6E8E8NNNN/NNNCN
121.25.209.00, SNM3NN/026BN07SAM6E8E8NNNN/NNNNN
11072140, SNM3NN/026BN91BAMFCACANNBN/NNNNN
121.25.276.00, SNM3NN/033BN01BAM1CACANNNB/NNNNN
121.25.098.00, SNM3NN/033BN01BAM1CACANNNN/NNNNN
11123586, SNM3NN/033BN01BAM6E6E6NNBB/NNNNN
121.25.120.00, SNM3NN/033BN01DAM1CACANNNN/NNNNN
121.25.129.00, SNM3NN/033BN01FAM1CACANNNN/NNNNN
121.25.277.00, SNM3NN/033BN01FAM6E9E9NNNN/NNNNN
83011088, SNM3NN/033BN06AAM1BABANNNB/NNNNA
121.25.242.00, SNM3NN/033BN06AAM1BBBBNNNB/NNNNN
121.25.190.00, SNM3NN/033BN07BCM6A4A4NNNN/NNNNN
121.25.176.00, SNM3NN/033BN07BCM6CZE8PLNN/NNNNN
121.25.224.00, SNM3NN/033BN07BCM6CZE8PRNN/NNNNN
121.25.137.00, SNM3NN/033BN07BCM6E9E9NNNN/NNNNN
121.25.165.00, SNM3NN/033BN07GAM6A4A4NNNN/NNNNN
83011245, SNM3NN/033BN07GAM6CACANNNN/NNNNN
121.25.180.00, SNM3NN/033BN07GAM6E9E9NNNN/NNNNN
121.25.104.00, SNM3NN/033BN07GBM6CZA4PLNN/NNNNN
121.25.273.00, SNM3NN/033BN07GBM6E9E9NNNN/NNNNN
121.25.200.00, SNM3NN/033BN07SAM6A4A4NNNN/NNNNN
121.25.218.00, SNM3NN/033BN07SAM6CACANNNN/NNNNN
121.25.210.00, SNM3NN/033BN07SAM6E9E9NNNN/NNNNN
121.25.301.00, SNM3NN/033BN07SAM6F6F6NNNN/NNNNN
83021216, SNM3NN/038BN01BAM1A4A4NNNN/NNNNN
121.25.281.00, SNM3NN/038BN01BAM1BBBBNNNN/NNNNN
11054897, SNM3NN/038BN01BAM1CACANNNB/NNNNN
121.25.099.00, SNM3NN/038BN01BAM1CACANNNN/NNNNN
11045954, SNM3NN/038BN01BAM2H8H8NNNN/NNNNN
11069147, SNM3NN/038BN01BAM6E6E6NNBB/NNNNN
121.25.121.00, SNM3NN/038BN01DAM1CACANNNN/NNNNN
121.25.130.00, SNM3NN/038BN01FAM1CACANNNN/NNNNN
83016057, SNM3NN/038BN03BBM1CACANNNN/NNNNN
121.25.254.00, SNM3NN/038BN06AAM1BBBBNNNB/NNNNN
83008116, SNM3NN/038BN07BCM6A4A4NNBN/NNNNN
121.25.191.00, SNM3NN/038BN07BCM6A4A4NNNN/NNNNN
121.25.177.00, SNM3NN/038BN07BCM6CZE8PLNN/NNNNN
121.25.225.00, SNM3NN/038BN07BCM6CZE8PRNN/NNNNN
121.25.138.00, SNM3NN/038BN07BCM6E9E9NNNN/NNNNN
121.25.166.00, SNM3NN/038BN07GAM6A4A4NNNN/NNNNN
121.25.181.00, SNM3NN/038BN07GAM6E9E9NNNN/NNNNN

11065899, SNM3NN/038BN07GAM6F6F6NNNN/NNNNN
121.25.108.00, SNM3NN/038BN07GBM6CZE8PLNN/NNNNN
121.25.248.00, SNM3NN/038BN07GBM6CZE8PRNN/NNNNN
121.25.201.00, SNM3NN/038BN07SAM6A4A4NNNN/NNNNN
11086145, SNM3NN/038BN07SAM6E8E8NNNN/NNNNN
121.25.211.00, SNM3NN/038BN07SAM6E9E9NNNN/NNNNN
11107695, SNM3NN/038BN91BAM1CACANNNN/NNNNN
11045326, SNM3NN/038BN91BAM2H8H8NNNN/NNNNN
11069190, SNM3NN/038BN91BAM6E6E6NNBB/NNNNN
121.25.100.00, SNM3NN/044BN01BAM1CACANNNN/NNNNN
11062693, SNM3NN/044BN01BAM6E9E9NNNB/NNNNN
121.25.122.00, SNM3NN/044BN01DAM1CACANNNN/NNNNN
121.25.131.00, SNM3NN/044BN01FAM1CACANNNN/NNNNN
121.25.148.00, SNM3NN/044BN03BBM1CACANNNN/NNNNN
83011211, SNM3NN/044BN03FBM1CACANNNN/NNNNN
121.25.255.00, SNM3NN/044BN06AAM1BBBBNNNB/NNNNN
121.25.192.00, SNM3NN/044BN07BCM6A4A4NNNN/NNNNN
121.25.235.00, SNM3NN/044BN07BCM6CZE8PLNN/NNNNN
121.25.226.00, SNM3NN/044BN07BCM6CZE8PRNN/NNNNN
121.25.139.00, SNM3NN/044BN07BCM6E9E9NNNN/NNNNN
11093489, SNM3NN/044BN07GAM6A3A3NNNN/NNNNN
121.25.167.00, SNM3NN/044BN07GAM6A4A4NNNN/NNNNN
121.25.182.00, SNM3NN/044BN07GAM6E9E9NNNN/NNNNN
121.25.109.00, SNM3NN/044BN07GBM6CZE8PLNN/NNNNN
121.25.279.00, SNM3NN/044BN07GBM6CZE8PRNN/NNNNN
121.25.202.00, SNM3NN/044BN07SAM6A4A4NNNN/NNNNN
121.25.212.00, SNM3NN/044BN07SAM6E9E9NNNN/NNNNN
11062696, SNM3NN/044BN91BAM6E9E9NNNB/NNNNN
121.25.101.00, SNM3NN/048BN01BAM1CACANNNN/NNNNN
11029657, SNM3NN/048BN01FAM1CACANNNN/NNNNN
121.25.256.00, SNM3NN/048BN06AAM1BBBBNNNB/NNNNN
121.25.140.00, SNM3NN/048BN07BCM6E9E9NNNN/NNNNN
121.25.168.00, SNM3NN/048BN07GAM6A4A4NNNN/NNNNN
121.25.110.00, SNM3NN/048BN07GBM6CZE8PLNN/NNNNN
121.25.203.00, SNM3NN/048BN07SAM6A4A4NNNN/NNNNN
11107717, SNM3NN/048BN91BAM1CACANNNN/NNNNN
83011521, SNM3NN/055BN01BAM1CACANNNB/NNNNN
121.25.102.00, SNM3NN/055BN01BAM1CACANNNN/NNNNN
121.25.133.00, SNM3NN/055BN01FAM1CACANNNN/NNNNN
121.25.150.00, SNM3NN/055BN03BBM1CACANNNN/NNNNN
121.25.257.00, SNM3NN/055BN06AAM1BBBBNNNB/NNNNN
121.25.266.00, SNM3NN/055BN06AAM6A5A5NNNB/NNNNN
121.25.194.00, SNM3NN/055BN07BCM6A4A4NNNN/NNNNN
83017237, SNM3NN/055BN07BCM6CACANNNN/NNNNN
121.25.236.00, SNM3NN/055BN07BCM6CZE8PLNN/NNNNN
121.25.141.00, SNM3NN/055BN07BCM6E9E9NNNN/NNNNN
121.25.169.00, SNM3NN/055BN07GAM6A4A4NNNN/NNNNN
121.25.184.00, SNM3NN/055BN07GAM6E9E9NNNN/NNNNN
121.25.111.00, SNM3NN/055BN07GBM6CZE8PLNN/NNNNN
121.25.280.00, SNM3NN/055BN07GBM6CZE8PRNN/NNNNN

121.25.204.00, SNM3NN/055BN07SAM6A4A4NNNN/NNNNN
121.25.214.00, SNM3NN/055BN07SAM6E9E9NNNN/NNNNN
121.25.103.00, SNM3NN/063BN01BAM1CACANNNN/NNNNN
83007784, SNM3NN/063BN01BAMFCDNBN/NNNNN
121.25.125.00, SNM3NN/063BN01DAM1CACANNNN/NNNNN
121.25.151.00, SNM3NN/063BN03BBM1CACANNNN/NNNNN
83021044, SNM3NN/063BN03BBM1CDCNNNN/NNNNN
121.25.268.00, SNM3NN/063BN03FBM1CACANNNN/NNNNN
121.25.267.00, SNM3NN/063BN06AAM6A5A5NNNB/NNNNN
11031982, SNM3NN/063BN06DDM1BBBBNNNN/NNNNN
121.25.241.00, SNM3NN/063BN07BBM1CACANNNN/NNNNN
121.25.195.00, SNM3NN/063BN07BCM6A4A4NNNN/NNNNN
121.25.142.00, SNM3NN/063BN07BCM6E9E9NNNN/NNNNN
121.25.170.00, SNM3NN/063BN07GAM6A4A4NNNN/NNNNN
121.25.185.00, SNM3NN/063BN07GAM6E9E9NNNN/NNNNN
121.25.205.00, SNM3NN/063BN07SAM6A4A4NNNN/NNNNN
121.25.215.00, SNM3NN/063BN07SAM6E9E9NNNN/NNNNN
11038697, SNM3NN/063BN07SAM6E9E9NNNN/NNNVN
11072245, SNM3NN/063BN91BAMFCDNBN/NNNNN
121.25.297.00, SNM3NN/075BN01BAM1CACANNNN/NNNNN
121.25.173.00, SNM3NN/075BN01FAM1CACANNNN/NNNNN
121.25.152.00, SNM3NN/075BN03BBM1CACANNNN/NNNNN
11063457, SNM3NN/075BN03FBM1CACANNNN/NNNNN
11053990, SNM3NN/075BN03FBM1F6F6NNNN/NNNNN
121.25.271.00, SNM3NN/075BN06AAM6A5A5NNNB/NNNNN
83010318, SNM3NN/075BN07BCM1CACANBN/NNNNN
121.25.196.00, SNM3NN/075BN07BCM6A4A4NNNN/NNNNN
121.25.243.00, SNM3NN/075BN07BCM6E9E9NNNN/NNNNN
121.25.171.00, SNM3NN/075BN07GAM6A4A4NNNN/NNNNN
11103112, SNM3NN/075BN07GAM6CDCNNNN/NNNNN
121.25.186.00, SNM3NN/075BN07GAM6E9E9NNNN/NNNNN
121.25.206.00, SNM3NN/075BN07SAM6A4A4NNNN/NNNNN
121.25.216.00, SNM3NN/075BN07SAM6E9E9NNNN/NNNNN
121.25.262.00, SNM3NN/090BN01BAM1CACANNNN/NNNNN
121.25.299.00, SNM3NN/090BN01FAM1CACANNNN/NNNNN
121.25.153.00, SNM3NN/090BN03BBM1CACANNNN/NNNNN
121.25.275.00, SNM3NN/090BN06AAM6A5A5NNNB/NNNNN
121.25.197.00, SNM3NN/090BN07BCM6A4A4NNNN/NNNNN
121.25.244.00, SNM3NN/090BN07BCM6E9E9NNNN/NNNNN
121.25.172.00, SNM3NN/090BN07GAM6A4A4NNNN/NNNNN
121.25.187.00, SNM3NN/090BN07GAM6E9E9NNNN/NNNNN
121.25.207.00, SNM3NN/090BN07SAM6A4A4NNNN/NNNNN
121.25.217.00, SNM3NN/090BN07SAM6E9E9NNNN/NNNNN
121.25.283.0A, SNM3YL/026LN07BCYLE6E6NNNN/XBRCN
121.25.259.0C, SNM3YN/026RN07BCY6A3A3NNNN/XARNN
121.25.261.0C, SNM3YN/026RN07BCY6A3A3NNNN/XASNN
121.25.285.0C, SNM3YN/033RN07BCY6A3A3NNNN/XBSNN
11042794, SNM3YN/033RN07BPY6A3A3NNNN/XBSWN
121.25.284.0A, SNM3YN/038LN07BCY6A3A3NNNN/XBUNN
211.10.233.00, SNO1NN/1,2RN11DPNNC2C2NNNN/NNNNN

83021612, SNO1NN/1,2RN11DPNNF3F3NNNN/NNNNN
83009555, SNO1NN/1,2RN21DPNNF3F3NNNN/NNNNN
211.10.235.00, SNO1NN/1,7RN11DPNNC2C2NNNN/NNNNN
211.10.237.00, SNO1NN/2,2RN11DPNNC2C2NNNN/NNNNN
83021614, SNO1NN/2,2RN11DPNNF3F3NNNN/NNNNN
211.10.255.00, SNO1NN/2,2RN21DPNNC2C2NNNN/NNNNN
83021609, SNO1NN/2,6LN11DPNNF3F3NNNN/NNNNN
211.10.163.00, SNO1NN/2,6R421DPNNNNB1NNNN/NNNNN
211.10.241.00, SNO1NN/3,2RN11DPNNC2C2NNNN/NNNNN
83019016, SNO1NN/3,2RN11DPNNC3C3NNNN/NNNNN
83021615, SNO1NN/3,2RN11DPNNF3F3NNNN/NNNNN
211.10.259.00, SNO1NN/3,2RN21DPNNC2C2NNNN/NNNNN
211.10.107.00, SNO1NN/3,2RN21DPNNF3F3NNNN/NNNNN
83021610, SNO1NN/3,8LN11DPNNF3F3NNNN/NNNNN
83021616, SNO1NN/4,3RN11DPNNF3F3NNNN/NNNNN
211.10.263.00, SNO1NN/4,3RN21DPNNC2C2NNNN/NNNNN
83021611, SNO1NN/6,0LN11DPNNF3F3NNNN/NNNNN
11030695, SNO1NN/6,0RN21DPNNF3F3NNNN/NNNNN
83021595, SNO1NN/7,8RN11DPNNF3F3NNNN/NNNNN
211.20.390.00, SNO2NN/011L103CINNF6F4NNNN/NNNNN
211.20.800.00, SNO2NN/011L503CHNNB7B5NNNN/NNNNN
211.20.844.00, SNO2NN/011L503CHNNC3C3NNNN/NNNNN
211.20.099.00, SNO2NN/011LN03CHNNB7B5NNNN/NNNNN
211.20.266.00, SNO2NN/011LN03CHNNC3C3NNNN/NNNNN
211.20.108.00, SNO2NN/011LN03CHNNE6E5NNNN/NNNNN
211.20.811.00, SNO2NN/011LN03CHNNF5F4NNNN/NNNNN
211.20.593.00, SNO2NN/011LN03DONNB7B5NNNN/NNNNN
211.20.566.00, SNO2NN/011R503CHNNB7B5NNNN/NNNNN
211.20.416.00, SNO2NN/011R503CHNNC3C3NNNN/NNNNN
11033554, SNO2NN/011R503CHNNF5F4NNNN/NNNNN
211.20.236.00, SNO2NN/011RN03CHNNB7B5NNNN/NNNNN
211.20.265.00, SNO2NN/011RN03CHNNC3C3NNNN/NNNNN
211.20.365.00, SNO2NN/011RN03CHNNE6E5NNNN/NNNNN
211.20.406.00, SNO2NN/011RN03CHNNF5F4NNNN/NNNNN
11048115, SNO2NN/014L503CHNNE6E5NNNN/NNNNN
11047388, SNO2NN/014L503CHNNF5F4NNNN/NNNNN
211.20.238.00, SNO2NN/014LN03CHNNB7B5NNNN/NNNNN
211.20.696.00, SNO2NN/014LN03CHNNB7B5NNNN/NNNNN
211.20.268.00, SNO2NN/014LN03CHNNC7C3NNNN/NNNNN
211.20.860.00, SNO2NN/014LN03CHNNE6E5NNNN/NNNNN
211.20.436.00, SNO2NN/014LN03DONNB7B5NNNN/NNNNN
211.20.412.00, SNO2NN/014R503CHNNC7C3NNNN/NNNNN
211.20.237.00, SNO2NN/014RN03CHNNB7B5NNNN/NNNNN
211.20.267.00, SNO2NN/014RN03CHNNC7C3NNNN/NNNNN
211.20.759.00, SNO2NN/014RN03CHNNE6E5NNNN/NNNNN
211.20.387.00, SNO2NN/014RN03CHNNF5F4NNNN/NNNNN
211.20.865.00, SNO2NN/017L503CHNNC7C3NNNN/NNNNN
211.20.087.00, SNO2NN/017LN03CHNNB7B5NNNN/NNNNN
211.20.695.00, SNO2NN/017LN03CHNNB7B5NNNN/NNNNN
211.20.269.00, SNO2NN/017LN03CHNNC7C3NNNN/NNNNN

83015641, SNO2NN/017LN03CHNNE6E5NNNN/NNNNN
211.20.623.00, SNO2NN/017LN03CHNNF5F4NNNN/NNNNN
211.20.722.00, SNO2NN/017LN03DONNB7B5D9NN/NNNNN
211.20.537.00, SNO2NN/017R503CHNNB7B5NNNN/NNNNN
211.20.341.00, SNO2NN/017R503CHNNC7C3NNNN/NNNNN
211.20.051.00, SNO2NN/017RN03CHNNB7B5NNNN/NNNNN
211.20.068.00, SNO2NN/017RN03CHNNC7C3NNNN/NNNNN
211.20.458.00, SNO2NN/017RN03CHNNE6E5NNNN/NNNNN
211.20.766.00, SNO2NN/017RN03CHNNF5F4NNNN/NNNNN
211.20.841.00, SNO2NN/019L503CHNNB7B5NNNN/NNNNN
211.20.884.00, SNO2NN/019L503CHNNC7C3NNNN/NNNNN
211.20.377.00, SNO2NN/019LN03CHNNB7B5NNNN/NNNNN
211.20.271.00, SNO2NN/019LN03CHNNC7C3NNNN/NNNNN
11036041, SNO2NN/019LN03DONNC7C3NNNN/NNNNN
211.20.504.00, SNO2NN/019R503CHNNC7C3NNNN/NNNNN
211.20.572.00, SNO2NN/019R503CHNNE6E5NNNN/NNNNN
211.20.226.00, SNO2NN/019RN03CHNNB7B5NNNN/NNNNN
211.20.270.00, SNO2NN/019RN03CHNNC7C3NNNN/NNNNN
211.20.879.00, SNO2NN/019RN03CHNNE6E5NNNN/NNNNN
211.20.724.00, SNO2NN/019RN03CHNNF5F4NNNN/NNNNN
211.20.822.00, SNO2NN/022LN03CHNNB7B5NNNN/NNNNN
83014191, SNO2NN/022LN03CHNNC7C3NNNN/NNNNN
211.20.573.00, SNO2NN/022R503CHNNE6E5NNNN/NNNNN
211.20.314.00, SNO2NN/022RN03CHNNB7B5NNNN/NNNNN
211.20.272.00, SNO2NN/022RN03CHNNC7C3NNNN/NNNNN
83014890, SNO2NN/022RN03CHNNF5F4NNNN/NNNNN
211.20.830.00, SNO2NN/022RN03DONNB7B5NNNN/NNNNN
11035591, SNO2NN/025LN03CHNNB7B5NNNN/NNNNN
211.20.275.00, SNO2NN/025LN03CHNNC8C7NNNN/NNNNN
211.20.538.00, SNO2NN/025RN03CHNNB7B5NNNN/NNNNN
211.20.274.00, SNO2NN/025RN03CHNNC8C7NNNN/NNNNN
211.20.837.00, SNO2NN/4,0L503CHNNB6B5NNNN/NNNNN
11037542, SNO2NN/4,0L503CHNNC3C3NNNN/NNNNN
211.20.519.00, SNO2NN/4,0L503CHNNE6E5NNNN/NNNNN
211.20.714.00, SNO2NN/4,0LN03CHNNB6B5NNNN/NNNNN
211.20.864.00, SNO2NN/4,0LN03CHNNE6E5NNNN/NNNNN
211.20.790.00, SNO2NN/4,0LN03CHNNF4F4NNNN/NNNNN
11067210, SNO2NN/4,0R503CHNNB6B5NNNN/NNNNN
211.20.597.00, SNO2NN/4,0R503CHNNC3C3NNNN/NNNNN
211.20.340.00, SNO2NN/4,0R503CHNNF4F4NNNN/NNNNN
211.20.308.00, SNO2NN/4,0RN03CHNNB6B5NNNN/NNNNN
211.20.410.00, SNO2NN/4,0RN03CHNNC3C3NNNN/NNNNN
211.20.797.00, SNO2NN/4,0RN03CHNNF4F4NNNN/NNNNN
211.20.074.00, SNO2NN/6,0LN03CHNNB6B5NNNN/NNNNN
211.20.262.00, SNO2NN/6,0LN03CHNNC3C3NNNN/NNNNN
211.20.114.00, SNO2NN/6,0LN03CHNNE6E5NNNN/NNNNN
211.20.485.00, SNO2NN/6,0R103CINNB6B5ZZNN/NNNNN
211.20.349.00, SNO2NN/6,0R503CHNNC3C3NNNN/NNNNN
83021275, SNO2NN/6,0R503CHNNF4F4NNNN/NNNNA
211.20.380.00, SNO2NN/6,0R503CHNNF4F4NNNN/NNNNN

211.20.188.00, SNO2NN/6,0RN03CHNNB6B5NNNN/NNNNN
211.20.261.00, SNO2NN/6,0RN03CHNNC3C3NNNN/NNNNN
83008741, SNO2NN/6,0RN03CHNNE6E5NNNN/NNNNN
211.20.292.00, SNO2NN/6,0RN03CHNNF4F4NNNN/NNNNN
211.20.216.00, SNO2NN/6,0RN03CHNNMBMBNNNN/NNNNN
211.20.577.00, SNO2NN/8,0LN03CHNNC3C3NNNN/NNNNN
211.20.408.00, SNO2NN/8,0LN03CHNNB7B5NNNN/NNNNN
211.20.264.00, SNO2NN/8,0LN03CHNNC3C3NNNN/NNNNN
83015185, SNO2NN/8,0LN03CHNNE6E5NNNN/NNNNN
211.20.824.00, SNO2NN/8,0R503CHNNB7B5NNNN/NNNNN
211.20.430.00, SNO2NN/8,0R503CHNNC3C3NNNN/NNNNN
211.20.873.00, SNO2NN/8,0R503CHNNE6E5NNNN/NNNNN
211.20.426.00, SNO2NN/8,0R503CHNNF4F4NNNN/NNNNN
211.20.386.00, SNO2NN/8,0RN03CHNNB7B5NNNN/NNNNN
211.20.693.00, SNO2NN/8,0RN03CHNNB7B5NNNN/NNNNN
211.20.263.00, SNO2NN/8,0RN03CHNNC3C3NNNN/NNNNN
211.20.745.00, SNO2NN/8,0RN03CHNNE6E5NNNN/NNNNN
211.20.339.00, SNO2NN/8,0RN03CHNNF4F4NNNN/NNNNN
211.25.174.00, SNO3NN/022BN11DMNNA3A2NNNN/NNNNN
211.25.114.00, SNO3NN/022BN11DMNNC7C7NNNN/NNNNN
211.25.359.00, SNO3NN/022BN11DMNNCAC7NNNN/NNNNN
83013397, SNO3NN/022BN11DMNNE8E6NNNN/NNNNN
211.25.159.00, SNO3NN/022BN11DMNNF5F5NNNN/NNNNN
211.25.415.00, SNO3NN/022BN11DMNNF6F5NNNN/NNNNN
211.25.046.0A, SNO3NN/022LN11DMNNBBBANNNN/NNNNN
211.25.046.0C, SNO3NN/022RN11DMNNBBBANNNN/NNNNN
211.25.175.00, SNO3NN/026BN11DMNNA3A2NNNN/NNNNN
211.25.115.00, SNO3NN/026BN11DMNNC7C7NNNN/NNNNN
83018393, SNO3NN/026BN11DMNNCAC7NNNN/NNNNN
211.25.456.00, SNO3NN/026BN11DMNNE8E6NNNN/NNNNN
211.25.160.00, SNO3NN/026BN11DMNNF5F5NNNN/NNNNN
211.25.091.00, SNO3NN/026BN11DMNNMFMFNNNN/NNNNN
211.25.047.0A, SNO3NN/026LN11DMNNBBBANNNN/NNNNN
211.25.047.0C, SNO3NN/026RN11DMNNBBBANNNN/NNNNN
211.25.176.00, SNO3NN/033BN11DMNNA4A3NNNN/NNNNN
211.25.116.00, SNO3NN/033BN11DMNNCAC7NNNN/NNNNN
83009144, SNO3NN/033BN11DMNNE9E8NNNN/NNNNN
211.25.161.00, SNO3NN/033BN11DMNNF6F5NNNN/NNNNN
11046973, SNO3NN/033BN11DMNNM6M5NNNN/NNNNN
211.25.048.0A, SNO3NN/033LN11DMNNBBBANNNN/NNNNN
211.25.048.0C, SNO3NN/033RN11DMNNBBBANNNN/NNNNN
83017358, SNO3NN/038BN11DMNNA4A3NNNB/NNNNN
211.25.177.00, SNO3NN/038BN11DMNNA4A3NNNN/NNNNN
83014877, SNO3NN/038BN11DMNNA4A4NNNN/NNNNN
211.25.117.00, SNO3NN/038BN11DMNNCAC7NNNN/NNNNN
211.25.162.00, SNO3NN/038BN11DMNNF6F5NNNN/NNNNN
83019214, SNO3NN/038LN11DMNNBBBANNNN/NNNNN
211.25.049.0C, SNO3NN/038RN11DMNNBBBANNNN/NNNNN
211.25.178.00, SNO3NN/044BN11DMNNA4A3NNNN/NNNNN
211.25.118.00, SNO3NN/044BN11DMNNCACANNNN/NNNNN

211.25.163.00, SNO3NN/044BN11DMNNF6F6NNNN/NNNNN
83018504, SNO3NN/044LN11DMNNBBBANNNN/NNNNN
211.25.050.00, SNO3NN/044RN11DMNNBBBANNNN/NNNNN
211.25.179.00, SNO3NN/048BN11DMNNA4A3NNNN/NNNNN
211.25.119.00, SNO3NN/048BN11DMNNCACANNNN/NNNNN
211.25.164.00, SNO3NN/048BN11DMNNF6F6NNNN/NNNNN
211.25.180.00, SNO3NN/055BN11DMNNA5A4NNNN/NNNNN
211.25.120.00, SNO3NN/055BN11DMNNCACANNNN/NNNNN
211.25.165.00, SNO3NN/055BN11DMNNF6F6NNNN/NNNNN
211.25.181.00, SNO3NN/063BN11DMNNA5A4NNNN/NNNNN
211.25.121.00, SNO3NN/063BN11DMNNCDCANNNN/NNNNN
211.25.166.00, SNO3NN/063BN11DMNNF7F6NNNN/NNNNN
211.25.182.00, SNO3NN/075BN11DMNNA5A4NNNN/NNNNN
211.25.122.00, SNO3NN/075BN11DMNNCDCANNNN/NNNNN
211.25.167.00, SNO3NN/075BN11DMNNF7F6NNNN/NNNNN
211.25.123.00, SNO3NN/090BN11DMNNCDCANNNN/NNNNN
211.10.119.00, SNP1/7,8 S SC11 MDX_E
11062814, SNP1IN/1,2RN01BAI1C2C2NNNN/VGQNN
111.10.249.00, SNP1IN/1,2RN01BAI1F3F3NNBN/NNNNN
111.10.242.00, SNP1IN/1,2RN01BAI1F3F3NNBN/VAANN
83006767, SNP1IN/1,2RN01DAI1C2C2NNNN/VGXNN
111.10.246.00, SNP1IN/1,7RN01BAI1F3F3NNNN/VGDNN
111.10.199.00, SNP1IN/1,7RN01DAI1F3F3NNNN/VGPNN
11062180, SNP1IN/2,2LN01DAI1C2C2NNNN/VGXNN
11035636, SNP1IN/2,2LN03CAI3D5D3SAAN/VLXNN
11038029, SNP1IN/2,2RN01BAI1B2B1NNNN/HAANN
83014385, SNP1IN/2,2RN01BAI1F3F3NNNN/VNZNN
111.10.245.00, SNP1IN/2,6RN01BAI1F3F3NNBN/VAANN
111.10.130.00, SNP1IN/2,6RN01BAI1F3F3NNNN/VGDNN
111.10.001.00, SNP1IN/3,8LN03CAI3E4E3SAAN/VFQNN
11029265, SNP1IN/4,3RN01BAI1C2C2NNNN/VGUNN
83009020, SNP1IN/4,3RN01BAI1F3F3NNNN/VNQNN
111.10.241.00, SNP1IN/6,0RN01BAI1C2C2NNNN/VLTNN
83016216, SNP1IN/7,8RN01BAI1F3F3NNNN/VMSNN
83013110, SNP1IN/7,8RN01DAI1C2C2NNNN/VGNNN
111.10.131.00, SNP1IN/7,8RN01DAI1C2C2NNNN/VGUNN
111.10.069.00, SNP1NN/1,2LN01BAP1B2B1NNNN/NNNNN
83016430, SNP1NN/1,2LN01BAP1C2C2NNBN/NNNNN
111.10.003.00, SNP1NN/1,2LN01BAP1C2C2NNNN/NNNNN
111.10.233.00, SNP1NN/1,2LN01BAP1F3F3NNNB/NNNNN
111.10.021.00, SNP1NN/1,2LN01BAP1F3F3NNNN/NNNNN
111.10.041.00, SNP1NN/1,2LN01BAP1F4F3NNNN/NNNNN
111.10.090.00, SNP1NN/1,2LN01DAP1C2C2NNNN/NNNNN
111.10.108.00, SNP1NN/1,2LN01DAP1F3F3NNNN/NNNNN
111.10.086.00, SNP1NN/1,2LN03CA03F4F3NNAN/NNNNN
83012336, SNP1NN/1,2LN03CA03F4F3NNNB/NNNNN
83014493, SNP1NN/1,2LN03CM03F4F3NNNB/NNNNN
111.10.068.00, SNP1NN/1,2RN01BAP1B2B1NNNN/NNNNN
111.10.236.00, SNP1NN/1,2RN01BAP1C2C2NNNB/NNNNN
111.10.002.00, SNP1NN/1,2RN01BAP1C2C2NNNN/NNNNN

111.10.221.00, SNP1NN/1,2RN01BAP1C3C3NNNN/NNNNN
111.10.210.00, SNP1NN/1,2RN01BAP1D5D5NNNN/NNNNN
111.10.248.00, SNP1NN/1,2RN01BAP1F3F3NNBN/NNNNN
111.10.020.00, SNP1NN/1,2RN01BAP1F3F3NNNN/NNNNN
111.10.217.00, SNP1NN/1,2RN01DAP1B2B1NNNN/NNNNN
111.10.089.00, SNP1NN/1,2RN01DAP1C2C2NNNN/NNNNN
111.10.132.00, SNP1NN/1,2RN01DAP1E4E3NNNN/NNNNN
111.10.107.00, SNP1NN/1,2RN01DAP1F3F3NNNN/NNNNN
83018293, SNP1NN/1,2RN03CA03D5D5NNNN/NNNNN
111.10.071.00, SNP1NN/1,7LN01BAP1B2B1NNNN/NNNNN
111.10.005.00, SNP1NN/1,7LN01BAP1C2C2NNNN/NNNNN
111.10.244.00, SNP1NN/1,7LN01BAP1C3C3NNNN/NNNNN
111.10.220.00, SNP1NN/1,7LN01BAP1D5D5NNNN/NNNNN
111.10.239.00, SNP1NN/1,7LN01BAP1F3F3NNNB/NNNNN
111.10.023.00, SNP1NN/1,7LN01BAP1F3F3NNNN/NNNNN
111.10.044.00, SNP1NN/1,7LN01BAP1F4F3NNNN/NNNNN
111.10.092.00, SNP1NN/1,7LN01DAP1C2C2NNNN/NNNNN
83007015, SNP1NN/1,7LN01DAP1E4E3NNNN/NNNNN
83007183, SNP1NN/1,7LN01DAP1F3F3NNNN/NNNNN
111.10.049.00, SNP1NN/1,7LN03CA03D5D3NNAN/NNNNN
83007640, SNP1NN/1,7LN03CA03D5D3NNNN/NNNNN
111.10.215.00, SNP1NN/1,7LN03CA03F3F3NNNN/NNNNN
111.10.212.00, SNP1NN/1,7RN01BAP1B2B1NNBN/NNNNN
111.10.070.00, SNP1NN/1,7RN01BAP1B2B1NNNN/NNNNN
111.10.004.00, SNP1NN/1,7RN01BAP1C2C2NNNN/NNNNN
111.10.243.00, SNP1NN/1,7RN01BAP1C3C3NNNN/NNNNN
111.10.211.00, SNP1NN/1,7RN01BAP1F3F3NNBN/NNNNN
111.10.022.00, SNP1NN/1,7RN01BAP1F3F3NNNN/NNNNN
111.10.045.00, SNP1NN/1,7RN01BAP1F4F4NNNN/NNNNN
111.10.091.00, SNP1NN/1,7RN01DAP1C2C2NNNN/NNNNN
111.10.109.00, SNP1NN/1,7RN01DAP1F3F3NNNN/NNNNN
111.10.185.00, SNP1NN/1,7RN03CA03D5D3NNNN/NNNNN
111.10.186.00, SNP1NN/1,7RN03CA03F3F3NNNN/NNNNN
111.10.073.00, SNP1NN/2,2LN01BAP1B2B1NNNN/NNNNN
83014064, SNP1NN/2,2LN01BAP1C2C2NNBN/NNNNN
111.10.007.00, SNP1NN/2,2LN01BAP1C2C2NNNN/NNNNN
111.10.227.00, SNP1NN/2,2LN01BAP1C3C3NNNN/NNNNN
111.10.234.00, SNP1NN/2,2LN01BAP1F3F3NNNB/NNNNN
111.10.025.00, SNP1NN/2,2LN01BAP1F3F3NNNN/NNNNN
111.10.198.00, SNP1NN/2,2LN01BAP1F3F3NNNN/NNNNN
83009560, SNP1NN/2,2LN01DAP1B2B1NNNN/NNNNN
111.10.094.00, SNP1NN/2,2LN01DAP1C2C2NNNN/NNNNN
111.10.159.00, SNP1NN/2,2LN03CA03B2B1NNNN/NNNNN
111.10.065.00, SNP1NN/2,2LN03CA03C2C2SAAN/NNNNN
111.10.051.00, SNP1NN/2,2LN03CA03D5D3NNAN/NNNNN
111.10.216.00, SNP1NN/2,2LN03CA03F3F3NNNN/NNNNN
111.10.087.00, SNP1NN/2,2LN03CA03F4F3NNAN/NNNNN
111.10.207.00, SNP1NN/2,2LN04AA03D5D3SANN/NNNNN
111.10.072.00, SNP1NN/2,2RN01BAP1B2B1NNNN/NNNNN
111.10.006.00, SNP1NN/2,2RN01BAP1C2C2NNNN/NNNNN

111.10.222.00, SNP1NN/2,2RN01BAP1C3C3NNNN/NNNN
111.10.253.00, SNP1NN/2,2RN01BAP1F3F3NNBN/NNNN
111.10.024.00, SNP1NN/2,2RN01BAP1F3F3NNNN/NNNN
83006827, SNP1NN/2,2RN01DAP1B2B1NNNN/NNNN
111.10.093.00, SNP1NN/2,2RN01DAP1C2C2NNNN/NNNN
111.10.214.00, SNP1NN/2,2RN01DAP1D5D3NNNN/NNNN
111.10.136.00, SNP1NN/2,2RN01DAP1E4E3NNNN/NNNN
111.10.111.00, SNP1NN/2,2RN01DAP1F3F3NNNN/NNNN
111.10.158.00, SNP1NN/2,2RN03CA03B2B1NNNN/NNNN
111.10.187.00, SNP1NN/2,2RN03CA03D5D3NNNN/NNNN
111.10.183.00, SNP1NN/2,2RN03CA03F3F3NNNN/NNNN
111.10.075.00, SNP1NN/2,6LN01BAP1B2B1NNNN/NNNN
111.10.009.00, SNP1NN/2,6LN01BAP1C2C2NNNN/NNNN
111.10.251.00, SNP1NN/2,6LN01BAP1C3C3NNNN/NNNN
111.10.200.00, SNP1NN/2,6LN01BAP1D5D5NNNN/NNNN
111.10.027.00, SNP1NN/2,6LN01BAP1F3F3NNNN/NNNN
111.10.042.00, SNP1NN/2,6LN01BAP1F4F3NNNN/NNNN
111.10.096.00, SNP1NN/2,6LN01DAP1C2C2NNNN/NNNN
11044406, SNP1NN/2,6LN01DAP1E4E3NNNN/NNNN
111.10.114.00, SNP1NN/2,6LN01DAP1F3F3NNNN/NNNN
111.10.053.00, SNP1NN/2,6LN03CA03D5D3NNAN/NNNN
111.10.152.00, SNP1NN/2,6LN03CA03F3F3NNNN/NNNN
111.10.074.00, SNP1NN/2,6RN01BAP1B2B1NNNN/NNNN
11045111, SNP1NN/2,6RN01BAP1C2C2NNBN/NNNN
111.10.008.00, SNP1NN/2,6RN01BAP1C2C2NNNN/NNNN
111.10.250.00, SNP1NN/2,6RN01BAP1C3C3NNNN/NNNN
111.10.182.00, SNP1NN/2,6RN01BAP1F3F3NNBN/NNNN
111.10.026.00, SNP1NN/2,6RN01BAP1F3F3NNNN/NNNN
111.10.161.00, SNP1NN/2,6RN01CFP1F3F3NNNN/NNNN
111.10.095.00, SNP1NN/2,6RN01DAP1C2C2NNNN/NNNN
11044347, SNP1NN/2,6RN01DAP1E4E3NNNN/NNNN
111.10.113.00, SNP1NN/2,6RN01DAP1F3F3NNNN/NNNN
83016904, SNP1NN/2,6RN01DAP1F4F3NNNN/NNNN
111.10.184.00, SNP1NN/2,6RN03CA03D5D3NNNN/NNNN
111.10.151.00, SNP1NN/2,6RN03CA03F3F3NNNN/NNNN
111.10.077.00, SNP1NN/3,2LN01BAP1B2B1NNNN/NNNN
111.10.011.00, SNP1NN/3,2LN01BAP1C2C2NNNN/NNNN
111.10.228.00, SNP1NN/3,2LN01BAP1C3C3NNNN/NNNN
111.10.029.00, SNP1NN/3,2LN01BAP1F3F3NNNN/NNNN
111.10.209.00, SNP1NN/3,2LN01DAP1B2B1NNNN/NNNN
111.10.098.00, SNP1NN/3,2LN01DAP1C2C2NNNN/NNNN
111.10.141.00, SNP1NN/3,2LN01DAP1E4E3NNNN/NNNN
111.10.116.00, SNP1NN/3,2LN01DAP1F3F3NNNN/NNNN
83009710, SNP1NN/3,2LN03CA03C2C2SAAN/NNNN
111.10.055.00, SNP1NN/3,2LN03CA03D5D3NNAN/NNNN
111.10.064.00, SNP1NN/3,2LN03CA03D5D5NNAN/NNNN
111.10.153.00, SNP1NN/3,2LN03CA03F3F3NNNN/NNNN
111.10.076.00, SNP1NN/3,2RN01BAP1B2B1NNNN/NNNN
11045123, SNP1NN/3,2RN01BAP1C2C2NNBN/NNNN
111.10.010.00, SNP1NN/3,2RN01BAP1C2C2NNNN/NNNN

111.10.223.00, SNP1NN/3,2RN01BAP1C3C3NNNN/NNNNN
111.10.213.00, SNP1NN/3,2RN01BAP1F3F3NNBN/NNNNN
111.10.028.00, SNP1NN/3,2RN01BAP1F3F3NNNN/NNNNN
111.10.097.00, SNP1NN/3,2RN01DAP1C2C2NNNN/NNNNN
111.10.115.00, SNP1NN/3,2RN01DAP1F3F3NNNN/NNNNN
111.10.126.00, SNP1NN/3,2RN03CA03F3F3NNAN/NNNNN
111.10.202.00, SNP1NN/3,2RN03CA03F3F3NNNN/NNNNN
111.10.079.00, SNP1NN/3,8LN01BAP1B2B1NNNN/NNNNN
111.10.013.00, SNP1NN/3,8LN01BAP1C2C2NNNN/NNNNN
111.10.013.00-OL, SNP1NN/3,8LN01BAP1C2C2NNNN/NNNNN
111.10.229.00, SNP1NN/3,8LN01BAP1C3C3NNNN/NNNNN
111.10.031.00, SNP1NN/3,8LN01BAP1F3F3NNNN/NNNNN
111.10.100.00, SNP1NN/3,8LN01DAP1C2C2NNNN/NNNNN
111.10.100.00-OL, SNP1NN/3,8LN01DAP1C2C2NNNN/NNNNN
83020579, SNP1NN/3,8LN03CA03B2B1SANN/NNNNN
111.10.066.00, SNP1NN/3,8LN03CA03D5D3NNAN/NNNNN
111.10.057.00, SNP1NN/3,8LN03CA03D5D5NNAN/NNNNN
111.10.160.00, SNP1NN/3,8LN03CA03D5D5NNNN/NNNNN
111.10.154.00, SNP1NN/3,8LN03CA03F3F3NNNN/NNNNN
111.10.078.00, SNP1NN/3,8RN01BAP1B2B1NNNN/NNNNN
111.10.237.00, SNP1NN/3,8RN01BAP1C2C2NNNB/NNNNN
111.10.012.00, SNP1NN/3,8RN01BAP1C2C2NNNN/NNNNN
111.10.224.00, SNP1NN/3,8RN01BAP1C3C3NNNN/NNNNN
83015131, SNP1NN/3,8RN01BAP1D5D5NNNN/NNNNN
111.10.030.00, SNP1NN/3,8RN01BAP1F3F3NNNN/NNNNN
111.10.247.00, SNP1NN/3,8RN01BAP1F3F3NNNN/NNNNN
111.10.099.00, SNP1NN/3,8RN01DAP1C2C2NNNN/NNNNN
111.10.117.00, SNP1NN/3,8RN01DAP1F3F3NNNN/NNNNN
111.10.201.00, SNP1NN/3,8RN03CA03D5D3NNNN/NNNNN
111.10.188.00, SNP1NN/3,8RN03CA03D5D5NNNN/NNNNN
111.10.203.00, SNP1NN/3,8RN03CA03F3F3NNNN/NNNNN
83018490, SNP1NN/4,3LN01BAP1B2B1NNBN/NNNNN
111.10.081.00, SNP1NN/4,3LN01BAP1B2B1NNNN/NNNNN
111.10.015.00, SNP1NN/4,3LN01BAP1C2C2NNNN/NNNNN
111.10.230.00, SNP1NN/4,3LN01BAP1C3C3NNNN/NNNNN
111.10.033.00, SNP1NN/4,3LN01BAP1F3F3NNNN/NNNNN
111.10.102.00, SNP1NN/4,3LN01DAP1C2C2NNNN/NNNNN
111.10.232.00, SNP1NN/4,3LN01DAP1C3C3NNNN/NNNNN
111.10.145.00, SNP1NN/4,3LN01DAP1E4E3NNNN/NNNNN
111.10.120.00, SNP1NN/4,3LN01DAP1F3F3NNNN/NNNNN
111.10.181.00, SNP1NN/4,3LN01DCP1F3F3NNNB/NNNNN
11050998, SNP1NN/4,3LN03CA03D5D5NNAN/NNNNN
111.10.059.00, SNP1NN/4,3LN03CA03D5D5NNAN/NNNNN
111.10.155.00, SNP1NN/4,3LN03CA03F3F3NNNN/NNNNN
111.10.080.00, SNP1NN/4,3RN01BAP1B2B1NNNN/NNNNN
111.10.014.00, SNP1NN/4,3RN01BAP1C2C2NNNN/NNNNN
111.10.252.00, SNP1NN/4,3RN01BAP1C3C3NNNN/NNNNN
111.10.032.00, SNP1NN/4,3RN01BAP1F3F3NNNN/NNNNN
83018983, SNP1NN/4,3RN01DAP1B2B1NNNB/NNNNN
111.10.208.00, SNP1NN/4,3RN01DAP1B2B1NNNN/NNNNN

111.10.101.00, SNP1NN/4,3RN01DAP1C2C2NNNN/NNNNN
111.10.144.00, SNP1NN/4,3RN01DAP1E4E3NNNN/NNNNN
111.10.119.00, SNP1NN/4,3RN01DAP1F3F3NNNN/NNNNN
111.10.127.00, SNP1NN/4,3RN03CA03F3F3NNAN/NNNNN
111.10.204.00, SNP1NN/4,3RN03CA03F3F3NNNN/NNNNN
111.10.083.00, SNP1NN/6,0LN01BAP1B2B2NNNN/NNNNN
111.10.017.00, SNP1NN/6,0LN01BAP1C2C2NNNN/NNNNN
111.10.128.00, SNP1NN/6,0LN01BAP1C3C3DFNB/NNNNN
111.10.035.00, SNP1NN/6,0LN01BAP1F3F3NNNN/NNNNN
111.10.104.00, SNP1NN/6,0LN01DAP1C2C2NNNN/NNNNN
111.10.156.00, SNP1NN/6,0LN03CA03F3F3NNNN/NNNNN
111.10.082.00, SNP1NN/6,0RN01BAP1B2B2NNNN/NNNNN
11044227, SNP1NN/6,0RN01BAP1C2C2NNBN/NNNNN
111.10.016.00, SNP1NN/6,0RN01BAP1C2C2NNNN/NNNNN
111.10.180.00, SNP1NN/6,0RN01BAP1C3C3DFNB/NNNNN
111.10.225.00, SNP1NN/6,0RN01BAP1C3C3NNNN/NNNNN
111.10.034.00, SNP1NN/6,0RN01BAP1F3F3NNNN/NNNNN
111.10.125.00, SNP1NN/6,0RN01BAP1F4F4NNNN/NNNNN
111.10.103.00, SNP1NN/6,0RN01DAP1C2C2NNNN/NNNNN
111.10.121.00, SNP1NN/6,0RN01DAP1F3F3NNNN/NNNNN
111.10.150.00, SNP1NN/6,0RN01DAP1F4F4NNNN/NNNNN
111.10.205.00, SNP1NN/6,0RN03CA03F3F3NNNN/NNNNN
83009155, SNP1NN/6,5RN01BAP1F3F3NNNN/NNNNN
111.10.085.00, SNP1NN/7,8LN01BAP1B2B2NNNN/NNNNN
111.10.238.00, SNP1NN/7,8LN01BAP1C2C2NNNB/NNNNN
111.10.019.00, SNP1NN/7,8LN01BAP1C2C2NNNN/NNNNN
111.10.129.00, SNP1NN/7,8LN01BAP1C3C3DFNB/NNNNN
111.10.231.00, SNP1NN/7,8LN01BAP1C3C3NNNN/NNNNN
111.10.235.00, SNP1NN/7,8LN01BAP1F3F3NNNB/NNNNN
111.10.037.00, SNP1NN/7,8LN01BAP1F3F3NNNN/NNNNN
111.10.106.00, SNP1NN/7,8LN01DAP1C2C2NNNN/NNNNN
111.10.218.00, SNP1NN/7,8LN01DCP1D7D5NNNB/NNNNN
111.10.157.00, SNP1NN/7,8LN03CA03F3F3NNNN/NNNNN
111.10.084.00, SNP1NN/7,8RN01BAP1B2B2NNNN/NNNNN
111.10.240.00, SNP1NN/7,8RN01BAP1C2C2NNNB/NNNNN
111.10.018.00, SNP1NN/7,8RN01BAP1C2C2NNNN/NNNNN
111.10.226.00, SNP1NN/7,8RN01BAP1C3C3NNNN/NNNNN
111.10.036.00, SNP1NN/7,8RN01BAP1F3F3NNNN/NNNNN
111.10.105.00, SNP1NN/7,8RN01DAP1C2C2NNNN/NNNNN
111.10.123.00, SNP1NN/7,8RN01DAP1F3F3NNNN/NNNNN
83012248, SNP1NN/7,8RN03CA03D5D3NNNN/NNNNN
111.10.206.00, SNP1NN/7,8RN03CA03F3F3NNNN/NNNNN
11092183, SNP2/ 8 D CO02 RRU_B
11125910, SNP2/ 8 D CO06 RPV_B
111.20.692.00, SNP2/ 8 D SC02 RRU_B
11097622, SNP2/11 D CI06 MIN_
111.20.A61.00, SNP2/11 D CO91 MHZ_
111.20.A60.00, SNP2/11 D SC03 MHY_C
111.20.B56.00, SNP2/11 S FR03 MKR_
111.20.C51.00, SNP2/11 S SC06 MNR_G

11031118, SNP2/11 S SC1C ...4F
11072340, SNP2/12 D SC46 +++4.
111.20.B55.00, SNP2/14 D SC06 MKP_G
211.20.635.00, SNP2/14 D SC1C ...4E
211.20.602.00, SNP2/14 D SC1C ...4F
11120089, SNP2/14 D SC46 ...4.
211.20.701.00, SNP2/14 D SC7C DVX4G
211.20.686.00, SNP2/14 S SC1C ...4E
11097333, SNP2/17 D ..43 MDD_E
111.20.995.00, SNP2/17 D CO01 MHQ1E
211.20.646.00, SNP2/17 D SC46 BNB_.
211.20.720.00, SNP2/17 D SC46 DPE4.
11111025, SNP2/17 S SC06 +++_.
11077169, SNP2/17 S SC06 +++_C
211.20.877.00, SNP2/17 S SC1C ...4F
211.20.639.00, SNP2/19 D ..43 MDD_C
211.20.685.00, SNP2/19 D ..43 MFX_C
11086357, SNP2/19 S SC1C ...4E
111.20.C52.00, SNP2/22 S SC06 MNR_G
11038234, SNP2/25 D SC06 +++4B
111.20.B54.00, SNP2/25 D SC06 MKP_G
11097780, SNP2/33 D SC06 +++4A
11038712, SNP2/33 D SC06 +++4B
11091234, SNP2/33 S FR03 DCM_B
111.20.985.00, SNP2/4 D SC06 MGD_.
111.20.991.00, SNP2/6 D FR03 MDS_E
111.20.A20.00, SNP2/6 D SC06 MGD_.
211.20.609.00, SNP2/6 D SC1C ...4F
211.20.744.00, SNP2/6 D SC46 ...4.
111.20.930.00, SNP2/7 D CO02 RZS_F
211.20.674.00, SNP2/7 D CO42 ...4.
11074202, SNP2/8 D ..43 MFX_G
111.20.A79.00, SNP2/8 D CO01 MIN1.
11076183, SNP2/8 D SC06 +++_.
211.20.652.00, SNP2/8 D SC46 ...4.
11071103, SNP2/8 D SC46 DUY4.
11040798, SNP2/8,7 D FR03 +++_F
111.20.A12.00, SNP2/8,7 D SC06 MFR_F
111.20.A81.00, SNP2/9,5 D CO02 MGT_B
111.20.821.00, SNP2EN/011L601B1E2C3C3NNNN/VGPNN
111.20.821.00-0L, SNP2EN/011L601B1E2C3C3NNNN/VGPNN
111.20.822.00, SNP2EN/011L601B1E2C3C3NNNN/VGRNN
111.20.822.00-0L, SNP2EN/011L601B1E2C3C3NNNN/VGRNN
83012003, SNP2EN/011LN03CAE4E6E5NNNN/VIWNN
111.20.C43.00, SNP2EN/011LN06SAE6E6E5NNNN/VCECN
111.20.A33.00, SNP2EN/011LN06SAE6E6E5NNNN/VIGNN
111.20.909.00, SNP2EN/011LNB1DGE1F5F3NNNA/VKUNN
111.20.A40.00, SNP2EN/011RN03CAE4E6E5NNNN/VIUNN
11034700, SNP2EN/011RN03CAE4E6E5NNNN/VIWNN
11120911, SNP2EN/011RN06GAE1F4F4NNNA/VGTNN

111.20.A39.00, SNP2EN/011RN06SAE6E6E5NNNN/VIGNN
111.20.A76.00, SNP2EN/011RN06SAE6E6E5NNNN/VLXNN
111.20.A93.00, SNP2EN/012RN06SAE6E6E5NNNN/VLXNN
11046413, SNP2EN/014LN01BBE1F5F3NNBA/VIWNN
111.20.824.00, SNP2EN/014LN01DAE1F5F3NNBA/VIWNN
11120921, SNP2EN/014RN06GAE1F4F4NNNA/VGTNN
11057607, SNP2EN/014RN06SAE1F5F4NNNN/VIWNN
111.20.880.00, SNP2EN/017LN01BBE1F5F3NNNA/VKWNN
83010290, SNP2EN/017LN01DAE1F5F3NNNA/VISNN
111.20.977.00, SNP2EN/017LN06SAE6E6E5NNNN/VLXNN
83015170, SNP2EN/017RN06SAE1F5F4NNNN/VGDNN
11043121, SNP2EN/017RN06SAE6E6E5NNNN/VGPNN
83007939, SNP2EN/019LN06SAE1C7C3NNNN/VIXNN
111.20.A86.00, SNP2EN/019LN06SAE6E6E5NNNN/VGUNN
111.20.A57.00, SNP2EN/019RN06SAE6E6E5NNNN/VGUNN
11032383, SNP2EN/022RN06SAE6E6E5NNNN/VGPNN
111.20.749.00, SNP2EN/025RN01BAE1C8C7NNNN/VGTNN
111.20.A48.00, SNP2EN/025RN06SAE6E6E5NNNN/VGUNN
111.20.698.00, SNP2EN/4,0RN03CAE3B6B5NNNN/VICNN
11045280, SNP2EN/4,0RN06SAE1F4F4NNNN/VIPNN
83007940, SNP2EN/6,0LN06SAE6E6E5NNNN/VGPNN
83013740, SNP2EN/6,0RN01DAE1C3C3NNNN/VOXNN
83013491, SNP2EN/6,0RN06GAE1F4F4NNNN/VGXNN
11037122, SNP2EN/6,0RN06SAE6E6E5NNNN/VGPNN
83019004, SNP2EN/8,0RN06GAE1F4F4NNNA/VGXNN
111.20.B35.00, SNP2IN/011LN01BAI1C3C3NNNN/VIQNN
111.20.960.00, SNP2IN/011LN01BAI1C3C3NNNN/VKRNN
111.20.C64.00, SNP2IN/011LN01BAI1C3C3NNNN/VMWNN
111.20.B80.00, SNP2IN/011LN03CAI3B7B5NNNN/VGWNN
111.20.B52.00, SNP2IN/011LN03CAI3B7B5NNNN/VIPNN
111.20.C48.00, SNP2IN/011LN03CAI3B7B5NNNN/VLJNN
111.20.C26.00, SNP2IN/011LN04AAI1E6E5NNNN/VGUNN
111.20.C42.00, SNP2IN/011LN04DBI1E6E5NNNN/VGVNN
83015773, SNP2IN/011LN06SAI1E8E6NNBN/VOCNN
111.20.714.00, SNP2IN/011RN01BAI1C3C3NNNN/VGPNN
111.20.B97.00, SNP2IN/011RN01BAI1C3C3NNNN/VKWNN
11041945, SNP2IN/011RN01BAI1F5F4NNNN/VGFNN
111.20.B89.00, SNP2IN/011RN01BAI1F5F4NNNN/VMFNN
111.20.646.00, SNP2IN/011RN02DBI1B7B5NNNN/VGZNN
111.20.B41.00, SNP2IN/011RN03CAI3B7B5NNNN/VLWNN
111.20.691.00, SNP2IN/011RN03CAI3C3C3NNNN/VGPNN
83017429, SNP2IN/011RN06GAI1E6E5NNNN/VJWNN
83015772, SNP2IN/011RN06SAI1E8E6NNBN/VOCNN
111.20.A38.00, SNP2IN/011RN06SAI1F5F4NNNN/VGUNN
83015432, SNP2IN/011RN06SAI1F5F4NNNN/VIYNN
111.20.904.00, SNP2IN/012RN02DBI1B7B5NNNN/VOVNN
111.20.851.00, SNP2IN/014LN01BAI1C7C3NNNN/VGXNN
111.20.966.00, SNP2IN/014LN03CAI3E6E5NNNN/VGXNN
111.20.934.00, SNP2IN/014LN06SAI1C7C3NNNN/VLWNN
111.20.982.00, SNP2IN/014LN06SAI1E6E5NNNN/VLTNN

111.20.862.00, SNP2IN/014RN01BAI1C7C3NNNN/VGMNN
111.20.669.00, SNP2IN/014RN01BAI1C7C3NNNN/VGXNN
111.20.C65.00, SNP2IN/014RN01BAI1C7C3NNNN/VMUNN
83018702, SNP2IN/014RN01BAI1F5F4NNNN/VGCNN
111.20.A53.00, SNP2IN/014RN01BAI1F5F4NNNN/VGDNN
111.20.B70.00, SNP2IN/014RN01DAI1B7B5NNNA/VLJNN
83007104, SNP2IN/014RN01DAI1F4F4NNNN/VIRNN
11030109, SNP2IN/014RN01FAI1E6E5NNNN/VGCNN
83019907, SNP2IN/014RN02AAI1B7B5NNNA/VLJNN
111.20.970.00, SNP2IN/014RN02DBI1B7B5NNNA/VGZNN
111.20.677.00, SNP2IN/014RN02DBI1B7B5NNNN/VGZNN
111.20.892.00, SNP2IN/014RN03CAI3C7C3NNNN/VLWNN
111.20.801.00, SNP2IN/014RN03CAI3F5F4NNNN/VIWNN
111.20.B36.00, SNP2IN/014RN05DBI1C7C3NNNN/VLXNN
83009561, SNP2IN/014RN06SAI1B7B5YYNN/VGXNN
11055391, SNP2IN/014RN06SAI1F4F4NNNN/VIRNN
11031909, SNP2IN/014RN06SAI1F5F4NNNN/VIWNN
111.20.B59.00, SNP2IN/014RNA6SAI1B7B5YYNN/VKUNN
111.20.A04.00, SNP2IN/017LN01BAI1C7C3NNNN/VKONN
11066754, SNP2IN/017LN01BBI1B7B5NNNN/VETNN
111.20.833.00, SNP2IN/017LN01DAI1C7C3NNNN/VLWNN
83020581, SNP2IN/017LN06SAI1E6E5NNNN/VGTNN
11066753, SNP2IN/017LN9MBBI1B7B5NNNN/VETNN
111.20.837.00, SNP2IN/017RN01BAI1C7C3NNNN/VGMNN
83010046, SNP2IN/017RN01BAI1C7C3NNNN/VKVNN
83010412, SNP2IN/017RN03CAI3F5F4NNNN/VGWNN
83020580, SNP2IN/017RN06SAI1E6E5NNNN/VGTNN
111.20.796.00, SNP2IN/019LN01BAI1C7C3NNNN/VGXNN
111.20.877.00, SNP2IN/019LN01DAI1C7C3NNNN/VLWNN
83013584, SNP2IN/019LN06SAI1C7C3NNNN/VIXNN
111.20.C18.00, SNP2IN/019RN01BAI1C7C3NNNN/VGMNN
11053638, SNP2IN/019RN01BAI1C7C3NNNN/VGUNN
111.20.556.00, SNP2IN/019RN01BAI1C7C3NNNN/VGWNN
111.20.C66.00, SNP2IN/019RN01BAI1C7C3NNNN/VMQNN
111.20.789.00, SNP2IN/019RN01BBI1F5F4NNNN/VKVNN
83009169, SNP2IN/019RN01DAI1E6E5NNNN/VLPNN
83010728, SNP2IN/019RN03CAI3F5F4NNNN/VGWNN
83021763, SNP2IN/019RN06SAI1E6E5NNNN/VKXNN
111.20.B67.00, SNP2IN/022LN02AAI1B7B5NNNN/VETNN
83008213, SNP2IN/022LN03CAI3B7B5NNNN/VGTNN
111.20.B78.00, SNP2IN/022LN04AAI1B7B5NNNN/VGUNN
111.20.A10.00, SNP2IN/022RN01BAI1C7C3NNNN/VGGNN
111.20.C19.00, SNP2IN/022RN01BAI1C7C3NNNN/VGMNN
111.20.910.00, SNP2IN/022RN01BAI1C7C3NNNN/VGRNN
111.20.B66.00, SNP2IN/022RN02AAI1B7B5NNNN/VETNN
83015161, SNP2IN/022RN03CAI3B7B5NNNN/VGTNN
111.20.A71.00, SNP2IN/022RN03CAI3C7C3NNNN/VGRNN
83019268, SNP2IN/022RN06SAI1B7B5YYNN/VKWNN
111.20.722.00, SNP2IN/025LN01BAI1C8C7NNNN/VGUNN
111.20.C69.00, SNP2IN/025LN03CAI3C8C7NNNN/VGGNN

83021698, SNP2IN/025LN06SAI1E6E5NNNN/VGMNN
111.20.C20.00, SNP2IN/025RN01BAI1C8C7NNNN/VGMNN
111.20.B06.00, SNP2IN/025RN01FAI1C8C7NNNN/VERNN
111.20.C68.00, SNP2IN/025RN03CAI3C8C7NNNN/VGGNN
83009671, SNP2IN/4,0LN01BAI1C3C3NNNN/VJXNN
83011074, SNP2IN/4,0LN01DAI1E6E5NNNN/VLONN
83019448, SNP2IN/4,0LN06SAI1E6E5NNNN/VKCNN
83021003, SNP2IN/4,0LN06SAI1E6E5NNNN/VKXNN
83021757, SNP2IN/4,0LN06SAI1E6E5NNNN/VKZNN
111.20.C03.00, SNP2IN/4,0RN01BAI1C3C3NNNN/VGMNN
83011039, SNP2IN/4,0RN01BAI1C3C3NNNN/VGXNN
83011038, SNP2IN/4,0RN06GAI1C3C3NNNN/VGXNN
111.20.B43.00, SNP2IN/4,0RN06GAI1F4F4NNNN/VLXNN
83017281, SNP2IN/4,0RN06SAI1E6E5NNNN/VNENN
11065905, SNP2IN/4,0RN06SAI1F4F4NNNN/VIANN
111.20.615.00, SNP2IN/6,0LN01BAI1C3C3NNNN/VIQNN
111.20.A15.00, SNP2IN/6,0LN03CAI3B6B5NNNN/VGJNN
111.20.B58.00, SNP2IN/6,0LN03CAI3B6B5NNNN/VGUNN
111.20.B72.00, SNP2IN/6,0LN06SAI1B7B5YYNN/VGUNN
11065504, SNP2IN/6,0LN06SAI1E6E5NNNN/VNCNN
111.20.A22.00, SNP2IN/6,0LNA4AAI1B6B5NNNN/VGPNN
111.20.B05.00, SNP2IN/6,0RN01BAI1C3C3NNNN/VGCNN
83022994, SNP2IN/6,0RN01BAI1F4F4NNBN/VGXNN
111.20.B88.00, SNP2IN/6,0RN01FAI1C3C3NNNN/VGPNN
111.20.A37.00, SNP2IN/6,0RN03CAI3B6B5NNNN/VKTNN
111.20.A24.00, SNP2IN/6,0RN03CAI3B6B5NNNN/VNPNN
111.20.951.00, SNP2IN/6,0RN03CAI3C3C3NNNN/VLWNN
111.20.B73.00, SNP2IN/6,0RN06GAI1E6E5NNNN/VITNN
11062164, SNP2IN/8,0LN03CAI3B7B5NNNN/VIPNN
11067201, SNP2IN/8,0LN06SAI1E6E5NNNN/VERNN
111.20.B27.00, SNP2IN/8,0RN03CAI3E6E4NNNN/VOENN
111.20.606.00, SNP2IN/8,0RN03CAI3E6E5NNNN/VGPNN
11045984, SNP2IN/8,0RN06SAI1E6E5NNNN/VERNN
83015430, SNP2IN/8,0RN06SAI1F4F4NNNN/VIYNN
111.20.B37.00, SNP2IN/8,0RNA6SAI1B7B5YYNN/VLWNN
111.20.B15.00, SNP2NN/011L603CDP3B7B5NNNN/NNNNN
11099709, SNP2NN/011L603CDP3CXH5C9NN/NNNNN
111.20.523.00, SNP2NN/011LN01B1P1C3C3NNNN/NNNNN
111.20.523.00-0L, SNP2NN/011LN01B1P1C3C3NNNN/NNNNN
111.20.378.00, SNP2NN/011LN01B1P1C7C5NNNN/NNNNN
111.20.378.00-0L, SNP2NN/011LN01B1P1C7C5NNNN/NNNNN
111.20.876.00, SNP2NN/011LN01BAP1B7B5ZZNN/NNNNN
111.20.C40.00, SNP2NN/011LN01BAP1B7B5ZZNN/NNNNN
111.20.A45.00, SNP2NN/011LN01BAP1C3C3D6NA/NNNNN
111.20.217.00, SNP2NN/011LN01BAP1C3C3NNNN/NNNNN
111.20.337.00, SNP2NN/011LN01BAP1C7C3NNNN/NNNNN
111.20.B64.00, SNP2NN/011LN01BAP1C7C7NNNN/NNNNN
111.20.279.00, SNP2NN/011LN01BAP1F5F4NNNN/NNNNN
111.20.664.00, SNP2NN/011LN01BBP1C3C3NNNN/NNNNN
111.20.817.00, SNP2NN/011LN01BBP1C7C3NNNN/NNNNN

111.20.956.00, SNP2NN/011LN01BBP1F4F4NNNN/NNNNN
111.20.B39.00, SNP2NN/011LN01BJP1C3C3NNNN/NNNNN
83017360, SNP2NN/011LN01DAP1B7B5NNNA/NNNNN
111.20.309.00, SNP2NN/011LN01DAP1B7B5NNNN/NNNNN
111.20.907.00, SNP2NN/011LN01DAP1B7B5ZZNN/NNNNN
111.20.261.00, SNP2NN/011LN01DAP1C3C3NNNN/NNNNN
111.20.428.00, SNP2NN/011LN01DAP1C7C3NNNN/NNNNN
111.20.376.00, SNP2NN/011LN01DAP1E6E5NNNN/NNNNN
111.20.B60.00, SNP2NN/011LN01DAP1E6E5NNNN/NNNZN
83014773, SNP2NN/011LN01DAP1F4F4NNNN/NNNNN
111.20.534.00, SNP2NN/011LN01DAP1F5F4NNNN/NNNNN
111.20.474.00, SNP2NN/011LN01FAP1C3C3NNNN/NNNNN
111.20.453.00, SNP2NN/011LN01FAP1F5F4NNNN/NNNNN
111.20.042.00, SNP2NN/011LN02AAP1B7B5NNNN/NNNNN
111.20.B69.00, SNP2NN/011LN02AAP1C3C3NNNN/NNNNN
111.20.065.00, SNP2NN/011LN02DBP1B7B5NNNN/NNNNN
111.20.942.00, SNP2NN/011LN02DBP1F5F4NNBA/NNNAN
111.20.079.00, SNP2NN/011LN03CAP3B7B5NNNN/NNNNN
111.20.744.00, SNP2NN/011LN03CAP3B7B5NNNN/NNNNN
83015714, SNP2NN/011LN03CAP3B7B5NNNN/NNNWN
83011065, SNP2NN/011LN03CAP3B7B5NNNN/NNNZN
111.20.303.00, SNP2NN/011LN03CAP3C3C3NNNN/NNNNN
111.20.455.00, SNP2NN/011LN03CAP3C7C3NNNN/NNNNN
111.20.425.00, SNP2NN/011LN03CAP3E6E5NNNN/NNNNN
111.20.688.00, SNP2NN/011LN03CAP3F5F4NNNN/NNNNN
111.20.805.00, SNP2NN/011LN03CMP3B7B5NNNN/NNNNN
83013048, SNP2NN/011LN04AAP1B7B5NNBN/NNNNN
11033085, SNP2NN/011LN04AAP1B7B5NNDN/NNNNN
111.20.097.00, SNP2NN/011LN04AAP1B7B5NNNN/NNNNN
111.20.593.00, SNP2NN/011LN04ABP1B7B5NNNN/NNNNN
111.20.987.00, SNP2NN/011LN04AMP1B7B5NNNN/NNNNN
111.20.639.00, SNP2NN/011LN04DBP1B7B5NNBN/NNNNN
111.20.414.00, SNP2NN/011LN04DBP1B7B5NNNN/NNNNN
83013304, SNP2NN/011LN04DBP1E6E5NNNN/NNNNN
111.20.231.00, SNP2NN/011LN05AAP1B7B5NNNN/NNNNN
83016289, SNP2NN/011LN06BAP1E6E5NNNN/NNNNN
83016453, SNP2NN/011LN06BBP1F5F4NNNN/NNNNN
111.20.244.00, SNP2NN/011LN06GAP1E6E5NNNN/NNNNN
111.20.624.00-02, SNP2NN/011LN06SAP1B7B5ELNN/NNNBN
111.20.594.00, SNP2NN/011LN06SAP1B7B5ELNN/NNNNN
111.20.149.00, SNP2NN/011LN06SAP1B7B5YYNN/NNNNN
83014149, SNP2NN/011LN06SAP1B7B5YYNN/NNNWN
111.20.A50.00, SNP2NN/011LN06SAP1B7B5ZZNA/NNNNN
111.20.670.00, SNP2NN/011LN06SAP1C3C3NNNN/NNNNN
11045753, SNP2NN/011LN06SAP1C7F4NNNN/NNNNN
83011981, SNP2NN/011LN06SAP1E6E5NNNA/NNNVN
111.20.978.00, SNP2NN/011LN06SAP1E6E5NNNN/NNNAN
111.20.131.00, SNP2NN/011LN06SAP1E6E5NNNN/NNNNN
83015155, SNP2NN/011LN06SAP1E6E5NNQN/NNNNN
111.20.741.00, SNP2NN/011LN06SAP1F5F4NNNN/NNNNN

111.20.205.00, SNP2NN/011LN09BJP1C7C3D6DN/NNNNN
111.20.205.00-0L, SNP2NN/011LN09BJP1C7C3D6DN/NNNNN
11034114, SNP2NN/011LN09BJP1F5H5DEDN/NNNNN
83018076, SNP2NN/011LN9FDBP3B7B5NNNN/NNNNN
83021518, SNP2NN/011LNA6SAP1B7B5YYNA/NNNNN
83010995, SNP2NN/011LNA6SAP1B7B5YYNN/NNNKN
111.20.187.00, SNP2NN/011LNA6SAP1B7B5YYNN/NNNNN
11043164, SNP2NN/011LNA6SAP1B7B5YYNN/NNNWN
111.20.169.00, SNP2NN/011LNA6SAP1E6E5NNNN/NNNNN
111.20.C27.00, SNP2NN/011LNA6SAP1H8H7NNNA/NNNNN
11037067, SNP2NN/011LNA9BJP1C7C3D6DN/NNNNN
111.20.899.00, SNP2NN/011LNB1DEP1C7C3NNBN/NNNNN
111.20.409.00, SNP2NN/011LNB1DEP1C7C3NNNN/NNNNN
111.20.636.00, SNP2NN/011RN01B1P1C3C3NNNN/NNNNN
111.20.636.00-0L, SNP2NN/011RN01B1P1C3C3NNNN/NNNNN
111.20.494.00, SNP2NN/011RN01B1P1C7C5NNNN/NNNNN
83018483, SNP2NN/011RN01BAP1B7B5NNNN/NNNNN
111.20.C41.00, SNP2NN/011RN01BAP1B7B5ZZNN/NNNNN
111.20.218.00, SNP2NN/011RN01BAP1C3C3NNNN/NNNNN
111.20.313.00, SNP2NN/011RN01BAP1C7C3NNNN/NNNNN
111.20.940.00, SNP2NN/011RN01BAP1E6E4NNNN/NNNNN
111.20.859.00, SNP2NN/011RN01BAP1F4F4NNNN/NNNNN
111.20.280.00, SNP2NN/011RN01BAP1F5F4NNNN/NNNNN
111.20.866.00, SNP2NN/011RN01BAP1F5F4NNNN/NNNNN
111.20.A43.00, SNP2NN/011RN01BBP1C3C3DGNA/NNNNN
111.20.381.00, SNP2NN/011RN01BBP1C3C3NNNN/NNNNN
111.20.512.00, SNP2NN/011RN01BBP1C7C3NNNN/NNNNN
111.20.772.00, SNP2NN/011RN01BBP1F5F3NNBN/NNNNN
111.20.B21.00, SNP2NN/011RN01BBP1F5F4NNNN/NNNNN
111.20.856.00, SNP2NN/011RN01DAP1B7B5NNNA/NNNNN
111.20.457.00, SNP2NN/011RN01DAP1B7B5NNNN/NNNNN
111.20.262.00, SNP2NN/011RN01DAP1C3C3NNNN/NNNNN
111.20.396.00, SNP2NN/011RN01DAP1C7C3NNNN/NNNNN
111.20.338.00, SNP2NN/011RN01DAP1E6E5NNNN/NNNNN
111.20.462.00, SNP2NN/011RN01DAP1F5F4NNNN/NNNNN
111.20.C05.00, SNP2NN/011RN01FAP1B7B5NNNN/NNNNN
111.20.467.00, SNP2NN/011RN01FAP1C3C3NNNN/NNNNN
111.20.652.00, SNP2NN/011RN01FAP1F5F4NNNN/NNNNN
83016353, SNP2NN/011RN02AAP1B7B5NNBN/NNNNN
111.20.925.00, SNP2NN/011RN02AAP1B7B5NNNA/NNNNN
111.20.049.00, SNP2NN/011RN02AAP1B7B5NNNN/NNNNN
111.20.765.00, SNP2NN/011RN02AAP1B7B5NNNN/NNNNN
111.20.828.00, SNP2NN/011RN02AAP1F5F4NNNN/NNNNN
111.20.946.00, SNP2NN/011RN02DBP1B7B5NNNA/NNNNN
111.20.064.00, SNP2NN/011RN02DBP1B7B5NNNN/NNNNN
111.20.947.00, SNP2NN/011RN02DBP1E6E5NNNN/NNNNN
111.20.879.00, SNP2NN/011RN03CAP3B7B5NNBN/NNNNN
111.20.080.00, SNP2NN/011RN03CAP3B7B5NNNN/NNNNN
111.20.809.00, SNP2NN/011RN03CAP3B7B5NNNN/NNNNN
11043129, SNP2NN/011RN03CAP3B7B5NNNN/NNNWN

83011030, SNP2NN/011RN03CAP3B7B5NNNN/NNNZN
111.20.301.00, SNP2NN/011RN03CAP3C3C3NNNN/NNNNN
111.20.318.00, SNP2NN/011RN03CAP3E6E5NNNN/NNNNN
111.20.924.00, SNP2NN/011RN03CAP3F4F4NNNN/NNNNN
111.20.434.00, SNP2NN/011RN03CAP3F5F4NNNN/NNNNN
83023217, SNP2NN/011RN03CAP3M3M2NNNN/NNNNN
111.20.B81.00, SNP2NN/011RN03DBP3C3C3NNNN/NNNNN
111.20.A78.00, SNP2NN/011RN03DBP3E6E5NNNN/NNNNN
111.20.096.00, SNP2NN/011RN04AAP1B7B5NNNN/NNNNN
111.20.342.00, SNP2NN/011RN04DBP1B7B5NNBN/NNNNN
111.20.668.00, SNP2NN/011RN04DBP1B7B5NNNN/NNNNN
111.20.314.00, SNP2NN/011RN05AAP1B7B5NNNN/NNNNN
111.20.331.00, SNP2NN/011RN05DBP1B7B5NNNN/NNNNN
83014242, SNP2NN/011RN05DBP1E6E5NNDN/NNNNN
111.20.860.00, SNP2NN/011RN06BAP1C3C3NNNN/NNNNN
111.20.839.00, SNP2NN/011RN06BAP1E6E5NNNN/NNNNN
11037771, SNP2NN/011RN06BAP1E6E5NNNN/NNNVN
11030980, SNP2NN/011RN06BBP1C3C3NNNN/NNNNN
111.20.243.00, SNP2NN/011RN06GAP1E6E5NNNN/NNNNN
111.20.550.00, SNP2NN/011RN06GAP1F5F4NNNN/NNNNN
111.20.984.00, SNP2NN/011RN06GBP1E6E5NNNN/NNNNN
111.20.148.00, SNP2NN/011RN06SAP1B7B5YYNN/NNNNN
111.20.834.00, SNP2NN/011RN06SAP1B7B5YYNN/NNNNN
111.20.645.00, SNP2NN/011RN06SAP1C3C3NNNN/NNNNN
83020486, SNP2NN/011RN06SAP1C7C5NNBN/NNNNN
83010206, SNP2NN/011RN06SAP1E6E5NNBN/NNNNN
111.20.A14.00, SNP2NN/011RN06SAP1E6E5NNNA/NNNVN
111.20.130.00, SNP2NN/011RN06SAP1E6E5NNNN/NNNNN
111.20.901.00, SNP2NN/011RN06SAP1E8E5NNNN/NNNNN
83008372, SNP2NN/011RN06SAP1E8E6NNNN/NNNNN
111.20.B07.00, SNP2NN/011RN06SAP1F5F4NNBA/NNNNN
111.20.B30.00, SNP2NN/011RN06SAP1F5F4NNBN/NNNNN
111.20.A69.00, SNP2NN/011RN06SAP1F5F4NNNN/NNNNN
111.20.C56.00, SNP2NN/011RN94DBP3B7B5NNNN/NNNNN
111.20.941.00, SNP2NN/011RN9BBAP1E6E4NNNN/NNNNN
83018075, SNP2NN/011RN9FDBP3B7B5NNNN/NNNNN
111.20.A77.00, SNP2NN/011RN9JDBP3E6E5NNNN/NNNNN
111.20.878.00, SNP2NN/011RNA6SAP1B7B5YYBN/NNNNN
111.20.186.00, SNP2NN/011RNA6SAP1B7B5YYNN/NNNNN
11043225, SNP2NN/011RNA6SAP1B7B5YYNN/NNNWN
111.20.C07.00, SNP2NN/011RNA6SAP1C3C3NNNN/NNNNN
111.20.168.00, SNP2NN/011RNA6SAP1E6E5NNNN/NNNNN
111.20.206.00, SNP2NN/011RNA9BJP1C7C3D6DN/NNNNN
111.20.206.00-0L, SNP2NN/011RNA9BJP1C7C3D6DN/NNNNN
111.20.898.00, SNP2NN/011RNB1DEP1C7C3NNBN/NNNNN
111.20.408.00, SNP2NN/011RNB1DEP1C7C3NNNN/NNNNN
111.20.838.00, SNP2NN/012LN01BAP1C3C3NNNN/NNNNN
111.20.754.00, SNP2NN/012LN01BAP1C7C3NNNN/NNNNN
111.20.524.00, SNP2NN/012LN06SAP1E6E5NNNN/NNNNN
111.20.752.00, SNP2NN/012RN01BAP1C7C3NNNN/NNNNN

111.20.A74.00, SNP2NN/012RN02AAP1B7B5NNNA/NNNNN
111.20.885.00, SNP2NN/012RN02AAP1B7B5NNNN/NNNNN
111.20.797.00, SNP2NN/012RN02DBP1B7B5NNNA/NNNNN
111.20.B17.00, SNP2NN/012RN06SAP1C7C3NNNN/NNNNN
111.20.539.00, SNP2NN/012RN06SAP1E6E5NNNN/NNNNN
111.20.B31.00, SNP2NN/012RN06SAP1F5F4NNBN/NNNNN
111.20.A70.00, SNP2NN/012RN06SAP1F5F4NNNN/NNNNN
111.20.735.00, SNP2NN/014L601BJP1C7C3NNNN/NNNNN
111.20.B16.00, SNP2NN/014L603CDP3B7B5NNNN/NNNNN
111.20.379.00, SNP2NN/014LN01B1P1C7C5NNNN/NNNNN
111.20.379.00-0L, SNP2NN/014LN01B1P1C7C5NNNN/NNNNN
111.20.836.00, SNP2NN/014LN01BAP1B7B5NNNN/NNNNN
111.20.873.00, SNP2NN/014LN01BAP1B7B5ZZNN/NNNNN
111.20.C15.00, SNP2NN/014LN01BAP1C7C3NNNA/NNNNN
111.20.219.00, SNP2NN/014LN01BAP1C7C3NNNN/NNNNN
111.20.219.00-0L, SNP2NN/014LN01BAP1C7C3NNNN/NNNNN
111.20.281.00, SNP2NN/014LN01BAP1F5F4NNNN/NNNNN
111.20.C12.00, SNP2NN/014LN01BBP1C7C3NNNA/NNNNN
111.20.296.00, SNP2NN/014LN01BBP1C7C3NNNN/NNNNN
111.20.333.00, SNP2NN/014LN01DAP1B7B5NNNN/NNNNN
111.20.263.00, SNP2NN/014LN01DAP1C7C3NNNN/NNNNN
111.20.516.00, SNP2NN/014LN01DAP1C7C3NNNN/NNNNN
111.20.327.00, SNP2NN/014LN01DAP1E6E5NNNN/NNNNN
111.20.969.00, SNP2NN/014LN01DAP1E6E5NNNN/NNNZN
111.20.B14.00, SNP2NN/014LN01DAP1F5F4NNNN/NNNNN
83018282, SNP2NN/014LN01DAP1F6F5NNNN/NNNNN
111.20.306.00, SNP2NN/014LN01FAP1C7C3NNNN/NNNNN
111.20.B18.00, SNP2NN/014LN01FAP1F5F4NNNN/NNNNN
111.20.050.00, SNP2NN/014LN02AAP1B7B5NNNN/NNNNN
111.20.067.00, SNP2NN/014LN02DBP1B7B5NNNN/NNNNN
111.20.813.00, SNP2NN/014LN02DBP1C7C3NNNN/NNNNN
111.20.081.00, SNP2NN/014LN03CAP3B7B5NNNN/NNNNN
111.20.573.00, SNP2NN/014LN03CAP3B7B5NNNN/NNNNN
111.20.745.00, SNP2NN/014LN03CAP3B7B5NNNN/NNNNN
111.20.C59.00, SNP2NN/014LN03CAP3B7B6DINN/NNNNN
111.20.C60.00, SNP2NN/014LN03CAP3B7B6DUNN/NNNNN
111.20.429.00, SNP2NN/014LN03CAP3C7C3NNNN/NNNNN
111.20.994.00, SNP2NN/014LN03CAP3CXH5D3NN/NNNNN
111.20.254.00, SNP2NN/014LN03CAP3E6E5NNNN/NNNNN
111.20.A90.00, SNP2NN/014LN03CAP3E6E5NNNN/NNNZN
111.20.506.00, SNP2NN/014LN03CAP3F5F4NNNN/NNNNN
111.20.846.00, SNP2NN/014LN03CAP3PGPGNNNN/NNNNN
111.20.B49.00, SNP2NN/014LN03DBP3C7C3NNNN/NNNNN
111.20.B09.00, SNP2NN/014LN03DBP3E6E5NNNN/NNNNN
111.20.099.00, SNP2NN/014LN04AAP1B7B5NNNN/NNNNN
111.20.522.00, SNP2NN/014LN04AAP1E6E5NNDN/NNNNN
111.20.988.00, SNP2NN/014LN04AMP1B7B5NNNN/NNNNN
111.20.343.00, SNP2NN/014LN04DBP1B7B5NNBN/NNNNN
111.20.690.00, SNP2NN/014LN04DBP1B7B5NNNN/NNNNN
111.20.335.00, SNP2NN/014LN05AAP1B7B5NNNN/NNNNN

83020879, SNP2NN/014LN05DBP1B7B5NNNN/NNNNN
111.20.768.00, SNP2NN/014LN06BAP1C7C3NNNN/NNNNN
111.20.823.00, SNP2NN/014LN06BAP1E6E5NNNN/NNNNN
83014086, SNP2NN/014LN06BBP1C7C3NNNN/NNNNN
83007808, SNP2NN/014LN06BBP1F5F4NNNN/NNNNN
111.20.245.00, SNP2NN/014LN06GAP1E6E5NNNN/NNNNN
111.20.C17.00, SNP2NN/014LN06SAP1B7B5YYDN/NNNVN
111.20.151.00, SNP2NN/014LN06SAP1B7B5YYNN/NNNNN
11102834, SNP2NN/014LN06SAP1B7B6NNNN/NNNNN
111.20.383.00, SNP2NN/014LN06SAP1C7C3NNNN/NNNNN
11065611, SNP2NN/014LN06SAP1E6E5NNBN/NNNNN
111.20.133.00, SNP2NN/014LN06SAP1E6E5NNNN/NNNNN
111.20.A92.00, SNP2NN/014LN06SAP1F5F4NNNN/NNNNN
111.20.454.00, SNP2NN/014LN09BJP1C7C3NNDN/NNNNN
111.20.454.00-0L, SNP2NN/014LN09BJP1C7C3NNDN/NNNNN
11044195, SNP2NN/014LN09BJP1E8E5NNDN/NNNNN
111.20.709.00, SNP2NN/014LN09BJP1F5H5DEDN/NNNNN
111.20.B50.00, SNP2NN/014LN9ADBP3C7C3NNNN/NNNNN
111.20.C33.00, SNP2NN/014LN9CDBP3C7C3NNNN/NNNNN
83018078, SNP2NN/014LN9FDBP3B7B5NNNN/NNNNN
111.20.B10.00, SNP2NN/014LN9JDBP3E6E5NNNN/NNNNN
111.20.B98.00, SNP2NN/014LNA6SAP1B7B5YYNA/NNNNN
111.20.189.00, SNP2NN/014LNA6SAP1B7B5YYNN/NNNNN
111.20.C31.00, SNP2NN/014LNA6SAP1C7C3NNNN/NNNNN
111.20.171.00, SNP2NN/014LNA6SAP1E6E5NNNN/NNNNN
111.20.341.00, SNP2NN/014LNB1DEP1C7C3D9BN/NNNNN
111.20.541.00, SNP2NN/014RN01B1P1C7C5NNNN/NNNNN
111.20.541.00-0L, SNP2NN/014RN01B1P1C7C5NNNN/NNNNN
111.20.A85.00, SNP2NN/014RN01BAP1C7C3NNBN/NNNNN
111.20.C10.00, SNP2NN/014RN01BAP1C7C3NNNA/NNNNN
111.20.220.00, SNP2NN/014RN01BAP1C7C3NNNN/NNNNN
111.20.883.00, SNP2NN/014RN01BAP1F5F4NNBN/NNNNN
111.20.282.00, SNP2NN/014RN01BAP1F5F4NNNN/NNNNN
111.20.C14.00, SNP2NN/014RN01BBP1C7C3NNNA/NNNNN
111.20.505.00, SNP2NN/014RN01BBP1C7C3NNNN/NNNNN
11040166, SNP2NN/014RN01BBP1E6E5NNNN/NNNNN
111.20.B22.00, SNP2NN/014RN01BBP1F5F4NNNN/NNNNN
111.20.325.00, SNP2NN/014RN01DAP1B7B5NNNN/NNNNN
111.20.264.00, SNP2NN/014RN01DAP1C7C3NNNN/NNNNN
111.20.204.00, SNP2NN/014RN01DAP1E6E5NNNN/NNNNN
111.20.938.00, SNP2NN/014RN01DAP1F5F3NNBA/NNNNN
111.20.609.00, SNP2NN/014RN01DAP1F5F4NNNN/NNNNN
11049973, SNP2NN/014RN01DAP1F6F5NNNN/NNNNN
111.20.468.00, SNP2NN/014RN01FAP1C7C3NNNN/NNNNN
111.20.393.00, SNP2NN/014RN01FAP1E6E5NNNN/NNNNN
111.20.385.00, SNP2NN/014RN01FAP1F5F4NNNN/NNNNN
111.20.051.00, SNP2NN/014RN02AAP1B7B5NNNN/NNNNN
111.20.066.00, SNP2NN/014RN02DBP1B7B5NNNN/NNNNN
111.20.082.00, SNP2NN/014RN03CAP3B7B5NNNN/NNNNN
11060734, SNP2NN/014RN03CAP3C3C3NNNN/NNNNN

111.20.302.00, SNP2NN/014RN03CAP3C7C3NNNN/NNNNN
111.20.317.00, SNP2NN/014RN03CAP3E6E5NNNN/NNNNN
111.20.A11.00, SNP2NN/014RN03CAP3F5F4NNNA/NNNNN
111.20.545.00, SNP2NN/014RN03CAP3F5F4NNNN/NNNNN
83012453, SNP2NN/014RN03CAP3MCM1NNNN/NNNNN
111.20.847.00, SNP2NN/014RN03CAP3PGPGNNNN/NNNNN
111.20.954.00, SNP2NN/014RN03DBP3B7B5NNNN/NNNNN
111.20.C22.00, SNP2NN/014RN03DBP3E6E5NNNN/NNNNN
111.20.B51.00, SNP2NN/014RN04AAP1B7B5NNDN/NNNNN
111.20.098.00, SNP2NN/014RN04AAP1B7B5NNNN/NNNNN
111.20.235.00, SNP2NN/014RN04DBP1B7B5NNBN/NNNNN
111.20.490.00, SNP2NN/014RN04DBP1B7B5NNNN/NNNNN
111.20.400.00, SNP2NN/014RN05AAP1B7B5NNNN/NNNNN
111.20.A54.00, SNP2NN/014RN05DBP1B7B5NNDN/NNNNN
83020878, SNP2NN/014RN05DBP1B7B5NNNN/NNNNN
111.20.B25.00, SNP2NN/014RN05DBP1C7C3NNNN/NNNNN
11052377, SNP2NN/014RN06BJP1E6E5NNNN/NNNNN
111.20.503.00, SNP2NN/014RN06GAP1B7B5YYNN/NNNNN
111.20.210.00, SNP2NN/014RN06GAP1E6E5NNNN/NNNNN
111.20.551.00, SNP2NN/014RN06GAP1F5F4NNNN/NNNNN
111.20.150.00, SNP2NN/014RN06SAP1B7B5YYNN/NNNNN
111.20.729.00, SNP2NN/014RN06SAP1C7C3NNNN/NNNNN
111.20.132.00, SNP2NN/014RN06SAP1E6E5NNNN/NNNNN
11037616, SNP2NN/014RN06SAP1E6E5NNNN/NNNVN
111.20.902.00, SNP2NN/014RN06SAP1E8E5NNNN/NNNNN
111.20.A84.00, SNP2NN/014RN06SAP1F5F4NNNN/NNNNN
111.20.955.00, SNP2NN/014RN94DBP3B7B5NNNN/NNNNN
83021221, SNP2NN/014RN94DBP3F5F4NNNN/NNNNN
83018077, SNP2NN/014RN9FDBP3B7B5NNNN/NNNNN
111.20.C23.00, SNP2NN/014RN9JDBP3E6E5NNNN/NNNNN
83017361, SNP2NN/014RNA6SAP1B7B5YYNA/NNNNN
111.20.188.00, SNP2NN/014RNA6SAP1B7B5YYNN/NNNNN
111.20.170.00, SNP2NN/014RNA6SAP1E6E5NNNN/NNNNN
111.20.B44.00, SNP2NN/014RNA6SAP1F5F4NNNN/NNNNN
11039803, SNP2NN/014RNA9BJP1C7C3D6DN/NNNNN
111.20.590.00, SNP2NN/014RNA9BJP1C7C3D6DN/NNNNN
111.20.407.00, SNP2NN/014RNB1DEP1C7C3D9BN/NNNNN
111.20.592.00, SNP2NN/014RNP6SAP1MCM1NNNN/NNNNN
11052480, SNP2NN/016LN03CAP1B7B5NNNA/NNNNN
111.20.C55.00, SNP2NN/016LN03CAP3B7B5NNNN/NNNNN
111.20.770.00, SNP2NN/017L603CDP3B7B5NNNN/NNNNN
111.20.305.00, SNP2NN/017LN01B1P1C7C5NNNN/NNNNN
111.20.305.00-0L, SNP2NN/017LN01B1P1C7C5NNNN/NNNNN
111.20.221.00, SNP2NN/017LN01BAP1C7C3NNNN/NNNNN
111.20.283.00, SNP2NN/017LN01BAP1F5F4NNNN/NNNNN
111.20.513.00, SNP2NN/017LN01BBP1C7C3NNNN/NNNNN
111.20.719.00, SNP2NN/017LN01BJP1C7C3NNNN/NNNNN
111.20.310.00, SNP2NN/017LN01DAP1B7B5NNNN/NNNNN
111.20.265.00, SNP2NN/017LN01DAP1C7C3NNNN/NNNNN
111.20.386.00, SNP2NN/017LN01DAP1E6E5NNNN/NNNNN

83012190, SNP2NN/017LN01DAP1E8E6NNNNN/NNNNN
111.20.470.00, SNP2NN/017LN01DAP1F5F4NNNNN/NNNNN
11062622, SNP2NN/017LN01DAP1F6F5NNNNN/NNNNN
111.20.694.00, SNP2NN/017LN01FAP1C7C3NNNNN/NNNNN
111.20.B19.00, SNP2NN/017LN01FAP1F5F4NNNNN/NNNNN
111.20.052.00, SNP2NN/017LN02AAP1B7B5NNNNN/NNNNN
111.20.069.00, SNP2NN/017LN02DBP1B7B5NNNNN/NNNNN
111.20.083.00, SNP2NN/017LN03CAP3B7B5NNNNN/NNNNN
111.20.746.00, SNP2NN/017LN03CAP3B7B5NNNNN/NNNNN
111.20.384.00, SNP2NN/017LN03CAP3C7C3NNNNN/NNNNN
111.20.476.00, SNP2NN/017LN03CAP3E6E5NNNNN/NNNNN
111.20.426.00, SNP2NN/017LN03CAP3F5F4NNNNN/NNNNN
111.20.678.00, SNP2NN/017LN03CMP3B7B5NNNNN/NNNNN
111.20.957.00, SNP2NN/017LN03CMP3B7B5NNNNN/NNNNN
111.20.979.00, SNP2NN/017LN03CMP3B7B5ZZNN/NNNNN
111.20.C49.00, SNP2NN/017LN03DBP3C7C3NNNNN/NNNNN
11033087, SNP2NN/017LN04AAP1B7B5NNDN/NNNNN
111.20.101.00, SNP2NN/017LN04AAP1B7B5NNNNN/NNNNN
111.20.812.00, SNP2NN/017LN04AAP1F5F4NNNNN/NNNNN
111.20.989.00, SNP2NN/017LN04AMP1B7B5NNNNN/NNNNN
111.20.626.00, SNP2NN/017LN04DBP1B7B5NNBN/NNNNN
111.20.515.00, SNP2NN/017LN04DBP1B7B5NNNNN/NNNNN
111.20.336.00, SNP2NN/017LN05AAP1B7B5NNNNN/NNNNN
111.20.791.00, SNP2NN/017LN06BAP1C7C3NNNNN/NNNNN
111.20.816.00, SNP2NN/017LN06BAP1E6E5NNNNN/NNNNN
111.20.926.00, SNP2NN/017LN06BAP1F5F4E2NN/NNNNN
111.20.B90.00, SNP2NN/017LN06BBP1C7C3NNNNN/NNNNN
11059965, SNP2NN/017LN06BBP1E6E5NNNNN/NNNNN
111.20.247.00, SNP2NN/017LN06GAP1E6E5NNNNN/NNNNN
111.20.A99.00, SNP2NN/017LN06SAP1B7B5NNBN/NNNNN
111.20.153.00, SNP2NN/017LN06SAP1B7B5YYNN/NNNNN
83014150, SNP2NN/017LN06SAP1B7B5YYNN/NNNWN
111.20.734.00, SNP2NN/017LN06SAP1C7C3NNNNN/NNNNN
111.20.135.00, SNP2NN/017LN06SAP1E6E5NNNNN/NNNNN
111.20.684.00, SNP2NN/017LN06SAP1E8E5FENN/NNNNN
111.20.527.00, SNP2NN/017LN06SAP1E8E6TDNN/NNNNN
11050940, SNP2NN/017LN06SAP1F5F4NNNNN/NNNNN
11037726, SNP2NN/017LN06SAP1H9H7NNNNN/NNNNN
83014399, SNP2NN/017LN9CDBP3B7B5NNNNN/NNNNN
111.20.C50.00, SNP2NN/017LN9CDBP3C7C3NNNNN/NNNNN
83018073, SNP2NN/017LN9FDBP3B7B5NNNNN/NNNNN
111.20.B99.00, SNP2NN/017LNA6SAP1B7B5YYNA/NNNNN
111.20.191.00, SNP2NN/017LNA6SAP1B7B5YYNN/NNNNN
11043176, SNP2NN/017LNA6SAP1B7B5YYNN/NNNWN
111.20.C30.00, SNP2NN/017LNA6SAP1C7C3NNNNN/NNNNN
111.20.173.00, SNP2NN/017LNA6SAP1E6E5NNNNN/NNNNN
111.20.A98.00, SNP2NN/017LNB1DEP1C7C3D9BN/NNNNN
111.20.983.00, SNP2NN/017RN01AAP1C7C3NNNNN/NNNNN
111.20.495.00, SNP2NN/017RN01B1P1C7C5NNNNN/NNNNN
111.20.222.00, SNP2NN/017RN01BAP1C7C3NNNNN/NNNNN

111.20.284.00, SNP2NN/017RN01BAP1F5F4NNNN/NNNNN
111.20.644.00, SNP2NN/017RN01BBP1C7C3NNNN/NNNNN
111.20.B23.00, SNP2NN/017RN01BBP1F5F4NNNN/NNNNN
111.20.326.00, SNP2NN/017RN01DAP1B7B5NNNN/NNNNN
111.20.920.00, SNP2NN/017RN01DAP1C7C3NNNA/NNNNN
111.20.266.00, SNP2NN/017RN01DAP1C7C3NNNN/NNNNN
111.20.323.00, SNP2NN/017RN01DAP1E6E5NNNN/NNNNN
111.20.424.00, SNP2NN/017RN01DAP1F5F4NNNN/NNNNN
11049977, SNP2NN/017RN01DAP1F6F5NNNN/NNNNN
111.20.475.00, SNP2NN/017RN01FAP1C7C3NNNN/NNNNN
83012852, SNP2NN/017RN01FAP1F5F4NNNN/NNNNN
83016354, SNP2NN/017RN02AAP1B7B5NNBN/NNNNN
111.20.053.00, SNP2NN/017RN02AAP1B7B5NNNN/NNNNN
111.20.767.00, SNP2NN/017RN02AAP1B7B5NNNN/NNNNN
111.20.068.00, SNP2NN/017RN02DBP1B7B5NNNN/NNNNN
111.20.084.00, SNP2NN/017RN03CAP3B7B5NNNN/NNNNN
111.20.295.00, SNP2NN/017RN03CAP3C7C3NNNN/NNNNN
111.20.319.00, SNP2NN/017RN03CAP3E6E5NNNN/NNNNN
111.20.435.00, SNP2NN/017RN03CAP3F5F4NNNN/NNNNN
111.20.B61.00, SNP2NN/017RN03DBP3B7B5NNNN/NNNNN
111.20.B82.00, SNP2NN/017RN03DBP3C7C3NNNN/NNNNN
111.20.100.00, SNP2NN/017RN04AAP1B7B5NNNN/NNNNN
111.20.413.00, SNP2NN/017RN04DBP1B7B5NNBN/NNNNN
111.20.330.00, SNP2NN/017RN04DBP1B7B5NNNN/NNNNN
111.20.448.00, SNP2NN/017RN05AAP1B7B5NNNN/NNNNN
111.20.705.00, SNP2NN/017RN05DBP1B7B5NNDN/NNNNN
111.20.307.00, SNP2NN/017RN05DBP1B7B5NNNN/NNNNN
111.20.751.00, SNP2NN/017RN06AAP1B7B5YYBN/NNNNN
111.20.B42.00, SNP2NN/017RN06BAP1E6E5NNNN/NNNNN
111.20.B93.00, SNP2NN/017RN06BBP1C7C3NNNN/NNNNN
111.20.C37.00, SNP2NN/017RN06GAP1C7C3NNNN/NNNNN
111.20.246.00, SNP2NN/017RN06GAP1E6E5NNNN/NNNNN
111.20.552.00, SNP2NN/017RN06GAP1F5F4NNNN/NNNNN
83012425, SNP2NN/017RN06SAP1B7B5YYNA/NNNNN
111.20.152.00, SNP2NN/017RN06SAP1B7B5YYNN/NNNNN
111.20.432.00, SNP2NN/017RN06SAP1C7C3NNNN/NNNNN
11065622, SNP2NN/017RN06SAP1E6E5NNNA/NNNNN
111.20.922.00, SNP2NN/017RN06SAP1E6E5NNNN/NNNAN
111.20.134.00, SNP2NN/017RN06SAP1E6E5NNNN/NNNNN
11037569, SNP2NN/017RN06SAP1E6E5NNNN/NNNVN
11062585, SNP2NN/017RN06SAP1E8E6NNNN/NNNNN
111.20.561.00, SNP2NN/017RN06SAP1E8E6TDNN/NNNNN
11050939, SNP2NN/017RN06SAP1F5F4NNNN/NNNNN
111.20.921.00, SNP2NN/017RN06SCP1E6E5NNNN/NNNAA
111.20.B84.00, SNP2NN/017RN94DBP3B7B5NNNN/NNNNN
111.20.B83.00, SNP2NN/017RN9ADBP3C7C3NNNN/NNNNN
83018074, SNP2NN/017RN9FDBP3B7B5NNNN/NNNNN
83015922, SNP2NN/017RN9JDBP3E6E5NNNN/NNNNN
111.20.190.00, SNP2NN/017RNA6SAP1B7B5YYNN/NNNNN
11043232, SNP2NN/017RNA6SAP1B7B5YYNN/NNNWN

111.20.993.00, SNP2NN/017RNA6SAP1C7C3NNNN/NNNNN
111.20.172.00, SNP2NN/017RNA6SAP1E6E5NNNN/NNNNN
83017407, SNP2NN/017RNA6SAP1F5F4NNNN/NNNNN
111.20.406.00, SNP2NN/017RNB1DEP1C7C3D9BN/NNNNN
111.20.223.00, SNP2NN/019LN01BAP1C7C3NNNN/NNNNN
111.20.285.00, SNP2NN/019LN01BAP1F5F4NNNN/NNNNN
111.20.298.00, SNP2NN/019LN01BBP1C7C3NNBN/NNNNN
111.20.672.00-02, SNP2NN/019LN01BBP1C7C3NNNN/NNNBN
111.20.294.00, SNP2NN/019LN01BBP1C7C3NNNN/NNNNN
111.20.546.00, SNP2NN/019LN01DAP1B7B5NNNN/NNNNN
111.20.267.00, SNP2NN/019LN01DAP1C7C3NNNN/NNNNN
111.20.630.00, SNP2NN/019LN01DAP1E6E5NNNN/NNNNN
111.20.681.00, SNP2NN/019LN01DAP1F5F4NNNN/NNNNN
111.20.469.00, SNP2NN/019LN01FAP1C7C3NNNN/NNNNN
111.20.054.00, SNP2NN/019LN02AAP1B7B5NNNN/NNNNN
111.20.459.00, SNP2NN/019LN02AAP1C7C3NNNN/NNNNN
111.20.071.00, SNP2NN/019LN02DBP1B7B5NNNN/NNNNN
111.20.039.00, SNP2NN/019LN03CAP3B7B5NNNN/NNNNN
111.20.292.00, SNP2NN/019LN03CAP3C7C3NNNN/NNNNN
111.20.321.00, SNP2NN/019LN03CAP3E6E5NNNN/NNNNN
111.20.659.00, SNP2NN/019LN03CAP3F5F4NNNN/NNNNN
111.20.B26.00, SNP2NN/019LN03CLP3B7B5NNNN/NNNNN
111.20.679.00, SNP2NN/019LN03CMP3B7B5NNNN/NNNNN
111.20.958.00, SNP2NN/019LN03CMP3B7B5NNNN/NNNNN
111.20.A25.00, SNP2NN/019LN03DBP3B7B5NNNN/NNNNN
111.20.616.00, SNP2NN/019LN03DBP3C7C3NNNN/NNNNN
111.20.A01.00, SNP2NN/019LN04AAP1B7B5NNDN/NNNNN
111.20.103.00, SNP2NN/019LN04AAP1B7B5NNNN/NNNNN
111.20.B62.00, SNP2NN/019LN04AAP1E6E5NNNN/NNNNN
111.20.990.00, SNP2NN/019LN04AMP1B7B5NNNN/NNNNN
111.20.651.00, SNP2NN/019LN04DBP1B7B5NNBN/NNNNN
111.20.A26.00, SNP2NN/019LN04DBP1B7B5NNNN/NNNNN
111.20.232.00, SNP2NN/019LN05AAP1B7B5NNNN/NNNNN
111.20.B91.00, SNP2NN/019LN06BBP1C7C3NNNN/NNNNN
111.20.509.00, SNP2NN/019LN06GAP1B7B5YYNN/NNNNN
111.20.511.00, SNP2NN/019LN06GAP1C7C3NNNN/NNNNN
111.20.249.00, SNP2NN/019LN06GAP1E6E5NNNN/NNNNN
111.20.155.00, SNP2NN/019LN06SAP1B7B5YYNN/NNNNN
111.20.715.00, SNP2NN/019LN06SAP1C7C3NNNN/NNNNN
111.20.A05.00, SNP2NN/019LN06SAP1E6E5NNBN/NNNNN
111.20.137.00, SNP2NN/019LN06SAP1E6E5NNNN/NNNNN
83011980, SNP2NN/019LN06SAP1E6E5NNNN/NNNVN
111.20.529.00, SNP2NN/019LN06SAP1E8E6TDNN/NNNNN
111.20.465.00, SNP2NN/019LN06SAP1F5F4NNNN/NNNNN
111.20.500.00, SNP2NN/019LN9ADBP3C7C3NNNN/NNNNN
111.20.C34.00, SNP2NN/019LN9CDBP3C7C3NNNN/NNNNN
111.20.835.00, SNP2NN/019LNA4AAP1B7B5NNNN/NNNNN
111.20.193.00, SNP2NN/019LNA6SAP1B7B5YYNN/NNNNN
11043170, SNP2NN/019LNA6SAP1B7B5YYNN/NNNWN
111.20.175.00, SNP2NN/019LNA6SAP1E6E5NNNN/NNNNN

111.20.405.00, SNP2NN/019LNB1DEP1C7C3F0BN/NNNNN
111.20.C39.00, SNP2NN/019RN01B1P1C7C5NNNN/NNNNN
111.20.224.00, SNP2NN/019RN01BAP1C7C3NNNN/NNNNN
111.20.392.00, SNP2NN/019RN01BAP1E6E5NNNN/NNNNN
111.20.286.00, SNP2NN/019RN01BAP1F5F4NNNN/NNNNN
111.20.676.00, SNP2NN/019RN01BAP1F6F5NNNN/NNNNN
111.20.297.00, SNP2NN/019RN01BBP1C7C3NNBN/NNNNN
111.20.665.00, SNP2NN/019RN01BBP1C7C3NNNN/NNNNN
111.20.725.00, SNP2NN/019RN01BBP1MEM2NNDN/NNNNN
111.20.339.00, SNP2NN/019RN01DAP1B7B5NNNN/NNNNN
111.20.A02.00, SNP2NN/019RN01DAP1C7C3NNDN/NNNNN
111.20.268.00, SNP2NN/019RN01DAP1C7C3NNNN/NNNNN
111.20.324.00, SNP2NN/019RN01DAP1E6E5NNNN/NNNNN
111.20.547.00, SNP2NN/019RN01DAP1F5F4NNNN/NNNNN
111.20.712.00, SNP2NN/019RN01FAP1C7C3NNNN/NNNNN
111.20.653.00, SNP2NN/019RN01FAP1F5F4NNNN/NNNNN
111.20.055.00, SNP2NN/019RN02AAP1B7B5NNNN/NNNNN
111.20.A87.00, SNP2NN/019RN02DBP1B7B5NNBN/NNNNN
111.20.070.00, SNP2NN/019RN02DBP1B7B5NNNN/NNNNN
111.20.085.00, SNP2NN/019RN03CAP3B7B5NNNN/NNNNN
83011062, SNP2NN/019RN03CAP3B7B5NNNN/NNNZN
111.20.499.00, SNP2NN/019RN03CAP3C7C3NNNN/NNNNN
111.20.320.00, SNP2NN/019RN03CAP3E6E5NNNN/NNNNN
111.20.582.00, SNP2NN/019RN03CAP3F5F4NNNN/NNNNN
111.20.C32.00, SNP2NN/019RN03DAP3B7B5NNNN/NNNNN
111.20.B85.00, SNP2NN/019RN03DBP3B7B5NNNN/NNNNN
111.20.617.00, SNP2NN/019RN03DBP3C7C3NNNN/NNNNN
111.20.102.00, SNP2NN/019RN04AAP1B7B5NNNN/NNNNN
111.20.832.00, SNP2NN/019RN04DBP1B7B5NNBN/NNNNN
111.20.374.00, SNP2NN/019RN04DBP1B7B5NNNN/NNNNN
111.20.973.00, SNP2NN/019RN04DBP1F5F4NNNN/NNNNN
111.20.449.00, SNP2NN/019RN05AAP1B7B5NNNN/NNNNN
111.20.962.00, SNP2NN/019RN05DBP1B7B5NNNN/NNNNN
111.20.B94.00, SNP2NN/019RN06BBP1C7C3NNNN/NNNNN
83007607, SNP2NN/019RN06GAP1B7B5YYBN/NNNNN
111.20.658.00, SNP2NN/019RN06GAP1B7B5YYNN/NNNNN
111.20.498.00, SNP2NN/019RN06GAP1C7C3NNNN/NNNNN
111.20.248.00, SNP2NN/019RN06GAP1E6E5NNNN/NNNNN
111.20.553.00, SNP2NN/019RN06GAP1F5F4NNNN/NNNNN
83012422, SNP2NN/019RN06SAP1B7B5YYDA/NNNNN
11057001, SNP2NN/019RN06SAP1B7B5YYNA/NNNWN
111.20.154.00, SNP2NN/019RN06SAP1B7B5YYNN/NNNNN
83013955, SNP2NN/019RN06SAP1C7C3NNNA/NNNNN
111.20.433.00, SNP2NN/019RN06SAP1C7C3NNNN/NNNNN
111.20.136.00, SNP2NN/019RN06SAP1E6E5NNNN/NNNNN
111.20.685.00, SNP2NN/019RN06SAP1E8E5F5NN/NNNNN
111.20.528.00, SNP2NN/019RN06SAP1E8E6TDNN/NNNNN
111.20.C53.00, SNP2NN/019RN06SAP1F5F4NNNN/NNNNN
111.20.B86.00, SNP2NN/019RN94DBP3B7B5NNNN/NNNNN
111.20.501.00, SNP2NN/019RN9ADBP3C7C3NNNN/NNNNN

11059956, SNP2NN/019RN9LBAP1C7C3NNNN/NNNNN
111.20.CO1.00, SNP2NN/019RNA6SAP1B7B5YYNA/NNNNN
111.20.192.00, SNP2NN/019RNA6SAP1B7B5YYNN/NNNNN
111.20.589.00, SNP2NN/019RNA6SAP1C7C3NNNN/NNNNN
111.20.174.00, SNP2NN/019RNA6SAP1E6E5NNNN/NNNNN
111.20.380.00, SNP2NN/019RNB1DEP1C7C3D9BN/NNNNN
111.20.415.00, SNP2NN/019RNB1DEP1C7C3F0BN/NNNNN
111.20.906.00, SNP2NN/019RNB1DGP1F5F4NNNA/NNNNN
111.20.225.00, SNP2NN/022LN01BAP1C7C3NNNN/NNNNN
111.20.287.00, SNP2NN/022LN01BAP1F5F4NNNN/NNNNN
111.20.B87.00, SNP2NN/022LN01BBP1C7C3NNNN/NNNNN
111.20.B45.00, SNP2NN/022LN01DAP1B7B5NNNN/NNNNN
111.20.269.00, SNP2NN/022LN01DAP1C7C3NNNN/NNNNN
111.20.B57.00, SNP2NN/022LN01DAP1E6E5NNNN/NNNNN
111.20.A68.00, SNP2NN/022LN01DAP1F5F4NNNN/NNNNN
11030778, SNP2NN/022LN01FAP1F5F4NNNN/NNNNN
111.20.056.00, SNP2NN/022LN02AAP1B7B5NNNN/NNNNN
111.20.073.00, SNP2NN/022LN02DBP1B7B5NNNN/NNNNN
11054833, SNP2NN/022LN02DBP1E6E5NNNN/NNNNN
111.20.087.00, SNP2NN/022LN03CAP3B7B5NNNN/NNNNN
111.20.375.00, SNP2NN/022LN03CAP3C7C3NNNN/NNNNN
111.20.477.00, SNP2NN/022LN03CAP3E6E5NNNN/NNNNN
111.20.A47.00, SNP2NN/022LN03CAP3F5F4NNNN/NNNNN
111.20.802.00, SNP2NN/022LN03CMP3B7B5NNNN/NNNNN
111.20.936.00, SNP2NN/022LN03CMP3B7B5ZZNN/NNNNN
111.20.105.00, SNP2NN/022LN04AAP1B7B5NNNN/NNNNN
83019275, SNP2NN/022LN04AAP1C7C3NNNN/NNNNN
111.20.B01.00, SNP2NN/022LN04ABP1C7C3NNNN/NNNNN
83011902, SNP2NN/022LN04DBP1B7B5EUBN/NNNNN
111.20.399.00, SNP2NN/022LN04DBP1B7B5NNNN/NNNNN
83018721, SNP2NN/022LN04DBP1C7C3NNNN/NNNNN
111.20.439.00, SNP2NN/022LN05AAP1B7B5NNNN/NNNNN
111.20.B92.00, SNP2NN/022LN06BBP1C7C3NNNN/NNNNN
111.20.251.00, SNP2NN/022LN06GAP1E6E5NNNN/NNNNN
83015011, SNP2NN/022LN06GAP1F5F4NNNN/NNNNN
111.20.157.00, SNP2NN/022LN06SAP1B7B5YYNN/NNNNN
83015237, SNP2NN/022LN06SAP1C7C3NNNB/NNNNN
111.20.736.00, SNP2NN/022LN06SAP1C7C3NNNN/NNNNN
111.20.A18.00, SNP2NN/022LN06SAP1E6E5NNBN/NNNNN
111.20.139.00, SNP2NN/022LN06SAP1E6E5NNNN/NNNNN
111.20.A21.00, SNP2NN/022LN06SAP1E8E5NNNN/NNNNN
111.20.B47.00, SNP2NN/022LN06SAP1F5F4NNNN/NNNNN
111.20.542.00, SNP2NN/022LNA6GAP1B7B5YYNN/NNNNN
83010996, SNP2NN/022LNA6SAP1B7B5YYNN/NNNKN
111.20.195.00, SNP2NN/022LNA6SAP1B7B5YYNN/NNNNN
111.20.177.00, SNP2NN/022LNA6SAP1E6E5NNNN/NNNNN
111.20.799.00, SNP2NN/022LNA6SAP1F5F4NNNN/NNNNN
111.20.236.00, SNP2NN/022LNB1DEP1C7C3FEBN/NNNNN
111.20.430.00, SNP2NN/022LNM4AAP1E6E5NNQN/NNNNN
83010739, SNP2NN/022RNO1BAP1B7B5NNNN/NNNNN

111.20.226.00, SNP2NN/022RN01BAP1C7C3NNNN/NNNNN
111.20.884.00, SNP2NN/022RN01BAP1F5F4NNBN/NNNNN
111.20.288.00, SNP2NN/022RN01BAP1F5F4NNNN/NNNNN
111.20.508.00, SNP2NN/022RN01BBP1C7C3NNNN/NNNNN
111.20.640.00, SNP2NN/022RN01DAP1B7B5NNNN/NNNNN
111.20.270.00, SNP2NN/022RN01DAP1C7C3NNNN/NNNNN
111.20.641.00, SNP2NN/022RN01DAP1E6E5NNNN/NNNNN
111.20.463.00, SNP2NN/022RN01DAP1F5F4NNNN/NNNNN
111.20.595.00, SNP2NN/022RN01DAP1MGMBNNNN/NNNNN
111.20.B12.00, SNP2NN/022RN01FAP1C7C3NNNN/NNNNN
111.20.625.00, SNP2NN/022RN01FAP1F5F4NNNN/NNNNN
111.20.057.00, SNP2NN/022RN02AAP1B7B5NNNN/NNNNN
111.20.072.00, SNP2NN/022RN02DBP1B7B5NNNN/NNNNN
111.20.086.00, SNP2NN/022RN03CAP3B7B5NNNN/NNNNN
111.20.491.00, SNP2NN/022RN03CAP3C7C3NNNN/NNNNN
111.20.478.00, SNP2NN/022RN03CAP3E6E5NNNN/NNNNN
111.20.583.00, SNP2NN/022RN03CAP3F5F4NNNN/NNNNN
111.20.104.00, SNP2NN/022RN04AAP1B7B5NNNN/NNNNN
111.20.397.00, SNP2NN/022RN04DBP1B7B5EUBN/NNNNN
111.20.638.00, SNP2NN/022RN04DBP1B7B5NNNN/NNNNN
11090659, SNP2NN/022RN04DBP1B7B6NNNN/NNNNN
111.20.440.00, SNP2NN/022RN05AAP1B7B5NNNN/NNNNN
111.20.A41.00, SNP2NN/022RN05DBP1B7B5NNNN/NNNNN
111.20.B95.00, SNP2NN/022RN06BBP1C7C3NNNN/NNNNN
83011545, SNP2NN/022RN06GAP1E6E5NNBN/NNNNN
111.20.250.00, SNP2NN/022RN06GAP1E6E5NNNN/NNNNN
111.20.562.00, SNP2NN/022RN06GAP1F5F4NNNN/NNNNN
111.20.156.00, SNP2NN/022RN06SAP1B7B5YYNN/NNNNN
83013923, SNP2NN/022RN06SAP1C7C3NNNB/NNNNN
111.20.466.00, SNP2NN/022RN06SAP1C7C3NNNN/NNNNN
83009783, SNP2NN/022RN06SAP1C7C7NNNN/NNNNN
111.20.B40.00, SNP2NN/022RN06SAP1E6E5NNBN/NNNNN
111.20.B13.00, SNP2NN/022RN06SAP1E6E5NNNA/NNNNN
111.20.138.00, SNP2NN/022RN06SAP1E6E5NNNN/NNNNN
111.20.A91.00, SNP2NN/022RN06SAP1F5F4NNNN/NNNNN
11057536, SNP2NN/022RN06SAP1H9H5NNLB/NNNAN
111.20.C47.00, SNP2NN/022RN06SAP1H9H5NNLN/NNNAN
111.20.964.00, SNP2NN/022RN06SAP1H9H5NNNN/NNNAN
83011278, SNP2NN/022RN91DBP3C7C3NNNN/NNNNN
11034276, SNP2NN/022RN94DBP3B7B5NNNN/NNNNN
111.20.194.00, SNP2NN/022RNA6SAP1B7B5YYNN/NNNNN
111.20.176.00, SNP2NN/022RNA6SAP1E6E5NNNN/NNNNN
111.20.800.00, SNP2NN/022RNA6SAP1F5F4NNNN/NNNNN
111.20.431.00, SNP2NN/022RNB1DEP1C7C3FEBN/NNNNN
111.20.227.00, SNP2NN/025LN01BAP1C8C7NNNN/NNNNN
111.20.289.00, SNP2NN/025LN01BAP1F6F5NNNN/NNNNN
111.20.806.00, SNP2NN/025LN01BBP1C8C7NNNN/NNNNN
111.20.531.00, SNP2NN/025LN01BBP1E8E5NNNN/NNNNN
111.20.A89.00, SNP2NN/025LN01BBP1F6F5NNNN/NNNNN
111.20.B96.00, SNP2NN/025LN01DAP1B7B5NNNN/NNNNN

111.20.271.00, SNP2NN/025LN01DAP1C8C7NNNN/NNNNN
111.20.C62.00, SNP2NN/025LN01DAP1E6E5NNNN/NNNNN
111.20.471.00, SNP2NN/025LN01DAP1F6F5NNNN/NNNNN
111.20.998.00, SNP2NN/025LN01FAP1C8C7NNNN/NNNNN
111.20.C54.00, SNP2NN/025LN01FAP1F6F5NNNN/NNNNN
111.20.438.00, SNP2NN/025LN02AAP1B7B5NNNN/NNNNN
111.20.443.00, SNP2NN/025LN02DBP1B7B5NNNN/NNNNN
111.20.C21.00, SNP2NN/025LN02DBP1C8C7NNNN/NNNNN
111.20.089.00, SNP2NN/025LN03CAP3B7B5NNNN/NNNNN
111.20.497.00, SNP2NN/025LN03CAP3C8C7NNNN/NNNNN
111.20.479.00, SNP2NN/025LN03CAP3E6E5NNNN/NNNNN
111.20.782.00, SNP2NN/025LN03CAP3F6F5NNNN/NNNNN
111.20.680.00, SNP2NN/025LN03CMP3B7B5NNNN/NNNNN
111.20.888.00, SNP2NN/025LN03DBP3C8C7NNNN/NNNNN
111.20.456.00, SNP2NN/025LN04AAP1B7B5NNNN/NNNNN
111.20.A80.00, SNP2NN/025LN04AAP1C8C7NNNN/NNNNN
83020831, SNP2NN/025LN04AAP1F6F5NNNN/NNNNN
111.20.A66.00, SNP2NN/025LN04ABP1C8C7NNNN/NNNNN
111.20.915.00, SNP2NN/025LN04DBP1B7B5NNNN/NNNNN
111.20.441.00, SNP2NN/025LN05AAP1B7B5NNNN/NNNNN
111.20.C06.00, SNP2NN/025LN05DBP1B7B5NNNN/NNNNN
83020399, SNP2NN/025LN06AAP1C8C7NNNN/NNNNN
111.20.792.00, SNP2NN/025LN06BAP1C8C7NNNN/NNNNN
111.20.C36.00, SNP2NN/025LN06BBP1C8C7NNNN/NNNNN
111.20.253.00, SNP2NN/025LN06GAP1E6E5NNNN/NNNNN
111.20.159.00, SNP2NN/025LN06SAP1B7B5YYNN/NNNNN
111.20.798.00, SNP2NN/025LN06SAP1C8C7NNNN/NNNNN
83010205, SNP2NN/025LN06SAP1E6E5NNBN/NNNNN
111.20.141.00, SNP2NN/025LN06SAP1E6E5NNNN/NNNNN
83008954, SNP2NN/025LN06SAP1E6E5NNQN/NNNNN
111.20.B71.00, SNP2NN/025LN06SAP1F6F5NNNN/NNNNN
83014804, SNP2NN/025LN09BJP1C7C3NNDN/NNNNN
111.20.887.00, SNP2NN/025LN9ADBP3C8C7NNNN/NNNNN
111.20.197.00, SNP2NN/025LNA6SAP1B7B5YYNN/NNNNN
111.20.179.00, SNP2NN/025LNA6SAP1E6E5NNNN/NNNNN
111.20.A19.00, SNP2NN/025LNA6SAP1F6F5NNNA/NNNAN
111.20.228.00, SNP2NN/025RN01BAP1C8C7NNNN/NNNNN
111.20.290.00, SNP2NN/025RN01BAP1F6F5NNNN/NNNNN
111.20.A16.00, SNP2NN/025RN01BBP1C7C3NNNN/NNNNN
111.20.666.00, SNP2NN/025RN01BBP1C8C7NNNN/NNNNN
111.20.A03.00, SNP2NN/025RN01BBP1F5F4NNNN/NNNNN
111.20.B24.00, SNP2NN/025RN01BBP1F6F5NNNN/NNNNN
111.20.332.00, SNP2NN/025RN01DAP1B7B5NNNN/NNNNN
111.20.623.00, SNP2NN/025RN01DAP1C8C7NNNN/NNNEN
111.20.272.00, SNP2NN/025RN01DAP1C8C7NNNN/NNNNN
111.20.533.00, SNP2NN/025RN01DAP1C8C7NNNN/NNNZN
111.20.642.00, SNP2NN/025RN01DAP1E6E5NNNN/NNNNN
111.20.464.00, SNP2NN/025RN01DAP1F6F5NNNN/NNNNN
111.20.507.00, SNP2NN/025RN01FAP1C8C7NNNN/NNNNN
111.20.649.00, SNP2NN/025RN01FAP1F6F5NNNN/NNNNN

111.20.437.00, SNP2NN/025RN02AAP1B7B5NNNN/NNNNN
111.20.444.00, SNP2NN/025RN02DBP1B7B5NNNN/NNNNN
111.20.088.00, SNP2NN/025RN03CAP3B7B5NNNN/NNNNN
111.20.496.00, SNP2NN/025RN03CAP3C8C7NNNN/NNNNN
111.20.322.00, SNP2NN/025RN03CAP3E6E5NNNN/NNNNN
111.20.965.00, SNP2NN/025RN03CAP3F5F4NNNN/NNNNN
111.20.452.00, SNP2NN/025RN03CAP3F6F5NNNN/NNNNN
111.20.A07.00, SNP2NN/025RN03DBP3B7B5NNNN/NNNNN
111.20.618.00, SNP2NN/025RN03DBP3C8C7NNNN/NNNNN
111.20.B76.00, SNP2NN/025RN03DBP3E6E5NNNN/NNNNN
111.20.445.00, SNP2NN/025RN04AAP1B7B5NNNN/NNNNN
111.20.610.00, SNP2NN/025RN04DBP1B7B5NNNN/NNNNN
111.20.820.00, SNP2NN/025RN05DBP1B7B5NNNN/NNNNN
111.20.C35.00, SNP2NN/025RN06BBP1C8C7NNNN/NNNNN
111.20.252.00, SNP2NN/025RN06GAP1E6E5NNNN/NNNNN
111.20.554.00, SNP2NN/025RN06GAP1F6F5NNNN/NNNNN
111.20.158.00, SNP2NN/025RN06SAP1B7B5YYNN/NNNNN
83020821, SNP2NN/025RN06SAP1C8C7NNNA/NNNNN
111.20.472.00, SNP2NN/025RN06SAP1C8C7NNNN/NNNNN
83016332, SNP2NN/025RN06SAP1E6E5NNBN/NNNNN
111.20.A13.00, SNP2NN/025RN06SAP1E6E5NNNN/NNNAN
111.20.140.00, SNP2NN/025RN06SAP1E6E5NNNN/NNNNN
11037615, SNP2NN/025RN06SAP1E6E5NNNN/NNNVN
111.20.B32.00, SNP2NN/025RN06SAP1F6F5NNBN/NNNNN
111.20.943.00, SNP2NN/025RN06SAP1F6F5NNNN/NNNNN
111.20.A08.00, SNP2NN/025RN94DBP3B7B5NNNN/NNNNN
111.20.B77.00, SNP2NN/025RN9JDBP3E6E5NNNN/NNNNN
83010997, SNP2NN/025RNA6SAP1B7B5YYNN/NNNKN
111.20.196.00, SNP2NN/025RNA6SAP1B7B5YYNN/NNNNN
111.20.178.00, SNP2NN/025RNA6SAP1E6E5NNNN/NNNNN
111.20.A58.00, SNP2NN/3,0LN06SAP1E5E4NNNN/NNNNN
111.20.211.00, SNP2NN/4,0LN01BAP1C3C3NNNN/NNNNN
111.20.273.00, SNP2NN/4,0LN01BAP1F4F4NNNN/NNNNN
83014958, SNP2NN/4,0LN01BBP1C3C3NNNN/NNNNN
111.20.776.00, SNP2NN/4,0LN01DAP1B6B5NNNN/NNNNN
111.20.255.00, SNP2NN/4,0LN01DAP1C3C3NNNN/NNNNN
111.20.543.00, SNP2NN/4,0LN01DAP1E6E5NNNN/NNNNN
111.20.874.00, SNP2NN/4,0LN01DAP1F4F4NNNA/NNNNN
111.20.775.00, SNP2NN/4,0LN01DAP1F4F4NNNN/NNNNN
111.20.043.00, SNP2NN/4,0LN02AAP1B6B5NNNN/NNNNN
111.20.059.00, SNP2NN/4,0LN02DBP1B6B5NNNN/NNNNN
111.20.075.00, SNP2NN/4,0LN03CAP3B6B5NNNN/NNNNN
111.20.C38.00, SNP2NN/4,0LN03CAP3C3C3NNBN/NNNNN
111.20.559.00, SNP2NN/4,0LN03CAP3C3C3NNNN/NNNNN
111.20.328.00, SNP2NN/4,0LN03CAP3E6E5NNNN/NNNNN
111.20.489.00, SNP2NN/4,0LN03CAP3F4F4NNNN/NNNNN
111.20.971.00, SNP2NN/4,0LN03CMP3B6B5NNNN/NNNNN
111.20.091.00, SNP2NN/4,0LN04AAP1B6B5NNNN/NNNNN
111.20.707.00, SNP2NN/4,0LN04AAP1E6E5NNNN/NNNNN
83015112, SNP2NN/4,0LN04DBP1B6B5NNNN/NNNNN

111.20.C02.00, SNP2NN/4,0LN05AAP1B6B5NNNN/NNNNN
11052472, SNP2NN/4,0LN06DBP1E6E5NNNN/NNNNN
111.20.369.00, SNP2NN/4,0LN06GAP1E6E5NNNN/NNNNN
111.20.351.00, SNP2NN/4,0LN06SAP1B6B5YYNN/NNNNN
111.20.739.00, SNP2NN/4,0LN06SAP1C3C3NNNN/NNNNN
111.20.345.00, SNP2NN/4,0LN06SAP1E6E5NNNN/NNNNN
83007546, SNP2NN/4,0LN06SAP1F4F4NNNN/NNNNN
11057882, SNP2NN/4,0LNA6SAP1B6B5YYNA/NNNNN
111.20.363.00, SNP2NN/4,0LNA6SAP1B6B5YYNN/NNNNN
111.20.357.00, SNP2NN/4,0LNA6SAP1E6E5NNNN/NNNNN
111.20.B68.00, SNP2NN/4,0RN01BAP1B6B5NNNN/NNNNN
111.20.212.00, SNP2NN/4,0RN01BAP1C3C3NNNN/NNNNN
111.20.A35.00, SNP2NN/4,0RN01BAP1F4F4NNNA/NNNNN
111.20.274.00, SNP2NN/4,0RN01BAP1F4F4NNNN/NNNNN
111.20.863.00, SNP2NN/4,0RN01BAP1F4F4NNNN/NNNNN
111.20.793.00, SNP2NN/4,0RN01BBP1C3C3NNNN/NNNNN
11052918, SNP2NN/4,0RN01BBP1E6E5NNMN/NNNNN
111.20.B33.00, SNP2NN/4,0RN01BBP1F4F4NNNN/NNNNN
111.20.544.00, SNP2NN/4,0RN01DAP1B6B5NNNN/NNNNN
111.20.256.00, SNP2NN/4,0RN01DAP1C3C3NNNN/NNNNN
111.20.731.00, SNP2NN/4,0RN01DAP1E6E5NNNN/NNNNN
111.20.460.00, SNP2NN/4,0RN01DAP1F4F4NNNN/NNNNN
111.20.540.00, SNP2NN/4,0RN01FAP1C3C3NNNN/NNNNN
111.20.647.00, SNP2NN/4,0RN01FAP1F4F4NNNN/NNNNN
83016351, SNP2NN/4,0RN02AAP1B6B5NNBN/NNNNN
111.20.044.00, SNP2NN/4,0RN02AAP1B6B5NNNN/NNNNN
111.20.886.00, SNP2NN/4,0RN02AAP1B6B5NNNN/NNNNN
111.20.198.00, SNP2NN/4,0RN02AAP1F4F4NNNN/NNNNN
111.20.058.00, SNP2NN/4,0RN02DBP1B6B5NNNN/NNNNN
111.20.074.00, SNP2NN/4,0RN03CAP3B6B5NNNN/NNNNN
111.20.403.00, SNP2NN/4,0RN03CAP3C3C3NNNN/NNNNN
111.20.872.00, SNP2NN/4,0RN03CAP3E5E5NNNN/NNNNN
11064195, SNP2NN/4,0RN03CAP3E6E5NNBN/NNNNN
111.20.293.00, SNP2NN/4,0RN03CAP3E6E5NNNN/NNNNN
111.20.334.00, SNP2NN/4,0RN03CAP3F4F4NNNN/NNNNN
11089827, SNP2NN/4,0RN03CAP3M2M2NNNN/NNNNN
111.20.758.00, SNP2NN/4,0RN03DBP3B6B5NNNN/NNNNN
111.20.090.00, SNP2NN/4,0RN04AAP1B6B5NNNN/NNNNN
111.20.949.00, SNP2NN/4,0RN04DBP1B6B5NNNN/NNNNN
111.20.657.00, SNP2NN/4,0RN05AAP1B6B5NNNN/NNNNN
111.20.627.00, SNP2NN/4,0RN05DBP1B6B5NNNN/NNNNN
111.20.A64.00, SNP2NN/4,0RN05DBP1C3C3NNNN/NNNNN
111.20.368.00, SNP2NN/4,0RN06GAP1E6E5NNNN/NNNNN
83017586, SNP2NN/4,0RN06GAP1F4F4NNNN/NNNNN
111.20.350.00, SNP2NN/4,0RN06SAP1B6B5YYNN/NNNNN
111.20.620.00, SNP2NN/4,0RN06SAP1C3C3NNNN/NNNNN
111.20.344.00, SNP2NN/4,0RN06SAP1E6E5NNNN/NNNNN
111.20.621.00, SNP2NN/4,0RN06SAP1F4F4NNNN/NNNNN
111.20.B11.00, SNP2NN/4,0RN91DBP3B6B5NNNN/NNNNN
111.20.C57.00, SNP2NN/4,0RN94DBP3B6B5NNNN/NNNNN

111.20.C63.00, SNP2NN/4,ORN9JDBP3E6E5NNNN/NNNNN
83017359, SNP2NN/4,ORNA6SAP1B6B5YYNA/NNNNN
111.20.362.00, SNP2NN/4,ORNA6SAP1B6B5YYNN/NNNNN
111.20.356.00, SNP2NN/4,ORNA6SAP1E6E5NNNN/NNNNN
111.20.945.00, SNP2NN/5,5LN06GAP1E6E5NNNA/NNNVN
111.20.757.00, SNP2NN/5,5LN06GAP1E6E5NNNN/NNNNN
111.20.756.00, SNP2NN/5,5RN06SAP1E6E5NNNA/NNNIN
111.20.213.00, SNP2NN/6,0LN01BAP1C3C3NNNN/NNNNN
111.20.275.00, SNP2NN/6,0LN01BAP1F4F4NNNN/NNNNN
111.20.662.00, SNP2NN/6,0LN01BBP1C3C3NNNN/NNNNN
111.20.504.00, SNP2NN/6,0LN01DAP1B6B5NNNN/NNNNN
111.20.257.00, SNP2NN/6,0LN01DAP1C3C3NNNN/NNNNN
111.20.778.00, SNP2NN/6,0LN01DAP1E6E5NNNN/NNNNN
111.20.972.00, SNP2NN/6,0LN01DAP1F4F3NNNN/NNNNN
11030473, SNP2NN/6,0LN01DAP1F4F4NNNN/NNNNN
111.20.519.00, SNP2NN/6,0LN01FAP1C3C3NNNN/NNNNN
111.20.045.00, SNP2NN/6,0LN02AAP1B6B5NNNN/NNNNN
111.20.061.00, SNP2NN/6,0LN02DBP1B6B5NNNN/NNNNN
83011735, SNP2NN/6,0LN03CAP3B6B5NNBN/NNNNN
111.20.077.00, SNP2NN/6,0LN03CAP3B6B5NNNN/NNNNN
111.20.567.00, SNP2NN/6,0LN03CAP3B6B5NNNN/NNNNN
111.20.C58.00, SNP2NN/6,0LN03CAP3B7B6DINN/NNNNN
111.20.C61.00, SNP2NN/6,0LN03CAP3B7B6DUNN/NNNNN
111.20.207.00, SNP2NN/6,0LN03CAP3C3C3NNNN/NNNNN
111.20.398.00, SNP2NN/6,0LN03CAP3E6E5NNNN/NNNNN
111.20.377.00, SNP2NN/6,0LN03CAP3F4F4NNNN/NNNNN
111.20.B65.00, SNP2NN/6,0LN03CAP3H8H7NNNN/NNNNN
111.20.854.00, SNP2NN/6,0LN03DBP3C3C3NNNN/NNNNN
111.20.093.00, SNP2NN/6,0LN04AAP1B6B5NNNN/NNNNN
111.20.A83.00, SNP2NN/6,0LN04AAP1F4F4NNNN/NNNNN
111.20.233.00, SNP2NN/6,0LN04DBP1B6B5NNBN/NNNNN
111.20.804.00, SNP2NN/6,0LN04DBP1B6B5NNNN/NNNNN
111.20.447.00, SNP2NN/6,0LN05AAP1B6B5NNNN/NNNNN
111.20.371.00, SNP2NN/6,0LN06GAP1E6E5NNNN/NNNNN
111.20.353.00, SNP2NN/6,0LN06SAP1B6B5YYNN/NNNNN
111.20.882.00, SNP2NN/6,0LN06SAP1C3C3NNNN/NNNNN
111.20.347.00, SNP2NN/6,0LN06SAP1E6E5NNNN/NNNNN
111.20.881.00, SNP2NN/6,0LN06SAP1F4F4NNNN/NNNNN
111.20.855.00, SNP2NN/6,0LN9ADBP3C3C3NNNN/NNNNN
83016703, SNP2NN/6,0LN9JDBP3C3C3NNNN/NNNNN
83017362, SNP2NN/6,0LNA6SAP1B6B5YYNA/NNNNN
111.20.365.00, SNP2NN/6,0LNA6SAP1B6B5YYNN/NNNNN
111.20.359.00, SNP2NN/6,0LNA6SAP1E6E5NNNN/NNNNN
111.20.C28.00, SNP2NN/6,0LNA6SAP1H8H7NNNA/NNNNN
111.20.C44.00, SNP2NN/6,ORN01BAP1B6B5ZZNN/NNNNN
83007119, SNP2NN/6,ORN01BAP1C3C3NNBN/NNNNN
111.20.214.00, SNP2NN/6,ORN01BAP1C3C3NNNN/NNNNN
111.20.276.00, SNP2NN/6,ORN01BAP1F4F4NNNN/NNNNN
111.20.864.00, SNP2NN/6,ORN01BAP1F4F4NNNN/NNNNN
111.20.A63.00, SNP2NN/6,ORN01BBP1C3C3NNNN/NNNNN

111.20.B20.00, SNP2NN/6,ORN01BBP1F4F4NNNN/NNNN
111.20.308.00, SNP2NN/6,ORN01DAP1B6B5NNNN/NNNN
111.20.918.00, SNP2NN/6,ORN01DAP1C3C3NNNA/NNNN
111.20.258.00, SNP2NN/6,ORN01DAP1C3C3NNNN/NNNN
111.20.643.00, SNP2NN/6,ORN01DAP1E6E5NNNN/NNNN
111.20.418.00, SNP2NN/6,ORN01DAP1F4F4NNNN/NNNN
111.20.473.00, SNP2NN/6,ORN01FAP1C3C3NNNN/NNNN
111.20.648.00, SNP2NN/6,ORN01FAP1F4F4NNNN/NNNN
111.20.046.00, SNP2NN/6,ORN02AAP1B6B5NNNN/NNNN
111.20.060.00, SNP2NN/6,ORN02DBP1B6B5NNNN/NNNN
111.20.C16.00, SNP2NN/6,ORN02DBP1C3C3NNNN/NNNN
111.20.076.00, SNP2NN/6,ORN03CAP3B6B5NNNN/NNNN
111.20.299.00, SNP2NN/6,ORN03CAP3C3C3NNNN/NNNN
111.20.315.00, SNP2NN/6,ORN03CAP3E6E5NNNN/NNNN
111.20.427.00, SNP2NN/6,ORN03CAP3F4F4NNNN/NNNN
111.20.458.00, SNP2NN/6,ORN03CAP3MBMBNNNN/NNNN
111.20.786.00, SNP2NN/6,ORN03DBP3C3C3NNNN/NNNN
111.20.A95.00, SNP2NN/6,ORN03DBP3E6E5NNNN/NNNN
111.20.092.00, SNP2NN/6,ORN04AAP1B6B5NNNN/NNNN
111.20.777.00, SNP2NN/6,ORN04DBP1B6B5NNNN/NNNN
111.20.446.00, SNP2NN/6,ORN05AAP1B6B5NNNN/NNNN
111.20.311.00, SNP2NN/6,ORN05DBP1B6B5NNNN/NNNN
111.20.A65.00, SNP2NN/6,ORN05DBP1C3C3NNNN/NNNN
111.20.C24.00, SNP2NN/6,ORN06GAP1B6B5YYNN/NNNN
111.20.370.00, SNP2NN/6,ORN06GAP1E6E5NNNN/NNNN
111.20.548.00, SNP2NN/6,ORN06GAP1F4F4NNNN/NNNN
111.20.352.00, SNP2NN/6,ORN06SAP1B6B5YYNN/NNNN
111.20.814.00, SNP2NN/6,ORN06SAP1C3C3NNNN/NNNN
83019577, SNP2NN/6,ORN06SAP1E5E4NNNN/NNNN
111.20.346.00, SNP2NN/6,ORN06SAP1E6E5NNNN/NNNN
111.20.B29.00, SNP2NN/6,ORN06SAP1F4F4NNBN/NNNN
111.20.660.00, SNP2NN/6,ORN06SAP1F4F4NNNN/NNNN
11117447, SNP2NN/6,ORN94DBP3E6E5NNNN/NNNN
111.20.787.00, SNP2NN/6,ORN9ADBP3C3C3NNNN/NNNN
111.20.A94.00, SNP2NN/6,ORN9JDBP3E6E5NNNN/NNNN
111.20.364.00, SNP2NN/6,ORNA6SAP1B6B5YYNN/NNNN
111.20.358.00, SNP2NN/6,ORNA6SAP1E6E5NNNN/NNNN
11041804, SNP2NN/7,ORN06SAP1E5E4NNNN/NNNN
11029912, SNP2NN/7,ORN06SAP1F5F4NNNN/NNNN
111.20.897.00, SNP2NN/8,0L6B1DFP1C3C3D5BN/NNNN
111.20.C25.00, SNP2NN/8,0LN01BAP1B7B5NNNN/NNNN
111.20.C08.00, SNP2NN/8,0LN01BAP1C3C3NNBN/NNNN
111.20.C13.00, SNP2NN/8,0LN01BAP1C3C3NNNA/NNNN
111.20.215.00, SNP2NN/8,0LN01BAP1C3C3NNNN/NNNN
111.20.215.00-0L, SNP2NN/8,0LN01BAP1C3C3NNNN/NNNN
111.20.C46.00, SNP2NN/8,0LN01BAP1C7C3NNNN/NNNN
83022172, SNP2NN/8,0LN01BAP1E6E5NNNN/NNNN
111.20.277.00, SNP2NN/8,0LN01BAP1F4F4NNNN/NNNN
111.20.404.00, SNP2NN/8,0LN01BBP1C3C3NNNN/NNNN
111.20.718.00, SNP2NN/8,0LN01BJP1C3C3NNNN/NNNN

111.20.493.00, SNP2NN/8,0LN01DAP1B7B5NNNN/NNNNN
83018701, SNP2NN/8,0LN01DAP1B7B5ZZNN/NNNNN
111.20.259.00, SNP2NN/8,0LN01DAP1C3C3NNNN/NNNNN
111.20.340.00, SNP2NN/8,0LN01DAP1E6E5NNNN/NNNNN
111.20.682.00, SNP2NN/8,0LN01DAP1F4F4NNNN/NNNNN
111.20.521.00, SNP2NN/8,0LN01FAP1C3C3NNNN/NNNNN
111.20.693.00, SNP2NN/8,0LN01FAP1F4F4NNNN/NNNNN
111.20.C70.00, SNP2NN/8,0LN01SAP1C3C3NNNN/NNNNN
111.20.894.00, SNP2NN/8,0LN02AAP1B7B5NNBN/NNNNN
111.20.047.00, SNP2NN/8,0LN02AAP1B7B5NNNN/NNNNN
111.20.203.00, SNP2NN/8,0LN02AAP1C3C3NNNN/NNNNN
111.20.063.00, SNP2NN/8,0LN02DBP1B7B5NNNN/NNNNN
111.20.B28.00, SNP2NN/8,0LN03CAP3B7B5NNBN/NNNNN
111.20.038.00, SNP2NN/8,0LN03CAP3B7B5NNNN/NNNNN
111.20.569.00, SNP2NN/8,0LN03CAP3B7B5NNNN/NNNNN
111.20.291.00, SNP2NN/8,0LN03CAP3C3C3NNNN/NNNNN
11119533, SNP2NN/8,0LN03CAP3CXH5NNNN/NNNNN
83007144, SNP2NN/8,0LN03CAP3E6E5NNBN/NNNNN
111.20.041.00, SNP2NN/8,0LN03CAP3E6E5NNNN/NNNNN
111.20.560.00, SNP2NN/8,0LN03CAP3F4F4NNNN/NNNNN
11031579, SNP2NN/8,0LN03CAP3F5F4NNNN/NNNNN
111.20.095.00, SNP2NN/8,0LN04AAP1B7B5NNNN/NNNNN
111.20.B03.00, SNP2NN/8,0LN04AAP1B7B5ZZNN/NNNNN
111.20.A32.00, SNP2NN/8,0LN04AAP1E6E5NNNN/NNNNN
111.20.986.00, SNP2NN/8,0LN04AMP1B7B5NNNN/NNNNN
111.20.234.00, SNP2NN/8,0LN04DBP1B7B5NNBN/NNNNN
111.20.492.00, SNP2NN/8,0LN04DBP1B7B5NNNN/NNNBN
111.20.492.00-02, SNP2NN/8,0LN04DBP1B7B5NNNN/NNNBN
111.20.304.00, SNP2NN/8,0LN04DBP1B7B5NNNN/NNNNN
111.20.416.00, SNP2NN/8,0LN05AAP1B7B5NNNN/NNNNN
83007639, SNP2NN/8,0LN06BAP1E6E5NNDN/NNNNN
111.20.C45.00, SNP2NN/8,0LN06GAP1B7B5YYNN/NNNNN
111.20.373.00, SNP2NN/8,0LN06GAP1E6E5NNNN/NNNNN
111.20.355.00, SNP2NN/8,0LN06SAP1B7B5YYNN/NNNNN
111.20.555.00, SNP2NN/8,0LN06SAP1C3C3NNNN/NNNNN
111.20.974.00, SNP2NN/8,0LN06SAP1E6E5NNNN/NNNAN
111.20.349.00, SNP2NN/8,0LN06SAP1E6E5NNNN/NNNNN
83017195, SNP2NN/8,0LN06SAP1F4F4NNNN/NNNNN
111.20.738.00, SNP2NN/8,0LN09BJP1C3C3NNDN/NNNNN
83011615, SNP2NN/8,0LNA6SAP1B7B5YYNA/NNNNN
111.20.367.00, SNP2NN/8,0LNA6SAP1B7B5YYNN/NNNNN
111.20.361.00, SNP2NN/8,0LNA6SAP1E6E5NNNN/NNNNN
111.20.896.00, SNP2NN/8,0LNB1DEP1C3C3NNBN/NNNNN
111.20.411.00, SNP2NN/8,0LNB1DEP1C3C3NNNN/NNNNN
11033046, SNP2NN/8,0LNU9BEP1CXE5SEDN/NNNNN
111.20.771.00, SNP2NN/8,0R603CDP3B7B5NNNN/NNNNN
83007120, SNP2NN/8,0RN01BAP1B7B5NNBN/NNNNN
83016116, SNP2NN/8,0RN01BAP1B7B5NNNN/NNNNN
111.20.216.00, SNP2NN/8,0RN01BAP1C3C3NNNN/NNNNN
83021223, SNP2NN/8,0RN01BAP1C7C3NNNN/NNNNN

111.20.278.00, SNP2NN/8,ORN01BAP1F4F4NNNN/NNNN
111.20.C11.00, SNP2NN/8,ORN01BBP1C3C3NNNA/NNNN
111.20.663.00, SNP2NN/8,ORN01BBP1C3C3NNNN/NNNN
111.20.A17.00, SNP2NN/8,ORN01BBP1E6E5NNMN/NNNN
111.20.B08.00, SNP2NN/8,ORN01BBP1F4F4NNNN/NNNN
83010001, SNP2NN/8,ORN01BEP1C3C3NNNN/NNNN
83017363, SNP2NN/8,ORN01DAP1B7B5NNNA/NNNN
111.20.395.00, SNP2NN/8,ORN01DAP1B7B5NNNN/NNNN
111.20.919.00, SNP2NN/8,ORN01DAP1C3C3NNNA/NNNN
111.20.260.00, SNP2NN/8,ORN01DAP1C3C3NNNN/NNNN
111.20.387.00, SNP2NN/8,ORN01DAP1E6E5NNNN/NNNN
11046976, SNP2NN/8,ORN01DAP1F4F3NNNN/NNNN
111.20.461.00, SNP2NN/8,ORN01DAP1F4F4NNNN/NNNN
111.20.520.00, SNP2NN/8,ORN01FAP1C3C3NNNN/NNNN
111.20.701.00, SNP2NN/8,ORN01FAP1F4F4NNNN/NNNN
83016352, SNP2NN/8,ORN02AAP1B7B5NNBN/NNNN
111.20.048.00, SNP2NN/8,ORN02AAP1B7B5NNNN/NNNN
111.20.764.00, SNP2NN/8,ORN02AAP1B7B5NNNN/NNNN
111.20.827.00, SNP2NN/8,ORN02AAP1F5F4NNNN/NNNN
111.20.062.00, SNP2NN/8,ORN02DBP1B7B5NNNN/NNNN
111.20.893.00, SNP2NN/8,ORN03CAP3B7B5NNBN/NNNN
111.20.078.00, SNP2NN/8,ORN03CAP3B7B5NNNN/NNNN
111.20.975.00, SNP2NN/8,ORN03CAP3B7B5NNNN/NNNN
111.20.585.00, SNP2NN/8,ORN03CAP3C3C3NNBN/NNNN
111.20.300.00, SNP2NN/8,ORN03CAP3C3C3NNNN/NNNN
111.20.536.00, SNP2NN/8,ORN03CAP3C7C3NNNN/NNNN
111.20.B02.00, SNP2NN/8,ORN03CAP3E6E4NNNN/NNNN
111.20.316.00, SNP2NN/8,ORN03CAP3E6E5NNNN/NNNN
111.20.451.00, SNP2NN/8,ORN03CAP3F4F4NNNN/NNNN
11052223, SNP2NN/8,ORN03CAP3F5F4NNNN/NNNN
111.20.760.00, SNP2NN/8,ORN03DBP3B7B5NNNN/NNNN
111.20.A97.00, SNP2NN/8,ORN03DBP3E6E5NNNN/NNNN
111.20.A88.00, SNP2NN/8,ORN04AAP1B7B5NNDN/NNNN
111.20.094.00, SNP2NN/8,ORN04AAP1B7B5NNNN/NNNN
111.20.514.00, SNP2NN/8,ORN04DBP1B7B5NNNN/NNNN
111.20.417.00, SNP2NN/8,ORN05AAP1B7B5NNNN/NNNN
111.20.779.00, SNP2NN/8,ORN05DBP1B7B5NNNN/NNNN
111.20.875.00, SNP2NN/8,ORN06BAP1E6E5NNNN/NNNN
111.20.929.00, SNP2NN/8,ORN06GAP1C3C3NNNN/NNNN
111.20.372.00, SNP2NN/8,ORN06GAP1E6E5NNNN/NNNN
111.20.549.00, SNP2NN/8,ORN06GAP1F4F4NNNN/NNNN
111.20.713.00, SNP2NN/8,ORN06GBP1E6E5NNNN/NNNN
111.20.354.00, SNP2NN/8,ORN06SAP1B7B5YYNN/NNNN
111.20.A09.00, SNP2NN/8,ORN06SAP1B7B5YYNN/NNNN
111.20.586.00, SNP2NN/8,ORN06SAP1C3C3NNNN/NNNN
111.20.996.00, SNP2NN/8,ORN06SAP1E6E5NNNA/NNAN
111.20.A06.00, SNP2NN/8,ORN06SAP1E6E5NNNA/NNNN
111.20.348.00, SNP2NN/8,ORN06SAP1E6E5NNNN/NNNN
111.20.A51.00, SNP2NN/8,ORN06SAP1F4F4NNNN/NNNN
111.20.717.00, SNP2NN/8,ORN06SAP1F5F4NNNN/NNNN

83008469, SNP2NN/8,ORN06SAP1M2M2NNNN/NNNNN
111.20.CO4.00, SNP2NN/8,ORN9FDBP3B7B5NNNN/NNNNN
111.20.A96.00, SNP2NN/8,ORN9JDBP3E6E5NNNN/NNNNN
111.20.B46.00, SNP2NN/8,ORNA6GAP1B7B5YYNN/NNNNN
111.20.366.00, SNP2NN/8,ORNA6SAP1B7B5YYNN/NNNNN
111.20.723.00, SNP2NN/8,ORNA6SAP1C3C3NNNN/NNNNN
111.20.785.00, SNP2NN/8,ORNA6SAP1E6E5NNBN/NNNNN
111.20.360.00, SNP2NN/8,ORNA6SAP1E6E5NNNN/NNNNN
111.20.857.00, SNP2NN/8,ORNA9BDP1CVE5NNBN/NNNNN
111.20.818.00, SNP2NN/8,ORNA9BJP1CVE5NNBN/NNNNN
111.20.410.00, SNP2NN/8,ORNB1DEP1C3C3NNNN/NNNNN
111.20.B34.00, SNP2NN/9,ORN06SAP1F5F4NNBN/NNNNN
111.20.A67.00, SNP2NN/9,5LN03CAP3C3C3NNNN/NNNNN
83012877, SNP2NN/9,5RN06SAP1F5F4NNBN/NNNNN
111.25.351.0C, SNP3/22 D SC07 MKQ_G
211.25.386.00, SNP3/22 D SC11 DZF4E
211.25.408.00, SNP3/22 D SC47 ...4.
111.25.166.0A, SNP3/22 S SC06 LGT_
111.25.351.0A, SNP3/22 S SC07 MKQ_G
11045062, SNP3/22 S SC11 ...4.
11106349, SNP3/26 D CO36 LML1.
11120217, SNP3/26 D SC07 LGE_C
11065678, SNP3/26 D SC11 ...4.
11032406, SNP3/26 D SC11 ...4E
11086352, SNP3/26 S SC47 ...4.
11045060, SNP3/26 S SC47 ...4C
211.25.387.00, SNP3/33 D CO41 DZG4A
211.25.385.00, SNP3/33 D CO47 DUN4E
11082770, SNP3/33 D SC07 +++_
11102342, SNP3/33 D SC11 ...4A
11032403, SNP3/33 D SC47 DUN4E
11102313, SNP3/33 D SC71 DDN4.
211.25.429.00, SNP3/33 S SC47 DDF4.
211.25.431.0C, SNP3/38 D SC47 LMW_C
211.25.443.0A, SNP3/38 S CO43 LMW_
211.25.372.00, SNP3/44 D CO41 DDQ4A
211.25.388.00, SNP3/44 D CO41 DZG4A
111.25.352.0C, SNP3/44 D CO91 LOY_
211.25.293.0C, SNP3/44 D SC47 LHS_C
211.25.458.00, SNP3/44 S CO41 ...4F
11085306, SNP3/44 S SC04 +++_
11065679, SNP3/48 D CO41 LMX4.
11079056, SNP3/48 D SC47 +++_C
11065680, SNP3/48 D SC71 DVW4.
211.25.423.0A, SNP3/48 S CO43 LMW_
111.25.022.0A, SNP3NN/022LN01BAP1C7C7NNNN/NNNNN
111.25.337.0A, SNP3NN/022LN01BAP1CAC7NNNN/NNNNN
111.25.066.0A, SNP3NN/022LN01BAP1F5F5NNNN/NNNNN
111.25.095.0A, SNP3NN/022LN01DAP1C7C7NNNN/NNNNN
111.25.156.0A, SNP3NN/022LN01FAP1C7C7NNNN/NNNNN

111.25.107.0A, SNP3NN/022LN02BAP1C7C7NNNN/NNNNN
83017508, SNP3NN/022LN02FAP1C7C7NNNN/NNNNN
111.25.075.0A, SNP3NN/022LN06AAP1BBBANNNN/NNNNN
111.25.034.0A, SNP3NN/022LN06CAP1BBBANNNN/NNNNN
111.25.216.0A, SNP3NN/022LN06DDP1BBBANNNN/NNNNN
11072383, SNP3NN/022LN07AAP1F5F5NNNN/NNNNN
111.25.046.0A, SNP3NN/022LN07GAP1A3A2NNNN/NNNNN
111.25.281.0A, SNP3NN/022LN07GAP1C7C7NNNN/NNNNN
111.25.044.0A, SNP3NN/022LN07GCP1A3A2NNNN/NNNNN
111.25.366.0A, SNP3NN/022LN07SAP1A3A2NNDN/NNNNN
111.25.011.0A, SNP3NN/022LN07SAP1A3A2NNNN/NNNNN
111.25.085.0A, SNP3NN/022LN07SAP1BBBANNNN/NNNNN
11042639, SNP3NN/022LN07SAP1BBBANNNN/NNNWN
111.25.001.0A, SNP3NN/022LN07SAP1C7C7NNNN/NNNNN
111.25.117.0A, SNP3NN/022LN07SAP1E8E6NNNN/NNNNN
11065855, SNP3NN/022LN07SAP1F5F5NNNN/NNNNN
11046931, SNP3NN/022LND7SAP1A3A2NNIN/NNNNN
111.25.022.0C, SNP3NN/022RN01BAP1C7C7NNNN/NNNNN
111.25.337.0C, SNP3NN/022RN01BAP1CAC7NNNN/NNNNN
111.25.066.0C, SNP3NN/022RN01BAP1F5F5NNNN/NNNNN
111.25.341.0C, SNP3NN/022RN01BAP1F6F5NNNN/NNNNN
111.25.116.0C, SNP3NN/022RN01BDP1C7C7NNNN/NNNNN
111.25.156.0C, SNP3NN/022RN01FAP1C7C7NNNN/NNNNN
111.25.075.0C, SNP3NN/022RN06AAP1BBBANNNN/NNNNN
83020145, SNP3NN/022RN06AAP1C7C7NNNN/NNNNN
83017507, SNP3NN/022RN06DDP1BBBANNNN/NNNNN
111.25.046.0C, SNP3NN/022RN07GAP1A3A2NNNN/NNNNN
111.25.281.0C, SNP3NN/022RN07GAP1C7C7NNNN/NNNNN
111.25.128.0C, SNP3NN/022RN07GAP1E8E6NNNN/NNNNN
11057479, SNP3NN/022RN07SAP1A3A2NNNB/NNNNN
111.25.011.0C, SNP3NN/022RN07SAP1A3A2NNNN/NNNNN
111.25.364.0C, SNP3NN/022RN07SAP1BBBANNNE/NNNNN
111.25.085.0C, SNP3NN/022RN07SAP1BBBANNNN/NNNNN
111.25.001.0C, SNP3NN/022RN07SAP1C7C7NNNN/NNNNN
111.25.117.0C, SNP3NN/022RN07SAP1E8E6NNNN/NNNNN
111.25.303.0C, SNP3NN/022RN07SAP1F5F5NNNN/NNNNN
11037898, SNP3NN/022RN07SAP1F5F5NNNN/NNNVN
111.25.340.0C, SNP3NN/022RN07SAP1F6F5NNNN/NNNNN
11033986, SNP3NN/022RN07SAP1H9H8NNNB/NNNNN
111.25.148.0C, SNP3NN/022RN09SBP1A3A2NNNN/NNNNN
111.25.199.0C, SNP3NN/022RN09SBP1C7C7NNNN/NNNNN
11039730, SNP3NN/022RND7SAP1A3A2NNIN/NNNNN
111.25.360.0A, SNP3NN/026LN01BAP1C7C7NNNB/NNNNN
111.25.155.0A-02, SNP3NN/026LN01BAP1C7C7NNNN/NNNBN
111.25.023.0A, SNP3NN/026LN01BAP1C7C7NNNN/NNNNN
111.25.302.0A, SNP3NN/026LN01BAP1CAC7NNNN/NNNNN
111.25.313.0A, SNP3NN/026LN01BAP1E8E6NNNN/NNNNN
111.25.267.0A-02, SNP3NN/026LN01BAP1GAG7NNNN/NNNBN
111.25.295.0A, SNP3NN/026LN01BAP1GAG7NNNN/NNNNN
111.25.096.0A, SNP3NN/026LN01DAP1C7C7NNNN/NNNNN

111.25.291.0A, SNP3NN/026LN01DAP1F6F5NNNN/NNNNN
111.25.157.0A, SNP3NN/026LN01FAP1C7C7NNNN/NNNNN
83011868, SNP3NN/026LN02BAP1C7C7NNNN/NNNNN
111.25.076.0A, SNP3NN/026LN06AAP1BBBANNNN/NNNNN
111.25.035.0A, SNP3NN/026LN06CAP1BBBANNNN/NNNNN
111.25.217.0A, SNP3NN/026LN06DDP1BBBANNNN/NNNNN
83014170, SNP3NN/026LN07AAP1C7C7NNNN/NNNNN
111.25.047.0A, SNP3NN/026LN07GAP1A3A2NNNN/NNNNN
11054459, SNP3NN/026LN07GAP1BBBANNNN/NNNNN
111.25.129.0A, SNP3NN/026LN07GAP1E8E6NNNN/NNNNN
111.25.358.0A, SNP3NN/026LN07GAP1F5F5NNNN/NNNNN
83008641, SNP3NN/026LN07GBP1A3A2NNNN/NNNNN
11048929, SNP3NN/026LN07SAP1A3A2NNDN/NNNNN
111.25.354.0A, SNP3NN/026LN07SAP1A3A2NNDN/NNNNN
83017355, SNP3NN/026LN07SAP1A3A2NNNB/NNNNN
111.25.012.0A, SNP3NN/026LN07SAP1A3A2NNNN/NNNNN
111.25.086.0A, SNP3NN/026LN07SAP1BBBANNNN/NNNNN
111.25.002.0A, SNP3NN/026LN07SAP1C7C7NNNN/NNNNN
11043518, SNP3NN/026LN07SAP1E8E6NNNB/NNNNN
111.25.118.0A, SNP3NN/026LN07SAP1E8E6NNNN/NNNNN
111.25.353.0A, SNP3NN/026LN07SAP1E8E6NNNN/NNNNN
11029869, SNP3NN/026LN07SAP1F5F5NNNN/NNNNN
111.25.149.0A, SNP3NN/026LN09SBP1A3A2NNNN/NNNNN
11067163, SNP3NN/026LND7SAP1A3A2NNIN/NNNNN
111.25.292.0C, SNP3NN/026RN01BAP1BBBANNNN/NNNNN
111.25.023.0C, SNP3NN/026RN01BAP1C7C7NNNN/NNNNN
111.25.302.0C, SNP3NN/026RN01BAP1CAC7NNNN/NNNNN
111.25.067.0C, SNP3NN/026RN01BAP1F5F5NNNN/NNNNN
111.25.343.0C, SNP3NN/026RN01BAP1F6F5NNNN/NNNNN
111.25.157.0C, SNP3NN/026RN01FAP1C7C7NNNN/NNNNN
83014912, SNP3NN/026RN02BAP1A3A2NNNN/NNNNN
111.25.108.0C, SNP3NN/026RN02BAP1C7C7NNNN/NNNNN
111.25.076.0C, SNP3NN/026RN06AAP1BBBANNNN/NNNNN
111.25.047.0C, SNP3NN/026RN07GAP1A3A2NNNN/NNNNN
111.25.129.0C, SNP3NN/026RN07GAP1E8E6NNNN/NNNNN
111.25.012.0C, SNP3NN/026RN07SAP1A3A2NNNN/NNNNN
83018786, SNP3NN/026RN07SAP1BBBANNNDN/NNNNN
111.25.086.0C, SNP3NN/026RN07SAP1BBBANNNN/NNNNN
111.25.002.0C, SNP3NN/026RN07SAP1C7C7NNNN/NNNNN
111.25.032.0C, SNP3NN/026RN07SAP1CAC7NNNN/NNNNN
111.25.118.0C, SNP3NN/026RN07SAP1E8E6NNNN/NNNNN
111.25.304.0C, SNP3NN/026RN07SAP1F5F5NNNN/NNNNN
111.25.149.0C, SNP3NN/026RN09SBP1A3A2NNNN/NNNNN
111.25.200.0C, SNP3NN/026RN09SBP1C7C7NNNN/NNNNN
11068057, SNP3NN/026RND7SAP1A3A2NNIN/NNNNN
111.25.024.0A, SNP3NN/033LN01BAP1CAC7NNNN/NNNNN
111.25.068.0A, SNP3NN/033LN01BAP1F6F5NNNN/NNNNN
111.25.097.0A, SNP3NN/033LN01DAP1CAC7NNNN/NNNNN
111.25.158.0A, SNP3NN/033LN01FAP1CAC7NNNN/NNNNN
111.25.171.0A, SNP3NN/033LN01FAP1F6F5NNNN/NNNNN

111.25.109.0A, SNP3NN/033LN02BAP1CAC7NNNN/NNNNN
111.25.077.0A, SNP3NN/033LN06AAP1BBBANNNN/NNNNN
111.25.036.0A, SNP3NN/033LN06CAP1BBBANNNN/NNNNN
111.25.218.0A, SNP3NN/033LN06DDP1BBBANNNN/NNNNN
83010846, SNP3NN/033LN07BBP1A4A3NNNN/NNNNN
83018051, SNP3NN/033LN07BBP1F6F5NNNN/NNNNN
111.25.048.0A, SNP3NN/033LN07GAP1A4A3NNNN/NNNNN
111.25.130.0A, SNP3NN/033LN07GAP1E9E8NNNN/NNNNN
111.25.346.0A, SNP3NN/033LN07GAP1F6A2NNNN/NNNNN
111.25.359.0A, SNP3NN/033LN07GAP1F6F5NNNN/NNNNN
111.25.350.0A, SNP3NN/033LN07SAP1A4A3NNDN/NNNNN
111.25.013.0A, SNP3NN/033LN07SAP1A4A3NNNN/NNNNN
11043234, SNP3NN/033LN07SAP1A4A3NNNN/NNNWN
111.25.087.0A, SNP3NN/033LN07SAP1BBBANNNN/NNNNN
111.25.003.0A, SNP3NN/033LN07SAP1CAC7NNNN/NNNNN
111.25.119.0A, SNP3NN/033LN07SAP1E9E8NNNN/NNNNN
111.25.305.0A, SNP3NN/033LN07SAP1F6F5NNNN/NNNNN
111.25.150.0A, SNP3NN/033LN09SBP1A4A3NNNN/NNNNN
11106781, SNP3NN/033LND7SAP1A3A2NNIN/NNNNN
111.25.249.0C, SNP3NN/033R707SAP1CAC7NNNN/NNNNN
111.25.024.0C, SNP3NN/033RN01BAP1CAC7NNNN/NNNNN
83014061, SNP3NN/033RN01BAP1CACANNNN/NNNNN
111.25.068.0C, SNP3NN/033RN01BAP1F6F5NNNN/NNNNN
111.25.097.0C, SNP3NN/033RN01DAP1CAC7NNNN/NNNNN
111.25.158.0C, SNP3NN/033RN01FAP1CAC7NNNN/NNNNN
111.25.109.0C, SNP3NN/033RN02BAP1CAC7NNNN/NNNNN
111.25.362.0C, SNP3NN/033RN02DAP1CAC7NNNN/NNNNN
111.25.208.0C, SNP3NN/033RN02FAP1CAC7NNNN/NNNNN
111.25.077.0C, SNP3NN/033RN06AAP1BBBANNNN/NNNNN
111.25.323.0C, SNP3NN/033RN06AAP1F6F5NNNN/NNNNN
111.25.218.0C, SNP3NN/033RN06DDP1BBBANNNN/NNNNN
111.25.048.0C, SNP3NN/033RN07GAP1A4A3NNNN/NNNNN
111.25.130.0C, SNP3NN/033RN07GAP1E9E8NNNN/NNNNN
83017354, SNP3NN/033RN07SAP1A4A3NNNB/NNNNN
111.25.013.0C, SNP3NN/033RN07SAP1A4A3NNNN/NNNNN
111.25.087.0C, SNP3NN/033RN07SAP1BBBANNNN/NNNNN
111.25.003.0C, SNP3NN/033RN07SAP1CAC7NNNN/NNNNN
111.25.119.0C, SNP3NN/033RN07SAP1E9E8NNNN/NNNNN
111.25.305.0C, SNP3NN/033RN07SAP1F6F5NNNN/NNNNN
11062563, SNP3NN/033RN07SAP1F6F5NNNN/NNNWN
111.25.150.0C, SNP3NN/033RN09SBP1A4A3NNNN/NNNNN
111.25.201.0C, SNP3NN/033RN09SBP1CAC7NNNN/NNNNN
11106767, SNP3NN/033RND7SAP1A3A2NNIN/NNNNN
83010697, SNP3NN/033RND7SAP1A4A3NNIN/NNNNN
111.25.355.0A, SNP3NN/038LN01BAP1BBBANNNN/NNNNN
111.25.025.0A, SNP3NN/038LN01BAP1CAC7NNNN/NNNNN
111.25.314.0A, SNP3NN/038LN01BAP1E8E6NNNN/NNNNN
111.25.069.0A, SNP3NN/038LN01BAP1F6F5NNNN/NNNNN
111.25.098.0A, SNP3NN/038LN01DAP1CAC7NNNN/NNNNN
111.25.159.0A, SNP3NN/038LN01FAP1CAC7NNNN/NNNNN

111.25.172.0A, SNP3NN/038LN01FAP1F6F5NNNN/NNNNN
111.25.110.0A, SNP3NN/038LN02BAP1CAC7NNNN/NNNNN
83014541, SNP3NN/038LN02FAP1A4A3NNNN/NNNNN
111.25.059.0A, SNP3NN/038LN03BBP1CAC7NNNN/NNNNN
83007877, SNP3NN/038LN03BBP1F6F5NNNN/NNNNN
111.25.078.0A, SNP3NN/038LN06AAP1BBBANNNN/NNNNN
111.25.037.0A, SNP3NN/038LN06CAP1BBBANNNN/NNNNN
83014247, SNP3NN/038LN06DDP1BBBANNNN/NNNNN
111.25.049.0A, SNP3NN/038LN07GAP1A4A3NNNN/NNNNN
111.25.131.0A, SNP3NN/038LN07GAP1E9E8NNNN/NNNNN
111.25.348.0A, SNP3NN/038LN07SAP1A4A3NNDN/NNNNN
111.25.014.0A, SNP3NN/038LN07SAP1A4A3NNNN/NNNNN
11041668, SNP3NN/038LN07SAP1A4A3NNNN/NNNWN
11084057, SNP3NN/038LN07SAP1BBBANNNN/NNNKN
111.25.088.0A, SNP3NN/038LN07SAP1BBBANNNN/NNNNN
111.25.004.0A, SNP3NN/038LN07SAP1CAC7NNNN/NNNNN
111.25.105.0A, SNP3NN/038LN07SAP1E9E6NNNN/NNNNN
111.25.151.0A, SNP3NN/038LN09SBP1A4A3NNNN/NNNNN
111.25.250.0C, SNP3NN/038R707SAP1CAC7NNNN/NNNNN
111.25.232.0C, SNP3NN/038RN01BAP1A4A3NNNN/NNNNN
111.25.025.0C, SNP3NN/038RN01BAP1CAC7NNNN/NNNNN
111.25.069.0C, SNP3NN/038RN01BAP1F6F5NNNN/NNNNN
83017866, SNP3NN/038RN01DAP1CAC7NNNN/NNNNN
111.25.159.0C, SNP3NN/038RN01FAP1CAC7NNNN/NNNNN
111.25.242.0C, SNP3NN/038RN02BAP1F6F5NNNN/NNNNN
111.25.078.0C, SNP3NN/038RN06AAP1BBBANNNN/NNNNN
111.25.219.0C, SNP3NN/038RN06DDP1BBBANNNN/NNNNN
111.25.049.0C, SNP3NN/038RN07GAP1A4A3NNNN/NNNNN
111.25.131.0C, SNP3NN/038RN07GAP1E9E8NNNN/NNNNN
111.25.014.0C, SNP3NN/038RN07SAP1A4A3NNNN/NNNNN
11084058, SNP3NN/038RN07SAP1BBBANNNN/NNNKN
111.25.088.0C, SNP3NN/038RN07SAP1BBBANNNN/NNNNN
111.25.004.0C, SNP3NN/038RN07SAP1CAC7NNNN/NNNNN
111.25.105.0C, SNP3NN/038RN07SAP1E9E6NNNN/NNNNN
111.25.120.0C, SNP3NN/038RN07SAP1E9E8NNNN/NNNNN
11052145, SNP3NN/038RN07SAP1F6F6NNNN/NNNNN
111.25.151.0C, SNP3NN/038RN09SBP1A4A3NNNN/NNNNN
111.25.202.0C, SNP3NN/038RN09SBP1CAC7NNNN/NNNNN
111.25.339.0A, SNP3NN/044LN01BAP1CAC7NNNN/NNNNN
111.25.026.0A, SNP3NN/044LN01BAP1CACANNNN/NNNNN
111.25.070.0A, SNP3NN/044LN01BAP1F6F6NNNN/NNNNN
111.25.099.0A, SNP3NN/044LN01DAP1CACANNNN/NNNNN
111.25.160.0A, SNP3NN/044LN01FAP1CACANNNN/NNNNN
111.25.111.0A, SNP3NN/044LN02BAP1CACANNNN/NNNNN
111.25.243.0A, SNP3NN/044LN02BAP1F6F6NNNN/NNNNN
111.25.210.0A, SNP3NN/044LN02FAP1CACANNNN/NNNNN
111.25.269.0A-02, SNP3NN/044LN03BBP1CACANNNN/NNNDA
111.25.060.0A, SNP3NN/044LN03BBP1CACANNNN/NNNNN
111.25.257.0A, SNP3NN/044LN03BBP1F6F6NNNN/NNNNN
111.25.275.0A, SNP3NN/044LN03FBP1CACANNNN/NNNNN

111.25.079.0A, SNP3NN/044LN06AAP1BBBANNNN/NNNNN
111.25.038.0A, SNP3NN/044LN06CAP1BBBANNNN/NNNNN
111.25.220.0A, SNP3NN/044LN06DDP1BBBANNNN/NNNNN
111.25.345.0A, SNP3NN/044LN07BBP1CACANNNN/NNNNN
111.25.050.0A, SNP3NN/044LN07GAP1A4A3NNNN/NNNNN
111.25.349.0A, SNP3NN/044LN07SAP1A4A3NNDN/NNNNN
83017356, SNP3NN/044LN07SAP1A4A3NNNB/NNNNN
111.25.015.0A, SNP3NN/044LN07SAP1A4A3NNNN/NNNNN
111.25.089.0A, SNP3NN/044LN07SAP1BBBANNNN/NNNNN
111.25.005.0A, SNP3NN/044LN07SAP1CACANNNN/NNNNN
111.25.121.0A, SNP3NN/044LN07SAP1E9E8NNNN/NNNNN
111.25.315.0A, SNP3NN/044LN07SAP1F6F5NNNN/NNNNN
83008627, SNP3NN/044LN09SBP1F6F6NNNN/NNNNN
111.25.026.0C, SNP3NN/044RN01BAP1CACANNNN/NNNNN
111.25.342.0C, SNP3NN/044RN01BAP1F6F5NNNN/NNNNN
111.25.070.0C, SNP3NN/044RN01BAP1F6F6NNNN/NNNNN
111.25.099.0C, SNP3NN/044RN01DAP1CACANNNN/NNNNN
111.25.160.0C, SNP3NN/044RN01FAP1CACANNNN/NNNNN
111.25.111.0C, SNP3NN/044RN02BAP1CACANNNN/NNNNN
111.25.243.0C, SNP3NN/044RN02BAP1F6F6NNNN/NNNNN
111.25.210.0C, SNP3NN/044RN02FAP1CACANNNN/NNNNN
111.25.060.0C, SNP3NN/044RN03BBP1CACANNNN/NNNNN
111.25.257.0C, SNP3NN/044RN03BBP1F6F6NNNN/NNNNN
111.25.275.0C, SNP3NN/044RN03FBP1CACANNNN/NNNNN
111.25.079.0C, SNP3NN/044RN06AAP1BBBANNNN/NNNNN
111.25.220.0C, SNP3NN/044RN06DDP1BBBANNNN/NNNNN
111.25.050.0C, SNP3NN/044RN07GAP1A4A3NNNN/NNNNN
83008098, SNP3NN/044RN07GAP1CACANNNN/NNNNN
111.25.132.0C, SNP3NN/044RN07GAP1E9E8NNNN/NNNNN
111.25.349.0C, SNP3NN/044RN07SAP1A4A3NNDN/NNNNN
111.25.325.0C, SNP3NN/044RN07SAP1A4A3NNNB/NNNNN
111.25.015.0C, SNP3NN/044RN07SAP1A4A3NNNN/NNNNN
11084059, SNP3NN/044RN07SAP1BBBANNNN/NNNKN
111.25.089.0C, SNP3NN/044RN07SAP1BBBANNNN/NNNNN
111.25.005.0C, SNP3NN/044RN07SAP1CACANNNN/NNNNN
111.25.363.0C, SNP3NN/044RN07SAP1E9E6NNNN/NNNNN
111.25.121.0C, SNP3NN/044RN07SAP1E9E8NNNN/NNNNN
11042715, SNP3NN/044RN07SAP1F6F6NNNN/NNNNN
83014858, SNP3NN/044RN09SBP1BBBANNNN/NNNNN
111.25.203.0C, SNP3NN/044RN09SBP1CACANNNN/NNNNN
111.25.317.0C, SNP3NN/044RN09SBP1F6F6NNNN/NNNNN
111.25.027.0A, SNP3NN/048LN01BAP1CACANNNN/NNNNN
111.25.045.0A, SNP3NN/048LN01BAP1F6F6NNNN/NNNNN
111.25.100.0A, SNP3NN/048LN01DAP1CACANNNN/NNNNN
111.25.161.0A, SNP3NN/048LN01FAP1CACANNNN/NNNNN
111.25.061.0A, SNP3NN/048LN03BBP1CACANNNN/NNNNN
111.25.276.0A, SNP3NN/048LN03FBP1CACANNNN/NNNNN
111.25.080.0A, SNP3NN/048LN06AAP1BBBANNNN/NNNNN
11055390, SNP3NN/048LN07GAP1A4A3NNNN/NNNNN
111.25.133.0A, SNP3NN/048LN07GAP1E9E8NNNN/NNNNN

111.25.016.0A, SNP3NN/048LN07SAP1A4A3NNNN/NNNNN
111.25.090.0A, SNP3NN/048LN07SAP1BBBANNNN/NNNNN
111.25.006.0A, SNP3NN/048LN07SAP1CACANNNN/NNNNN
111.25.122.0A, SNP3NN/048LN07SAP1E9E8NNNN/NNNNN
111.25.316.0A, SNP3NN/048LN07SAP1F6F5NNNN/NNNNN
111.25.027.0C, SNP3NN/048RN01BAP1CACANNNN/NNNNN
111.25.326.0C, SNP3NN/048RN01BAP1F6F5NNNN/NNNNN
111.25.045.0C, SNP3NN/048RN01BAP1F6F6NNNN/NNNNN
111.25.161.0C, SNP3NN/048RN01FAP1CACANNNN/NNNNN
111.25.061.0C, SNP3NN/048RN03BBP1CACANNNN/NNNNN
111.25.080.0C, SNP3NN/048RN06AAP1BBBANNNN/NNNNN
111.25.324.0C, SNP3NN/048RN06AAP1F6F5NNNN/NNNNN
111.25.051.0C, SNP3NN/048RN07GAP1A4A3NNNN/NNNNN
111.25.133.0C, SNP3NN/048RN07GAP1E9E8NNNN/NNNNN
111.25.365.0C, SNP3NN/048RN07SAP1A4A3NNDN/NNNNN
111.25.016.0C, SNP3NN/048RN07SAP1A4A3NNNN/NNNNN
111.25.090.0C, SNP3NN/048RN07SAP1BBBANNNN/NNNNN
83009059, SNP3NN/048RN07SAP1CACANNNB/NNNNN
111.25.006.0C, SNP3NN/048RN07SAP1CACANNNN/NNNNN
111.25.122.0C, SNP3NN/048RN07SAP1E9E8NNNN/NNNNN
111.25.316.0C, SNP3NN/048RN07SAP1F6F5NNNN/NNNNN
111.25.033.0A, SNP3NN/050LN07GAP1A5A3NNNN/NNNNN
111.25.028.0A, SNP3NN/055LN01BAP1CACANNNN/NNNNN
111.25.322.0A, SNP3NN/055LN01BAP1EAE9NNNN/NNNNN
11031261, SNP3NN/055LN01BAP1F6F6NNNN/NNNNN
111.25.101.0A, SNP3NN/055LN01DAP1CACANNNN/NNNNN
83020356, SNP3NN/055LN01FAP1CACANNNN/NNNNN
111.25.113.0A, SNP3NN/055LN02BAP1CACANNNN/NNNNN
11035500, SNP3NN/055LN02FAP1F6F6NNNN/NNNNN
111.25.062.0A, SNP3NN/055LN03BBP1CACANNNN/NNNNN
11037166, SNP3NN/055LN03FBP1F6F6NNNN/NNNNN
111.25.081.0A, SNP3NN/055LN06AAP1BBBANNNN/NNNNN
11031893, SNP3NN/055LN06DDP1BBBANNNN/NNNNN
111.25.052.0A, SNP3NN/055LN07GAP1A5A4NNNN/NNNNN
111.25.106.0A, SNP3NN/055LN07SAP1A5A4NNDN/NNNNN
83017357, SNP3NN/055LN07SAP1A5A4NNNB/NNNNN
111.25.017.0A, SNP3NN/055LN07SAP1A5A4NNNN/NNNNN
111.25.091.0A, SNP3NN/055LN07SAP1BBBANNNN/NNNNN
11062580, SNP3NN/055LN07SAP1BBBANNNN/NNNWN
111.25.167.0A, SNP3NN/055LN07SAP1CAC7NNNN/NNNNN
111.25.007.0A, SNP3NN/055LN07SAP1CACANNNN/NNNNN
111.25.123.0A, SNP3NN/055LN07SAP1EAE9NNNN/NNNNN
83010686, SNP3NN/055LN07SAP1F6F5NNNN/NNNNN
111.25.168.0C, SNP3NN/055R707SAP1CACANNNN/NNNNN
111.25.356.0C, SNP3NN/055RN01BAP1BBBANNNN/NNNNN
111.25.028.0C, SNP3NN/055RN01BAP1CACANNNN/NNNNN
111.25.318.0C, SNP3NN/055RN01BAP1E8E6NNNN/NNNNN
111.25.357.0C, SNP3NN/055RN01BAP1F6F5NNNN/NNNNN
111.25.071.0C, SNP3NN/055RN01BAP1F6F6NNNN/NNNNN
111.25.101.0C, SNP3NN/055RN01DAP1CACANNNN/NNNNN

111.25.162.0C, SNP3NN/055RN01FAP1CACANNNN/NNNNN
111.25.113.0C, SNP3NN/055RN02BAP1CACANNNN/NNNNN
111.25.245.0C, SNP3NN/055RN02BAP1F6F6NNNN/NNNNN
111.25.212.0C, SNP3NN/055RN02FAP1CACANNNN/NNNNN
111.25.062.0C, SNP3NN/055RN03BBP1CACANNNN/NNNNN
111.25.081.0C, SNP3NN/055RN06AAP1BBBANNNN/NNNNN
111.25.222.0C, SNP3NN/055RN06DDP1BBBANNNN/NNNNN
111.25.052.0C, SNP3NN/055RN07GAP1A5A4NNNN/NNNNN
111.25.134.0C, SNP3NN/055RN07GAP1EAE9NNNN/NNNNN
111.25.106.0C, SNP3NN/055RN07SAP1A5A4NNDN/NNNNN
111.25.017.0C, SNP3NN/055RN07SAP1A5A4NNNN/NNNNN
111.25.091.0C, SNP3NN/055RN07SAP1BBBANNNN/NNNNN
83007902, SNP3NN/055RN07SAP1BBBANNNN/NNNWN
111.25.268.0C-02, SNP3NN/055RN07SAP1CACANNNN/NNNDA
111.25.007.0C, SNP3NN/055RN07SAP1CACANNNN/NNNNN
11034671, SNP3NN/055RN07SAP1EAE9NNNN/NNNNN
111.25.347.0C, SNP3NN/055RN07SAP1F6F5NNNN/NNNNN
111.25.029.0A, SNP3NN/063LN01BAP1CDCANNNN/NNNNN
111.25.102.0A, SNP3NN/063LN01DAP1CDCANNNN/NNNNN
111.25.163.0A, SNP3NN/063LN01FAP1CDCANNNN/NNNNN
111.25.186.0A, SNP3NN/063LN02FAP1F7F6NNNN/NNNNN
111.25.063.0A, SNP3NN/063LN03BBP1CDCANNNN/NNNNN
111.25.082.0A, SNP3NN/063LN06AAP1BCBBNNNN/NNNNN
111.25.053.0A, SNP3NN/063LN07GAP1A5A4NNNN/NNNNN
111.25.018.0A, SNP3NN/063LN07SAP1A5A4NNNN/NNNNN
111.25.092.0A, SNP3NN/063LN07SAP1BCBBNNNN/NNNNN
111.25.008.0A, SNP3NN/063LN07SAP1CDCANNNN/NNNNN
111.25.124.0A, SNP3NN/063LN07SAP1EAE9NNNN/NNNNN
83010684, SNP3NN/063LN07SAP1F7F6NNNN/NNNNN
111.25.029.0C, SNP3NN/063RN01BAP1CDCANNNN/NNNNN
111.25.361.0C, SNP3NN/063RN01BAP1EAE9NNNN/NNNNN
111.25.072.0C, SNP3NN/063RN01BAP1F7F6NNNN/NNNNN
111.25.163.0C, SNP3NN/063RN01FAP1CDCANNNN/NNNNN
111.25.114.0C, SNP3NN/063RN02BAP1CDCANNNN/NNNNN
111.25.246.0C, SNP3NN/063RN02BAP1F7F6NNNN/NNNNN
111.25.213.0C, SNP3NN/063RN02FAP1CDCANNNN/NNNNN
111.25.063.0C, SNP3NN/063RN03BBP1CDCANNNN/NNNNN
111.25.260.0C, SNP3NN/063RN03BBP1F7F6NNNN/NNNNN
83012154, SNP3NN/063RN03FBP1CDCANNNN/NNNNN
111.25.082.0C, SNP3NN/063RN06AAP1BCBBNNNN/NNNNN
111.25.053.0C, SNP3NN/063RN07GAP1A5A4NNNN/NNNNN
111.25.135.0C, SNP3NN/063RN07GAP1EAE9NNNN/NNNNN
111.25.344.0C, SNP3NN/063RN07GAP1F7F6NNNN/NNNNN
111.25.018.0C, SNP3NN/063RN07SAP1A5A4NNNN/NNNNN
111.25.092.0C, SNP3NN/063RN07SAP1BCBBNNNN/NNNNN
111.25.008.0C, SNP3NN/063RN07SAP1CDCANNNN/NNNNN
111.25.124.0C, SNP3NN/063RN07SAP1EAE9NNNN/NNNNN
83010685, SNP3NN/063RN07SAP1F7F6NNNN/NNNNN
111.25.145.0C, SNP3NN/063RN08RAP1A5A4NNNN/NNNNN
111.25.030.0A, SNP3NN/075LN01BAP1CDCANNNN/NNNNN

111.25.103.0A, SNP3NN/075LN01DAP1CDCANNNN/NNNNN
111.25.164.0A, SNP3NN/075LN01FAP1CDCANNNN/NNNNN
83009542, SNP3NN/075LN02BAP1CDCANNNN/NNNNN
111.25.064.0A, SNP3NN/075LN03BBP1CDCANNNN/NNNNN
111.25.279.0A, SNP3NN/075LN03FBP1CDCANNNN/NNNNN
111.25.054.0A, SNP3NN/075LN07GAP1A5A4NNNN/NNNNN
111.25.019.0A, SNP3NN/075LN07SAP1A5A4NNNN/NNNNN
111.25.093.0A, SNP3NN/075LN07SAP1BCBBNNNN/NNNNN
111.25.009.0A, SNP3NN/075LN07SAP1CDCANNNN/NNNNN
11053569, SNP3NN/075LN07SAP1F7F6NNNN/NNNNN
111.25.030.0C, SNP3NN/075RN01BAP1CDCANNNN/NNNNN
111.25.073.0C, SNP3NN/075RN01BAP1F7F6NNNN/NNNNN
111.25.164.0C, SNP3NN/075RN01FAP1CDCANNNN/NNNNN
83012424, SNP3NN/075RN02BAP1CDCANNDN/NNNNN
111.25.115.0C, SNP3NN/075RN02BAP1CDCANNNN/NNNNN
111.25.064.0C, SNP3NN/075RN03BBP1CDCANNNN/NNNNN
111.25.261.0C, SNP3NN/075RN03BBP1F7F6NNNN/NNNNN
111.25.083.0C, SNP3NN/075RN06AAP1BCBBNNNN/NNNNN
111.25.054.0C, SNP3NN/075RN07GAP1A5A4NNNN/NNNNN
111.25.019.0C, SNP3NN/075RN07SAP1A5A4NNNN/NNNNN
111.25.093.0C, SNP3NN/075RN07SAP1BCBBNNNN/NNNNN
111.25.009.0C, SNP3NN/075RN07SAP1CDCANNNN/NNNNN
111.25.338.0C, SNP3NN/075RN07SAP1EAE8NNNN/NNNNN
11084004, SNP3NN/075RN07SAP1EAE9NNNN/NNNNN
83013228, SNP3NN/075RN07SAP1F7F6NNNN/NNNNN
111.25.031.0A, SNP3NN/090LN01BAP1CDCANNNN/NNNNN
83016970, SNP3NN/090LN01FAP1F7F6NNNN/NNNNN
111.25.065.0A, SNP3NN/090LN03BBP1CDCANNNN/NNNNN
111.25.055.0A, SNP3NN/090LN07GAP1A5A4NNNN/NNNNN
111.25.020.0A, SNP3NN/090LN07SAP1A5A4NNNN/NNNNN
111.25.010.0A, SNP3NN/090LN07SAP1CDCANNNN/NNNNN
111.25.031.0C, SNP3NN/090RN01BAP1CDCANNNN/NNNNN
111.25.165.0C, SNP3NN/090RN01FAP1CDCANNNN/NNNNN
83012423, SNP3NN/090RN02BAP1CDCANNDN/NNNNN
111.25.065.0C, SNP3NN/090RN03BBP1CDCANNNN/NNNNN
111.25.262.0C, SNP3NN/090RN03BBP1F7F6NNNN/NNNNN
111.25.055.0C, SNP3NN/090RN07GAP1A5A4NNNN/NNNNN
83018912, SNP3NN/090RN07SAP1A5A4NNDN/NNNNN
111.25.020.0C, SNP3NN/090RN07SAP1A5A4NNNN/NNNNN
111.25.094.0C, SNP3NN/090RN07SAP1BCBBNNNN/NNNNN
111.25.010.0C, SNP3NN/090RN07SAP1CDCANNNN/NNNNN
83011479, SNP3NN/090RN07SAP1EAE9NNNN/NNNNN
211.10.139.00, SNQ1NN/1,2LN11DEP1C2C2NNNN/NNNNN
211.10.045.00, SNQ1NN/1,2LN11DEP1F3F3NNNN/NNNNN
211.10.009.00, SNQ1NN/1,2LN21DEP1C2C2NNNN/NNNNN
211.10.195.00, SNQ1NN/1,2LN21DEP1E4E3NNNN/NNNNN
211.10.082.00, SNQ1NN/1,2LN21DEP1F3F3NNNN/NNNNN
211.10.289.00, SNQ1NN/1,2LN31DEP1C2C2NNNN/NNNNN
83023140, SNQ1NN/1,2R421DEP1NNE3NNNN/NNNNN
211.10.138.00, SNQ1NN/1,2RN11DEP1C2C2NNNN/NNNNN

211.10.044.00, SNQ1NN/1,2RN11DEP1F3F3NNNN/NNNNN
83017957, SNQ1NN/1,2RN21DEP1B2B1NNNN/NNNNN
211.10.008.00, SNQ1NN/1,2RN21DEP1C2C2NNNN/NNNNN
211.10.194.00, SNQ1NN/1,2RN21DEP1E4E3NNNN/NNNNN
211.10.081.00, SNQ1NN/1,2RN21DEP1F3F3NNNN/NNNNN
211.10.288.00, SNQ1NN/1,2RN31DEP1C2C2NNNN/NNNNN
83013165, SNQ1NN/1,7LN11DEP1B2B1NNNN/NNNNN
211.10.141.00, SNQ1NN/1,7LN11DEP1C2C2NNNN/NNNNN
211.10.047.00, SNQ1NN/1,7LN11DEP1F3F3NNNN/NNNNN
211.10.011.00, SNQ1NN/1,7LN21DEP1C2C2NNNN/NNNNN
211.10.197.00, SNQ1NN/1,7LN21DEP1E4E3NNNN/NNNNN
211.10.084.00, SNQ1NN/1,7LN21DEP1F3F3NNNN/NNNNN
211.10.156.00, SNQ1NN/1,7LN21DEP1F4F3NNNN/NNNNN
211.10.291.00, SNQ1NN/1,7LN31DEP1C2C2NNNN/NNNNN
211.10.140.00, SNQ1NN/1,7RN11DEP1C2C2NNNN/NNNNN
211.10.046.00, SNQ1NN/1,7RN11DEP1F3F3NNNN/NNNNN
211.10.313.00, SNQ1NN/1,7RN21DEP1B2B1NNNN/NNNNN
211.10.010.00, SNQ1NN/1,7RN21DEP1C2C2NNNN/NNNNN
211.10.083.00, SNQ1NN/1,7RN21DEP1F3F3NNNN/NNNNN
211.10.290.00, SNQ1NN/1,7RN31DEP1C2C2NNNN/NNNNN
211.10.143.00, SNQ1NN/2,2LN11DEP1C2C2NNNN/NNNNN
211.10.049.00, SNQ1NN/2,2LN11DEP1F3F3NNNN/NNNNN
11059052, SNQ1NN/2,2LN21DEP1B2B1NNNN/NNNNN
211.10.013.00, SNQ1NN/2,2LN21DEP1C2C2NNNN/NNNNN
211.10.086.00, SNQ1NN/2,2LN21DEP1F3F3NNNN/NNNNN
211.10.293.00, SNQ1NN/2,2LN31DEP1C2C2NNNN/NNNNN
211.10.066.00, SNQ1NN/2,2R421DEP1NNE3NNNN/NNNNN
211.10.142.00, SNQ1NN/2,2RN11DEP1C2C2NNNN/NNNNN
211.10.048.00, SNQ1NN/2,2RN11DEP1F3F3NNNN/NNNNN
83006945, SNQ1NN/2,2RN21DEP1B2B1NNNN/NNNNN
211.10.012.00, SNQ1NN/2,2RN21DEP1C2C2NNNN/NNNNN
211.10.198.00, SNQ1NN/2,2RN21DEP1E4E3NNNN/NNNNN
211.10.085.00, SNQ1NN/2,2RN21DEP1F3F3NNNN/NNNNN
211.10.292.00, SNQ1NN/2,2RN31DEP1C2C2NNNN/NNNNN
211.10.315.00, SNQ1NN/2,6LN11DEP1B2B1NNNN/NNNNN
211.10.145.00, SNQ1NN/2,6LN11DEP1C2C2NNNN/NNNNN
211.10.051.00, SNQ1NN/2,6LN11DEP1F3F3NNNN/NNNNN
211.10.015.00, SNQ1NN/2,6LN21DEP1C2C2NNNN/NNNNN
11036608, SNQ1NN/2,6LN21DEP1E4E3NNNN/NNNNN
211.10.088.00, SNQ1NN/2,6LN21DEP1F3F3NNNN/NNNNN
211.10.295.00, SNQ1NN/2,6LN31DEP1C2C2NNNN/NNNNN
211.10.181.00, SNQ1NN/2,6R411DEP1B2B1YYNN/NNNNN
11071218, SNQ1NN/2,6R421DEP1NNE3NNNN/NNNNN
211.10.144.00, SNQ1NN/2,6RN11DEP1C2C2NNNN/NNNNN
83019017, SNQ1NN/2,6RN11DEP1C3C3NNNN/NNNNN
211.10.050.00, SNQ1NN/2,6RN11DEP1F3F3NNNN/NNNNN
211.10.014.00, SNQ1NN/2,6RN21DEP1C2C2NNNN/NNNNN
211.10.200.00, SNQ1NN/2,6RN21DEP1E4E3NNNN/NNNNN
211.10.087.00, SNQ1NN/2,6RN21DEP1F3F3NNNN/NNNNN
211.10.294.00, SNQ1NN/2,6RN31DEP1C2C2NNNN/NNNNN

211.10.147.00, SNQ1NN/3,2LN11DEP1C2C2NNNN/NNNNN
211.10.053.00, SNQ1NN/3,2LN11DEP1F3F3NNNN/NNNNN
211.10.308.00, SNQ1NN/3,2LN21DEP1B2B1NNNN/NNNNN
211.10.017.00, SNQ1NN/3,2LN21DEP1C2C2NNNN/NNNNN
211.10.090.00, SNQ1NN/3,2LN21DEP1F3F3NNNN/NNNNN
211.10.297.00, SNQ1NN/3,2LN31DEP1C2C2NNNN/NNNNN
11079776, SNQ1NN/3,2R421DEP1NNE3NNNN/NNNNN
211.10.146.00, SNQ1NN/3,2RN11DEP1C2C2NNNN/NNNNN
211.10.052.00, SNQ1NN/3,2RN11DEP1F3F3NNNN/NNNNN
83022348, SNQ1NN/3,2RN21DEP1B2B1NNBN/NNNNN
11060767, SNQ1NN/3,2RN21DEP1B2B1NNNN/NNNNN
211.10.016.00, SNQ1NN/3,2RN21DEP1C2C2NNNN/NNNNN
211.10.202.00, SNQ1NN/3,2RN21DEP1E4E3NNNN/NNNNN
211.10.089.00, SNQ1NN/3,2RN21DEP1F3F3NNNN/NNNNN
211.10.296.00, SNQ1NN/3,2RN31DEP1C2C2NNNN/NNNNN
211.10.149.00, SNQ1NN/3,8LN11DEP1C2C2NNNN/NNNNN
211.10.055.00, SNQ1NN/3,8LN11DEP1F3F3NNNN/NNNNN
211.10.019.00, SNQ1NN/3,8LN21DEP1C2C2NNNN/NNNNN
211.10.092.00, SNQ1NN/3,8LN21DEP1F3F3NNNN/NNNNN
11055858, SNQ1NN/3,8LN21DEP1H7H5NNNB/NNNNN
211.10.316.00, SNQ1NN/3,8LN21DEP1H7H5NNNN/NNNNN
211.10.299.00, SNQ1NN/3,8LN31DEP1C2C2NNNN/NNNNN
211.10.148.00, SNQ1NN/3,8RN11DEP1C2C2NNNN/NNNNN
211.10.054.00, SNQ1NN/3,8RN11DEP1F3F3NNNN/NNNNN
211.10.018.00, SNQ1NN/3,8RN21DEP1C2C2NNNN/NNNNN
211.10.091.00, SNQ1NN/3,8RN21DEP1F3F3NNNN/NNNNN
211.10.298.00, SNQ1NN/3,8RN31DEP1C2C2NNNN/NNNNN
211.10.151.00, SNQ1NN/4,3LN11DEP1C2C2NNNN/NNNNN
211.10.057.00, SNQ1NN/4,3LN11DEP1F3F3NNNN/NNNNN
83008293, SNQ1NN/4,3LN21DEP1B2B1NNNN/NNNNN
211.10.021.00, SNQ1NN/4,3LN21DEP1C2C2NNNN/NNNNN
211.10.094.00, SNQ1NN/4,3LN21DEP1F3F3NNNN/NNNNN
211.10.301.00, SNQ1NN/4,3LN31DEP1C2C2NNNN/NNNNN
211.10.074.00, SNQ1NN/4,3R421DEP1NNE3NNNN/NNNNN
211.10.150.00, SNQ1NN/4,3RN11DEP1C2C2NNNN/NNNNN
211.10.056.00, SNQ1NN/4,3RN11DEP1F3F3NNNN/NNNNN
211.10.309.00, SNQ1NN/4,3RN21DEP1B2B1NNNN/NNNNN
211.10.020.00, SNQ1NN/4,3RN21DEP1C2C2NNNN/NNNNN
211.10.093.00, SNQ1NN/4,3RN21DEP1F3F3NNNN/NNNNN
211.10.300.00, SNQ1NN/4,3RN31DEP1C2C2NNNN/NNNNN
211.10.059.00, SNQ1NN/6,0LN11DEP1F3F3NNNN/NNNNN
211.10.023.00, SNQ1NN/6,0LN21DEP1C2C2NNNN/NNNNN
211.10.096.00, SNQ1NN/6,0LN21DEP1F3F3NNNN/NNNNN
211.10.303.00, SNQ1NN/6,0LN31DEP1C2C2NNNN/NNNNN
211.10.312.00, SNQ1NN/6,0RN11DEP1B2B2NNNN/NNNNN
211.10.152.00, SNQ1NN/6,0RN11DEP1C2C2NNNN/NNNNN
211.10.058.00, SNQ1NN/6,0RN11DEP1F3F3NNNN/NNNNN
211.10.022.00, SNQ1NN/6,0RN21DEP1C2C2NNNN/NNNNN
211.10.095.00, SNQ1NN/6,0RN21DEP1F3F3NNNN/NNNNN
211.10.302.00, SNQ1NN/6,0RN31DEP1C2C2NNNN/NNNNN

211.10.155.00, SNQ1NN/7,8LN11DEP1C2C2NNNN/NNNNN
211.10.118.00, SNQ1NN/7,8LN11DEP1E5E4NNNN/NNNNN
211.10.061.00, SNQ1NN/7,8LN11DEP1F3F3NNNN/NNNNN
211.10.025.00, SNQ1NN/7,8LN21DEP1C2C2NNNN/NNNNN
211.10.098.00, SNQ1NN/7,8LN21DEP1F3F3NNNN/NNNNN
211.10.305.00, SNQ1NN/7,8LN31DEP1C2C2NNNN/NNNNN
211.10.154.00, SNQ1NN/7,8RN11DEP1C2C2NNNN/NNNNN
211.10.060.00, SNQ1NN/7,8RN11DEP1F3F3NNNN/NNNNN
211.10.024.00, SNQ1NN/7,8RN21DEP1C2C2NNNN/NNNNN
211.10.097.00, SNQ1NN/7,8RN21DEP1F3F3NNNN/NNNNN
211.10.304.00, SNQ1NN/7,8RN31DEP1C2C2NNNN/NNNNN
211.25.025.0A, SNQ3NN/022LN11DBP1A3A2NNNN/NNNNN
211.25.058.0A, SNQ3NN/022LN11DBP1BBBANNNN/NNNNN
211.25.093.0A, SNQ3NN/022LN11DBP1C7C7NNNN/NNNNN
211.25.226.0A, SNQ3NN/022LN11DBP1E8E6NNNN/NNNNN
211.25.236.0A, SNQ3NN/022LN11DBP1F5F5NNNN/NNNNN
11106939, SNQ3NN/022LN11DBP1MFMFNNNN/NNNNN
211.25.417.0C, SNQ3NN/022RN11DBP1A3A2NNNB/NNNCN
211.25.025.0C, SNQ3NN/022RN11DBP1A3A2NNNN/NNNNN
211.25.058.0C, SNQ3NN/022RN11DBP1BBBANNNN/NNNNN
211.25.093.0C, SNQ3NN/022RN11DBP1C7C7NNNN/NNNNN
211.25.226.0C, SNQ3NN/022RN11DBP1E8E6NNNN/NNNNN
211.25.236.0C, SNQ3NN/022RN11DBP1F5F5NNNN/NNNNN
211.25.026.0A, SNQ3NN/026LN11DBP1A3A2NNNN/NNNNN
211.25.059.0A, SNQ3NN/026LN11DBP1BBBANNNN/NNNNN
211.25.094.0A, SNQ3NN/026LN11DBP1C7C7NNNN/NNNNN
11048363, SNQ3NN/026LN11DBP1E8E6NNNB/NNNNN
211.25.227.0A, SNQ3NN/026LN11DBP1E8E6NNNN/NNNNN
211.25.237.0A, SNQ3NN/026LN11DBP1F5F5NNNN/NNNNN
211.25.421.0A, SNQ3NN/026LN11DBP1F6F5NNNN/NNNNN
11039366, SNQ3NN/026LN11DBP1H9H8NNNN/NNNNN
211.25.246.0C, SNQ3NN/026R8V3DEP1E9E6NNNN/NNNNN
211.25.343.0C, SNQ3NN/026RN11DBP1A3A2NNNN/NNNEN
211.25.026.0C, SNQ3NN/026RN11DBP1A3A2NNNN/NNNNN
211.25.059.0C, SNQ3NN/026RN11DBP1BBBANNNN/NNNNN
211.25.280.0C, SNQ3NN/026RN11DBP1BBBANNNN/NNNZN
211.25.094.0C, SNQ3NN/026RN11DBP1C7C7NNNN/NNNNN
211.25.227.0C, SNQ3NN/026RN11DBP1E8E6NNNN/NNNNN
211.25.237.0C, SNQ3NN/026RN11DBP1F5F5NNNN/NNNNN
83010844, SNQ3NN/033LN11DBP1A4A3NNNB/NNNNN
211.25.027.0A, SNQ3NN/033LN11DBP1A4A3NNNN/NNNNN
211.25.060.0A, SNQ3NN/033LN11DBP1BBBANNNN/NNNNN
83009018, SNQ3NN/033LN11DBP1CAC7NNNB/NNNNN
211.25.095.0A, SNQ3NN/033LN11DBP1CAC7NNNN/NNNNN
11060573, SNQ3NN/033LN11DBP1E8E6NNNB/NNNNN
211.25.238.0A, SNQ3NN/033LN11DBP1F6F5NNNN/NNNNN
211.25.027.0C, SNQ3NN/033RN11DBP1A4A3NNNN/NNNNN
83017493, SNQ3NN/033RN11DBP1BBBANNNB/NNNNN
211.25.060.0C, SNQ3NN/033RN11DBP1BBBANNNN/NNNNN
211.25.345.0C, SNQ3NN/033RN11DBP1CAC7NNNN/NNNEN

211.25.095.0C, SNQ3NN/033RN11DBP1CAC7NNNN/NNNNN
211.25.320.0C, SNQ3NN/033RN11DBP1CAC7NNNN/NNNZN
211.25.228.0C, SNQ3NN/033RN11DBP1E9E8NNNN/NNNNN
11041657, SNQ3NN/033RN11DBP1F6F5NNNB/NNNNN
211.25.238.0C, SNQ3NN/033RN11DBP1F6F5NNNN/NNNNN
11058739, SNQ3NN/033RN11DBP1F6F6NNNN/NNNNN
11048022, SNQ3NN/033RN11DBP1M6M5NNNN/NNNNN
211.25.028.0A, SNQ3NN/038LN11DBP1A4A3NNNN/NNNNN
211.25.061.0A, SNQ3NN/038LN11DBP1BBBANNNN/NNNNN
211.25.096.0A, SNQ3NN/038LN11DBP1CAC7NNNN/NNNNN
11062112, SNQ3NN/038LN11DBP1E9E8NNNN/NNNNN
211.25.028.0C, SNQ3NN/038RN11DBP1A4A3NNNN/NNNNN
211.25.061.0C, SNQ3NN/038RN11DBP1BBBANNNN/NNNNN
211.25.096.0C, SNQ3NN/038RN11DBP1CAC7NNNN/NNNNN
211.25.229.0C, SNQ3NN/038RN11DBP1E9E8NNNN/NNNNN
211.25.239.0C, SNQ3NN/038RN11DBP1F6F5NNNN/NNNNN
211.25.029.0A, SNQ3NN/044LN11DBP1A4A3NNNN/NNNNN
211.25.062.0A, SNQ3NN/044LN11DBP1BBBANNNN/NNNNN
211.25.097.0A, SNQ3NN/044LN11DBP1CACANNNN/NNNNN
211.25.029.0C, SNQ3NN/044RN11DBP1A4A3NNNN/NNNNN
211.25.062.0C, SNQ3NN/044RN11DBP1BBBANNNN/NNNNN
211.25.097.0C, SNQ3NN/044RN11DBP1CACANNNN/NNNNN
211.25.433.0C, SNQ3NN/044RN11DBP1E9E8NNNN/NNNNN
211.25.240.0C, SNQ3NN/044RN11DBP1F6F6NNNN/NNNNN
211.25.030.0A, SNQ3NN/048LN11DBP1A4A3NNNN/NNNNN
211.25.098.0A, SNQ3NN/048LN11DBP1CACANNNN/NNNNN
11068376, SNQ3NN/048LN11DBP1F6F6NNNN/NNNNN
211.25.030.0C, SNQ3NN/048RN11DBP1A4A3NNNN/NNNNN
211.25.098.0C, SNQ3NN/048RN11DBP1CACANNNN/NNNNN
211.25.412.0C, SNQ3NN/048RN11DBP1F6F5NNNN/NNNNN
211.25.241.0C, SNQ3NN/048RN11DBP1F6F6NNNN/NNNNN
211.25.031.0A, SNQ3NN/055LN11DBP1A5A4NNNN/NNNNN
211.25.064.0A, SNQ3NN/055LN11DBP1BBBANNNN/NNNNN
211.25.099.0A, SNQ3NN/055LN11DBP1CACANNNN/NNNNN
211.25.031.0C, SNQ3NN/055RN11DBP1A5A4NNNN/NNNNN
211.25.099.0C, SNQ3NN/055RN11DBP1CACANNNN/NNNNN
211.25.414.0C, SNQ3NN/055RN11DBP1F6F5NNNN/NNNNN
211.25.242.0C, SNQ3NN/055RN11DBP1F6F6NNNN/NNNNN
211.25.065.0A, SNQ3NN/063LN11DBP1BCBBNNNN/NNNNN
211.25.100.0A, SNQ3NN/063LN11DBP1CDCANNNN/NNNNN
211.25.347.0C, SNQ3NN/063RN11DBP1A5A4NNNN/NNNEN
211.25.032.0C, SNQ3NN/063RN11DBP1A5A4NNNN/NNNNN
211.25.324.0C, SNQ3NN/063RN11DBP1A5A4NNNN/NNNZN
211.25.100.0C, SNQ3NN/063RN11DBP1CDCANNNN/NNNNN
83018426, SNQ3NN/063RN11DBP1EAE9NNNN/NNNNN
211.25.243.0C, SNQ3NN/063RN11DBP1F7F6NNNN/NNNNN
11035284, SNQ3NN/075LN11DBP1BCBBNNNN/NNNNN
211.25.101.0A, SNQ3NN/075LN11DBP1CDCANNNN/NNNNN
211.25.033.0C, SNQ3NN/075RN11DBP1A5A4NNNN/NNNNN
211.25.101.0C, SNQ3NN/075RN11DBP1CDCANNNN/NNNNN